

## Appendix A: Hazardous Energies Control Procedure Form

### UC Irvine HAZARDOUS ENERGIES CONTROL PROCEDURE

NOTE: This procedure must be strictly followed to ensure protection of all persons involved.

Equipment ID: Mfgr., Model #, ID #:			
Equipment Location(s):		Date Performed:	
Task To Be Performed:			

#### Energy Forms: (check and list all that apply)

**1. Electrical**

**a. Voltage** - Potential is > 30V RMS or DC but < 600V

List: \_\_\_\_\_

**b. Voltage** - Potentials are > 600V

List: \_\_\_\_\_

**c. High Current** - > 25 amperes at any voltage

List: \_\_\_\_\_

**d. Static Electricity**

**2. Chemical** – Explosion, pressure, extreme heat, fire, corrosive, reactive, oxidizer, toxic

List: \_\_\_\_\_

**3. Pressure** - > 1 atm, pneumatic, hydraulic, liquid

List: \_\_\_\_\_

**4. Vacuum** - < 1 atm

**5. Mechanical/Kinetic** – capable of crushing, pinching, cutting, snagging, striking

List: \_\_\_\_\_

**6. Thermal** - High or Low Temperature - >60°C or < 0°C surface temperature, hot liquids, steam, cryogens

List: \_\_\_\_\_

**7. Ionizing Radiation** - > 2mRem/hr

**8. Non-Ionizing Radiation**

**a. Ultraviolet** - > ACGIH TLV

**b. Infrared** - > ACGIH TLV

**c. Rf/Microwave** - > ACGIH TLV

**d. Laser** - Class II, Class III, Class IV

**e. Magnetic Fields** - > ACGIH TLV

**9. Potential** - Flywheels, springs, differences in elevation, elevated parts that could drop, capacitors, batteries

**Note on SHIFT CHANGES:** If this procedure lasts more than one work shift, the oncoming persons will apply their locks and tags before the departing shift removes their locks and tags.

### Lockout Procedure

Follow the procedure below exactly as listed - check off each line as each step is completed:

1. Notify all Affected and Other Employees of intended lockout.
2. Turn off or shutdown and lockout and tag each energy control point listed below.

### Specific Lockout Locations



3. Dissipate any stored energy as described below.

**Dissipate These Energy Sources**


4. Block any mechanical parts, and remove any mechanical links listed below. Lock blocking in place. (Note: Two physical blocks in the line required with the space in between depressurized and emptied to break and secure any hazardous gas/liquid line.)

**Block These Parts/Remove Linkages**


5. Verify all persons clear of Hazard Zone.
6. Attempt to re-start machinery or re-energize equipment.
7. Verify no hazardous energy remains by the methods listed below. Use circuit tester/meter if electricity is involved.

**Verify No Residual Energy By These Methods**


8. Perform required work.

**Procedure To Return Equipment To Operation**

9. Verify Hazard Zone is clear of equipment, workers, tools, and test equipment.
10. Unlock and remove any blocking devices; replace linkages.
11. Reposition any safety valve(s) left open to prevent re-buildup of pressure.
12. Remove all locks and tags from energy control points.
13. Re-start or re-energize the equipment.
14. Notify all Affected and Other Employees that the lockout has been cleared.

Names of Authorized Lockout/Tagout Employee(s) performing this lockout (only individuals who have completed Advanced Electrical Safety/Lockout/Tagout Training)	

Names of Affected Employees affected by this Lockout procedure (include tool owners, Security, Facilities Management, EH&S, Affected lab managers)	