Demo Zone™

For use with equipment having "K" Number:

K1854-1



This manual covers equipment which is no longer in production by The Lincoln Electric Co. Specifications and availability of optional features may have changed.

Safety Depends on You

Lincoln arc welding and cutting equipment is designed and built with safety in mind. However, your overall safety can be increased by proper installation ... and thoughtful operation on your part. DO NOT INSTALL, OPERATE OR REPAIR THIS EQUIPMENT WITHOUT READING THIS MANUAL AND THE SAFETY PRECAUTIONS CONTAINED THROUGHOUT. And, most importantly, think before you act and be careful.



OPERATOR'S MANUAL



Copyright © 2001 Lincoln Global Inc.

World's Leader in Welding and Cutting Products •

Sales and Service through Subsidiaries and Distributors Worldwide

Cleveland, Ohio 44117-1199 U.S.A. TEL: 216.481.8100 FAX: 216.486.1751 WEB SITE: www.lincolnelectric.com

SAFETY

WARNING

▲ CALIFORNIA PROPOSITION 65 WARNINGS ▲

Diesel engine exhaust and some of its constituents are known to the State of California to cause cancer, birth defects, and other reproductive harm. The engine exhaust from this product contains chemicals known to the State of California to cause cancer, birth defects, or other reproductive harm.

The Above For Diesel Engines

The Above For Gasoline Engines

ARC WELDING CAN BE HAZARDOUS. PROTECT YOURSELF AND OTHERS FROM POSSIBLE SERIOUS INJURY OR DEATH. KEEP CHILDREN AWAY. PACEMAKER WEARERS SHOULD CONSULT WITH THEIR DOCTOR BEFORE OPERATING.

Read and understand the following safety highlights. For additional safety information, it is strongly recommended that you purchase a copy of "Safety in Welding & Cutting - ANSI Standard Z49.1" from the American Welding Society, P.O. Box 351040, Miami, Florida 33135 or CSA Standard W117.2-1974. A Free copy of "Arc Welding Safety" booklet E205 is available from the Lincoln Electric Company, 22801 St. Clair Avenue, Cleveland, Ohio 44117-1199.

BE SURE THAT ALL INSTALLATION, OPERATION, MAINTENANCE AND REPAIR PROCEDURES ARE PERFORMED ONLY BY QUALIFIED INDIVIDUALS.

FOR ENGINE powered equipment.

- 1.a. Turn the engine off before troubleshooting and maintenance work unless the maintenance work requires it to be running.

1.b. Operate engines in open, well-ventilated areas or vent the engine exhaust fumes outdoors.



1.c. Do not add the fuel near an open flame welding arc or when the engine is running. Stop the engine and allow it to cool before refueling to prevent spilled fuel from vaporizing on contact with hot engine parts and igniting. Do not spill fuel when filling tank. If fuel is spilled, wipe it up and do not start engine until fumes have been eliminated.

- 1.d. Keep all equipment safety guards, covers and devices in position and in good repair.Keep hands, hair, clothing and tools away from V-belts, gears, fans and all other moving parts when starting, operating or repairing equipment.
- 1.e. In some cases it may be necessary to remove safety guards to perform required maintenance. Remove guards only when necessary and replace them when the maintenance requiring their removal is complete. Always use the greatest care when working near moving parts.



1.f. Do not put your hands near the engine fan. Do not attempt to override the governor or idler by pushing on the throttle control rods while the engine is running.

1.g. To prevent accidentally starting gasoline engines while turning the engine or welding generator during maintenance work, disconnect the spark plug wires, distributor cap or magneto wire as appropriate.



1.h. To avoid scalding, do not remove the radiator pressure cap when the engine is hot.



ELECTRIC AND MAGNETIC FIELDS may be dangerous

- 2.a. Electric current flowing through any conductor causes localized Electric and Magnetic Fields (EMF). Welding current creates EMF fields around welding cables and welding machines
- 2.b. EMF fields may interfere with some pacemakers, and welders having a pacemaker should consult their physician before welding.
- 2.c. Exposure to EMF fields in welding may have other health effects which are now not known.
- 2.d. All welders should use the following procedures in order to minimize exposure to EMF fields from the welding circuit:
 - 2.d.1. Route the electrode and work cables together Secure them with tape when possible.
 - 2.d.2. Never coil the electrode lead around your body.
 - 2.d.3. Do not place your body between the electrode and work cables. If the electrode cable is on your right side, the work cable should also be on your right side.
 - 2.d.4. Connect the work cable to the workpiece as close as possible to the area being welded.

2.d.5. Do not work next to welding power source.

Mar '95



ARC RAYS can burn.

4.a. Use a shield with the proper filter and cover plates to protect your eyes from sparks and the rays of the arc when welding or observing open arc welding. Headshield and filter lens should conform to ANSI Z87. I standards.

- 4.b. Use suitable clothing made from durable flame-resistant material to protect your skin and that of your helpers from the arc rays.
- 4.c. Protect other nearby personnel with suitable, non-flammable screening and/or warn them not to watch the arc nor expose themselves to the arc rays or to hot spatter or metal.



FUMES AND GASES can be dangerous.

5.a. Welding may produce fumes and gases hazardous to health. Avoid breathing these fumes and gases.When welding, keep your head out of the fume. Use enough ventilation and/or exhaust at the arc to keep

fumes and gases away from the breathing zone. When welding with electrodes which require special ventilation such as stainless or hard facing (see instructions on container or MSDS) or on lead or cadmium plated steel and other metals or coatings which produce highly toxic fumes, keep exposure as low as possible and below Threshold Limit Values (TLV) using local exhaust or mechanical ventilation. In confined spaces or in some circumstances, outdoors, a respirator may be required. Additional precautions are also required when welding on galvanized steel.

- 5.b. Do not weld in locations near chlorinated hydrocarbon vapors coming from degreasing, cleaning or spraying operations. The heat and rays of the arc can react with solvent vapors to form phosgene, a highly toxic gas, and other irritating products.
- 5.c. Shielding gases used for arc welding can displace air and cause injury or death. Always use enough ventilation, especially in confined areas, to insure breathing air is safe.
- 5.d. Read and understand the manufacturer's instructions for this equipment and the consumables to be used, including the material safety data sheet (MSDS) and follow your employer's safety practices. MSDS forms are available from your welding distributor or from the manufacturer.
- 5.e. Also see item 1.b.

Mar '95



ELECTRIC SHOCK can kill. 3.a. The electrode and work (or ground) circuits

3.a. The electrode and work (or ground) circuits are electrically "hot" when the welder is on. Do not touch these "hot" parts with your bare skin or wet clothing. Wear dry, hole-free gloves to insulate hands.

3.b. Insulate yourself from work and ground using dry insulation. Make certain the insulation is large enough to cover your full area of physical contact with work and ground.

In addition to the normal safety precautions, if welding must be performed under electrically hazardous conditions (in damp locations or while wearing wet clothing; on metal structures such as floors, gratings or scaffolds; when in cramped positions such as sitting, kneeling or lying, if there is a high risk of unavoidable or accidental contact with the workpiece or ground) use the following equipment:

- Semiautomatic DC Constant Voltage (Wire) Welder.
- DC Manual (Stick) Welder.
- AC Welder with Reduced Voltage Control.
- 3.c. In semiautomatic or automatic wire welding, the electrode, electrode reel, welding head, nozzle or semiautomatic welding gun are also electrically "hot".
- 3.d. Always be sure the work cable makes a good electrical connection with the metal being welded. The connection should be as close as possible to the area being welded.
- 3.e. Ground the work or metal to be welded to a good electrical (earth) ground.
- 3.f. Maintain the electrode holder, work clamp, welding cable and welding machine in good, safe operating condition. Replace damaged insulation.
- 3.g. Never dip the electrode in water for cooling.
- 3.h. Never simultaneously touch electrically "hot" parts of electrode holders connected to two welders because voltage between the two can be the total of the open circuit voltage of both welders.
- 3.i. When working above floor level, use a safety belt to protect yourself from a fall should you get a shock.
- 3.j. Also see Items 6.c. and 8.





7.a. Use only compressed gas cylinders containing the correct shielding gas for the process used and properly operating regulators designed for the gas and

pressure used. All hoses, fittings, etc. should be suitable for the application and maintained in good condition.

- 7.b. Always keep cylinders in an upright position securely chained to an undercarriage or fixed support.
- 7.c. Cylinders should be located:
 Away from areas where they may be struck or subjected to physical damage.
 - A safe distance from arc welding or cutting operations and any other source of heat, sparks, or flame.
- 7.d. Never allow the electrode, electrode holder or any other electrically "hot" parts to touch a cylinder.
- 7.e. Keep your head and face away from the cylinder valve outlet when opening the cylinder valve.
- 7.f. Valve protection caps should always be in place and hand tight except when the cylinder is in use or connected for use.
- 7.g. Read and follow the instructions on compressed gas cylinders, associated equipment, and CGA publication P-I, "Precautions for Safe Handling of Compressed Gases in Cylinders," available from the Compressed Gas Association 1235 Jefferson Davis Highway, Arlington, VA 22202.

FOR ELECTRICALLY powered equipment.

8.a. Turn off input power using the disconnect switch at the fuse box before working on the equipment.

- 8.b. Install equipment in accordance with the U.S. National Electrical Code, all local codes and the manufacturer's recommendations.
- 8.c. Ground the equipment in accordance with the U.S. National Electrical Code and the manufacturer's recommendations.

Mar '95



6.a. Remove fire hazards from the welding area. If this is not possible, cover them to prevent the welding sparks from starting a fire. Remember that welding sparks and hot

WELDING SPARKS can

materials from welding can easily go through small cracks and openings to adjacent areas. Avoid welding near hydraulic lines. Have a fire extinguisher readily available.

- 6.b. Where compressed gases are to be used at the job site, special precautions should be used to prevent hazardous situations. Refer to "Safety in Welding and Cutting" (ANSI Standard Z49.1) and the operating information for the equipment being used.
- 6.c. When not welding, make certain no part of the electrode circuit is touching the work or ground. Accidental contact can cause overheating and create a fire hazard.
- 6.d. Do not heat, cut or weld tanks, drums or containers until the proper steps have been taken to insure that such procedures will not cause flammable or toxic vapors from substances inside. They can cause an explosion even though they have been "cleaned". For information, purchase "Recommended Safe Practices for the Preparation for Welding and Cutting of Containers and Piping That Have Held Hazardous Substances", AWS F4.1 from the American Welding Society (see address above).
- 6.e. Vent hollow castings or containers before heating, cutting or welding. They may explode.
- 6.f. Sparks and spatter are thrown from the welding arc. Wear oil free protective garments such as leather gloves, heavy shirt, cuffless trousers, high shoes and a cap over your hair. Wear ear plugs when welding out of position or in confined places. Always wear safety glasses with side shields when in a welding area.
- 6.g. Connect the work cable to the work as close to the welding area as practical. Work cables connected to the building framework or other locations away from the welding area increase the possibility of the welding current passing through lifting chains, crane cables or other alternate circuits. This can create fire hazards or overheat lifting chains or cables until they fail.
- 6.h. Also see item 1.c.

PRÉCAUTIONS DE SÛRETÉ

Pour votre propre protection lire et observer toutes les instructions et les précautions de sûreté specifiques qui parraissent dans ce manuel aussi bien que les précautions de sûreté générales suivantes:

Sûreté Pour Soudage A L'Arc

- 1. Protegez-vous contre la secousse électrique:
 - a. Les circuits à l'électrode et à la piéce sont sous tension quand la machine à souder est en marche. Eviter toujours tout contact entre les parties sous tension et la peau nue ou les vétements mouillés. Porter des gants secs et sans trous pour isoler les mains.
 - b. Faire trés attention de bien s'isoler de la masse quand on soude dans des endroits humides, ou sur un plancher metallique ou des grilles metalliques, principalement dans les positions assis ou couché pour lesquelles une grande partie du corps peut être en contact avec la masse.
 - c. Maintenir le porte-électrode, la pince de masse, le câble de soudage et la machine à souder en bon et sûr état defonctionnement.
 - d.Ne jamais plonger le porte-électrode dans l'eau pour le refroidir.
 - e. Ne jamais toucher simultanément les parties sous tension des porte-électrodes connectés à deux machines à souder parce que la tension entre les deux pinces peut être le total de la tension à vide des deux machines.
 - f. Si on utilise la machine à souder comme une source de courant pour soudage semi-automatique, ces precautions pour le porte-électrode s'applicuent aussi au pistolet de soudage.
- Dans le cas de travail au dessus du niveau du sol, se protéger contre les chutes dans le cas ou on recoit un choc. Ne jamais enrouler le câble-électrode autour de n'importe quelle partie du corps.
- Un coup d'arc peut être plus sévère qu'un coup de soliel, donc:
 - a. Utiliser un bon masque avec un verre filtrant approprié ainsi qu'un verre blanc afin de se protéger les yeux du rayonnement de l'arc et des projections quand on soude ou quand on regarde l'arc.
 - b. Porter des vêtements convenables afin de protéger la peau de soudeur et des aides contre le rayonnement de l'arc.
 - c. Protéger l'autre personnel travaillant à proximité au soudage à l'aide d'écrans appropriés et non-inflammables.
- 4. Des gouttes de laitier en fusion sont émises de l'arc de soudage. Se protéger avec des vêtements de protection libres de l'huile, tels que les gants en cuir, chemise épaisse, pantalons sans revers, et chaussures montantes.
- Toujours porter des lunettes de sécurité dans la zone de soudage. Utiliser des lunettes avec écrans lateraux dans les

zones où l'on pique le laitier.

- 6. Eloigner les matériaux inflammables ou les recouvrir afin de prévenir tout risque d'incendie dû aux étincelles.
- Quand on ne soude pas, poser la pince à une endroit isolé de la masse. Un court-circuit accidental peut provoquer un échauffement et un risque d'incendie.
- 8. S'assurer que la masse est connectée le plus prés possible de la zone de travail qu'il est pratique de le faire. Si on place la masse sur la charpente de la construction ou d'autres endroits éloignés de la zone de travail, on augmente le risque de voir passer le courant de soudage par les chaines de levage, câbles de grue, ou autres circuits. Cela peut provoquer des risques d'incendie ou d'echauffement des chaines et des câbles jusqu'à ce qu'ils se rompent.
- Assurer une ventilation suffisante dans la zone de soudage. Ceci est particuliérement important pour le soudage de tôles galvanisées plombées, ou cadmiées ou tout autre métal qui produit des fumeés toxiques.
- 10. Ne pas souder en présence de vapeurs de chlore provenant d'opérations de dégraissage, nettoyage ou pistolage. La chaleur ou les rayons de l'arc peuvent réagir avec les vapeurs du solvant pour produire du phosgéne (gas fortement toxique) ou autres produits irritants.
- Pour obtenir de plus amples renseignements sur la sûreté, voir le code "Code for safety in welding and cutting" CSA Standard W 117.2-1974.

PRÉCAUTIONS DE SÛRETÉ POUR LES MACHINES À SOUDER À TRANSFORMATEUR ET À REDRESSEUR

- Relier à la terre le chassis du poste conformement au code de l'électricité et aux recommendations du fabricant. Le dispositif de montage ou la piece à souder doit être branché à une bonne mise à la terre.
- 2. Autant que possible, l'installation et l'entretien du poste seront effectués par un électricien qualifié.
- 3. Avant de faires des travaux à l'interieur de poste, la debrancher à l'interrupteur à la boite de fusibles.
- 4. Garder tous les couvercles et dispositifs de sûreté à leur place.

Mar. '93



for selecting a **QUALITY** product by Lincoln Electric. We want you Thank You — for selecting a QUALITY product by Lincoln Electric. We want you to take pride in operating this Lincoln Electric Company product ... as much pride as we have in bringing this product to youl ••• as much pride as we have in bringing this product to you!

Please Examine Carton and Equipment For Damage Immediately

When this equipment is shipped, title passes to the purchaser upon receipt by the carrier. Consequently, Claims for material damaged in shipment must be made by the purchaser against the transportation company at the time the shipment is received.

Please refer to Individual machine Operator's Manuals for Parts Order information.

Read this Operators Manual and any others included with this equipment completely before attempting to use this equipment. Save this manual and keep it handy for quick reference. Pay particular attention to the safety instructions we have provided for your protection. The level of seriousness to be applied to each is explained below:

This statement appears where the information **must** be followed **exactly** to avoid **serious personal injury** or loss of life.

A CAUTION

This statement appears where the information **must** be followed to avoid **minor personal injury** or **damage to** this equipment.

i ugo

Installation	Section A
Technical Specifications	A-1
Safety Precautions.	A-2
Input and Grounding Connections	A-2
Input Power	A-2
Grounding	A-2
Output Cables, Connections and Limitations	A-2
Electrode and Work Cable Connections	A-2
Installation of Field Installed Options	A-3
Caster Wheels	A-3
Installation of Equipment Required for Recommended Processes	A-3
General Installation Requirements	A-4
Location	A-4
Engine Exhaust	A-4
Welding Smoke and Fume	A-4
Stacking	A-4
Handling	A-4

Operation	Section B
Safety Precautions.	B-1
General Description	B-1
Demo Zone	B-1
Recommended Processes and Equipment	B-1
Recommended Processes	B-1
Process Limitations	B-1
Recommended Equipment / Interface	B-2
Equipment Limitations	B-2
Design Features	B-2
Platform Commonalities	B-2
Operational Controls and Features of the Demo Zone	B-2
Circuit Breaker	B-2
Regulatory Requirements	B-2
Operating Instructions	B-2
Additional Safety Precautions	B-2
Welding and Cutting Area	B-2
Gas Cylinders	B-2
Power Sources	B-2
Welder Operation	B-3
Duty Cycle	B-3
Auviliary Power Operation	B-3
Accessories	Section C
Factory Installed Options / Accessories	C-1
Field Installed Options / Accessories	C-1
Caster Wheels	C-1
Maintenance	Section D
Safaty Procesitions	
Dauting Maintenance	D-1
Rouline Maintenance	D-1
Periodic Maintenance	D-1
Troubleshooting	Section E
Diagrams Wiring Diagram	Section F

TECHNICAL SPECIFICATIONS - Demo Zone (K-1854-1)

ELECTRICAL INPUT REQUIREMENTS		
Voltage Specification	Input Connection Specification	
230 VAC single phase, 40 amps	Type 6-50P plug	

RATED OUTPUT

The Demo Zone is intended for display and demonstration use. It is intended for light duty operation. The Demo Zone operator must observe the 40 amp input current limitation. Because of the input power limitation, power sources (except Ranger 250) when used at maximum output must be operated at low duty cycles. Refer to Welder Operation - Duty Cycle section of this manual.

PHYSICAL DIMENSIONS			
HEIGHT	WIDTH	DEPTH	WEIGHT
53.00 in.	66.00 in.	53.00 in.	1707 lbs. (w/o gas cylinders) 2467 lbs. (with gas cylinders)
1346.2 mm	1676.4 mm	1346.2 mm	774.3 kg. (w/o gas cylinders) 1119.0 kg. (with gas cylinders)



SAFETY PRECAUTIONS

WARNING



- ELECTRIC SHOCK can kill.
 Only qualified personnel should perform this installation.
- Turn the input power OFF at the circuit breaker or fuse box before working on this equipment.
- Do not touch electrically hot parts.
- Always connect the Demo Zone to a power supply grounded per the National Electrical Code and any local codes.
- This demonstration rack is intended for indoor use and display only.
- Shelter or protect from rain, moisture and condensation.
- Do not operate electric equipment when wet.



CYLINDERS could explode if damaged.

- Keep cylinders upright and secured to a support.
- Keep cylinders away from areas where they could be damaged.
- Never allow the electrodes or torches to touch the cylinders.
- Keep cylinders away from live electrical circuits.
- Maximum inlet pressures must be observed.



FALLING EQUIPMENT can cause injury.

- Do not lift with gas cylinder in place.
- Do not trailer or transport over the road



ENGINE EXHAUST can kill.

 Use in open, well ventilated areas or vent exhaust outside

INPUT AND GROUNDING CONNECTIONS

INPUT POWER

The Demo Zone is designed to operate from 230 volt, 60 Hz single-phase input power with 40-amp capacity. A 6-50R type receptacle must be provided by the user. The receptacle must be installed by a qualified person and must be in accordance with applicable local and national electrical codes.

The lighting system requires 120 volt 60 Hz power. Plug the line cord into a conventional 120 volt receptacle for lighting operation. The lighting system is for display and convenience purposes.

The Input Plugs for the Demo Zone are connected at the factory.

GROUNDING

When the Demo Zone is connected to a conventional power distribution system, the frame of the Demo Zone must be grounded. The input cable provided with the Demo Zone contains a grounding conductor. Additionally, another ground lead must be connected. Connect the frame of the Demo Zone to a good electrical ground using the #1 AWG lead included with the Demo Zone. The purpose of this additional ground is to minimize disturbance of the high frequency unit and to provide a path for stray welding currents.

Some applications may not use conventional input power and instead utilize the generating capability of the Ranger 250 for power. In this case, the ground lead is required only if the high frequency unit of the Square Wave TIG 175 is used.

OUTPUT CABLES AND CONNECTIONS

ELECTRODE AND WORK CABLE CON-NECTIONS

The Demo Zone is supplied with the output cables connected at the power sources for positive electrode polarity. To change the polarity of a power source, switch the cables at the output terminals of the power source, or change the power source polarity switch as applicable.

A bolted work lead runs from the work buss connection of the Demo Zone to the work table. The work table connection must be firm and secure.



INSTALLATION OF FIELD INSTALLED OPTIONS

CASTER WHEELS (PART OF K1848-1)

Caster wheels, which are provided, can be installed by lifting the Demo Zone approximately eight inches above ground level. Use the mounting hardware supplied to fasten the caster wheel to the mounting plate. Tighten all fasteners.

INSTALLATION OF EQUIPMENT REQUIRED FOR RECOMMENDED PROCESSES

- 1. As shipped from the factory, two diagonal braces are bolted to either side of the Demo Zone. The braces are approximately 62" in length.
- Remove the brace on the tool box side of the Demo Zone
- Do not remove the brace located on the Ranger 250 side of the Demo Zone.
- 2. The Demo Zone is made for ease of set up. Drive rolls are installed and liners are in the guns.
- 3. A Harris Kit, containing gas components, is included with the Demo Zone. Some details about the kit:
- The double flow meter-regulator is for the argon gas cylinder. A "Y" fitting is also used on one of the flow meter outlets. The argon is fed to the Spool Gun, The Square Wave TIG 175 and the two-piece TIG torch attached to the Ranger 250.
- The other regulator is provided for the 75/25 argon/CO2 gas cylinder. Connect a "Y" fitting to this regulator. The Power MIG and LN25 is fed from the "Y" fitting. Use hoses with inert gas fittings. The short hose is used with the LN7.
- The oxygen fitting (with 1/4 inch pipe thread) is for use with the Pro-Cut gas hose. Use the short oxygen hose between the Pro-Cut and regulator.
- 4. Two plasma torches are provided with the Demo Zone. Use the short length plasma torch with the Demo Zone. The torch with the long length is not recommended because the length is inconvenient when used with the Demo Zone. Store the long plasma torch. Use the long torch if the Pro Cut is removed from the Demo Zone.
- 5. BEFORE the gas cylinders are installed, run the gun for the Power MIG from the back of the rack through the bench (under) and then up to the Power MIG. This gun will run along the back of the Square Wave TIG 175 and then to a gun holder. It should be long enough to reach the worktable and this helps keep the cables from getting tangled.

- 6. BEFORE the gas cylinders are installed, measure the cable length needed for the spool gun (it is routed the same way as the Power MIG gun) and coil the rest, wire tie it and store it underneath the bench between the Ranger and Power MIG.
- 7. BEFORE the gas cylinders are installed, connect the battery in the Ranger 250.
- 8. Gas cylinder covers will improve the appearance of your unit. When used, put the covers on before installing the cylinder.
- 9. Place the cylinders in the Demo Zone. The cylinders can be installed by using the rear or side openings, or a combination of both.

When using the rear frame opening, move the upper and lower support bars out of way. Install the cylinders and replace the support bars to the closed position.

When using side frame opening, lift brace and swing out of the way. Install the cylinders and swing brace back into position, push brace down through locking tube to secure.

Place the air cylinder directly in back of the Pro Cut. Place the argon cylinder next to the air cylinder.

- 10. Install the optional casters. This is easily done after placing cylinders in Demo Zone, as the height of the Demo Zone is higher with the wheels installed.
- 11. Set up the two TIG torches provided. The TIG torch that comes with the SW175 is used on both AC and DC. A recommendation is to use a point at one end of the tungsten and a ball at the other end.
- 12. The welding table must exposed before demonstrating. Pull the table to the open position when in use. The table can be pushed back in, out of the way, when the table is not in use. Since the table has a bolted work lead permanently attached, no work clamp is necessary for welding or cutting operations.



GENERAL INSTALLATION REQUIREMENTS

LOCATION

Locate the Demo Zone on a flat surface. The Demo Zone is intended for indoor use only. The Demo Zone must be sheltered from rain and water.

ENGINE EXHAUST

Provide an exhaust capability for the Ranger 250 machine. Flexible metal exhaust hose, available from automobile parts stores, should be used to exhaust gasses to the outdoors. The exhaust pipe on the Ranger 250 is 1.5" diameter nominal. Use a clamp at the muffler to ensure a good seal.

The exhaust pipe and flexible metal exhaust hose is hot! Do not touch when hot. Keep flammable material away from the exhaust hose. Place a "Hot - Do not touch" sign near the hose to warn of the hazard.

Ensure that there is sufficient fresh air and ventilation available during operation of the Ranger 250.

WELDING SMOKE AND FUME

Provide an exhaust for welding smoke and fume.

STACKING

The Demo Zone is not designed for stacking.

HANDLING

A pallet jack or forklift truck can be used to move the Demo Zone and to install the caster kit. The placement of the pallet jack or forks must balance the Demo Zone load to prevent tipping.

A WARNING



FALLING EQUIPMENT can cause injury.

 Do not lift the Demo Zone by overhead crane.

- Do not lift the Demo Zone with gas cylinder in place.
- Lift from front of Demo Zone only. Do not lift from left, right or rear sides.

The Demo Zone is too heavy for one person to move by hand on an inclined surface. Avoid situations that may injure yourself or others.



SAFETY PRECAUTIONS

Read and understand this entire section before operating the machine.

WARNING



ELECTRIC SHOCK can kill.

- Do not touch electrically live parts or electrode with skin or wet clothing.
- · Insulate yourself from work and ground.
- · Always wear dry insulating gloves.
- Read and follow "Electric Shock Warnings" in the Safety section if welding must be performed under electrically hazardous conditions such as welding in wet areas or on or in the workpiece.



FUMES AND GASES can be dangerous.

- · Keep your head out of fumes.
- Use ventilation or exhaust to remove fumes from breathing zone.



WELDING SPARKS can cause fire or explosion

- Keep flammable material away.
- Do not weld on containers that have held combustibles.



ARC RAYS can burn.

Wear eye, ear and body protection.

Observe additional Safety Guidelines detailed in the beginning of this manual.

GENERAL DESCRIPTION

DEMO ZONE

The Demo Zone is a compact system to display and demonstrate welding and cutting equipment.

The Demo Zone contains:

- Square Wave TIG 175 Power Source
- Power MIG 255 Power Source
- Ranger 250 Power Source
- V350 Pro Power Source
- Pro Cut 55 Plasma Cutter
- LN-25 Wire Feeder
- LN-7GMA Wire Feeder
- Holder for 4 gas cylinders
- Welding table
- Power distribution system with circuit breaker protection
- Welding cables and torches
- Tool box for storage of tools, welding accessories and welding plates
- Illuminated lower area by neon and florescent lamps
- Prominent promotional sign
- Caster wheels allow easy movement.

All equipment on the Demo Zone is connected and ready to weld. The Demo Zone obtains its power from a 230V 40A receptacle.

RECOMMENDED PROCESSES AND EQUIPMENT

RECOMMENDED PROCESSES

The Demo Zone is capable of demonstrating MIG, TIG, SMAW, CAC and plasma cutting.

PROCESS LIMITATIONS

- determined by individual equipment





RECOMMENDED EQUIPMENT / ADDITIONAL SAFETY PRECAUTIONS INTERFACE

EQUIPMENT LIMITATIONS

B-2

The Demo Zone is intended for indoor display and demonstration use. The Demo Zone is intended for light duty operation. Because of the input power limitation, power sources (except Ranger 250) may only be used at maximum output with low duty cycles. (Refer to Welder Operation-Duty Cycle section of this manual).

The Demo zone is not intended for road transportation or to be hauled on a trailer.

The Demo zone must not be lifted with gas cylinders in place.

DESIGN FEATURES

PLATFORM COMMONALTIES

The Demo Zone utilizes standard power source and wire feeder configurations. Output cables and torches are modified in length for use with the Demo Zone.

OPERATIONAL CONTROLS AND FEATURES OF THE DEMO ZONE

Refer to the individual Operator's Manuals for equipment included in the Demo Zone.

CIRCUIT BREAKER

The 230V input power to the Demo Zone is controlled by a 40-amp circuit breaker located on the rear of the Demo Zone.

REGULATORY REQUIREMENTS

The power source and wire feed equipment included with the Demo Zone are individually listed or certified to CSA or UL agencies.

OPERATING INSTRUCTIONS

Read and understand the Operator's Manuals for all of the equipment contained in the Demo Zone. The operating instructions for each equipment type are not repeated here in the Demo Zone manual.

Plug the Demo Zone into a 230 volt 40 amp receptacle. Locate the circuit breaker at the rear of the Demo Zone and switch it on. Plug the lighting system into a 120 volt receptacle. Switch the power for individual machines on as required for demonstration purposes.

WELDING AND CUTTING AREA

Welding and Cutting must take place only on the welding table provided with the Demo Zone. Do not weld or cut on objects away from the Demo Zone welding table. Do not weld on the frame of the Demo Zone.

Direct sparks away from welding machines, especially the fuel fill area of the Ranger 250.



CYLINDERS could explode if damaged.

•Keep cylinders upright and secured to a support.

- Keep cylinders away from areas where they could be damaged.
- Never allow the electrodes or torches to touch the cylinders.
- · Keep cylinders away from live electrical circuits.
- Maximum inlet pressures must be observed.
- Do not lift Demo Zone with gas cylinders in place.
- Do not strike an arc on any gas cylinders. Never allow the electrode, electrode holder or any other electrically "hot" parts to touch a cylinder.
- Gas cylinders must be securely fastened to the Demo Zone frame. Chains are supplied and are attached to the frame.
- When caster wheels are installed, block the Demo Zone from movement when removing or installing gas clinders.

POWER SOURCES

The Demo Zone is a flexible system capable of demonstrating many varied processes. The set-up of equipment may require polarity changes, torch changes or electrode changes. Turn-off the welding power source or plasma cutter when changing or connecting output cables torches or electrodes.



WELDER OPERATION

DUTY CYCLE

Full output and duty cycle may not be obtained from all power sources. The output and duty cycle may be limited by the 40 amp input power limitation of the Demo Zone. The duty cycle of the power source must be adjusted to be within the capability of the 40 amp input supply.

Duty cycle is based upon a ten minute period. A 10% duty cycle represents 1 minute of welding and 9 minutes of idling in a ten minute period.

Some examples of allowable duty cycles of the Demo Zone are given. If the duty cycle or input currents exceed the capability of the 40 amp circuit breaker, the breaker will trip off. For lower output currents, the duty cycle is extended from what is listed.

V350-PRO

200A at 28v 275A at 31V	100% duty cycle 10% duty cycle	41A input 62A input	
Power MIG 255 (machine limited)			
200A at 28v 250A at 30v	60% duty cycle 40% duty cycle	37A input 46A input	
Pro Cut 55			
55A	15% duty cycle	55A input	
Square Wave TIG 175			
150A	10% duty cycle	65A input	

AUXILIARY POWER OPERATION

Duty cycle and maximum current may be less than rated value if the power sources are powered from the Ranger 250.

(Refer to Ranger 250 Operator's Manual).

FACTORY INSTALLED OPTIONS / ACCESSORIES

- none

C-1

FIELD INSTALLED OPTIONS / ACCESSORIES

CASTER WHEELS

Caster wheels, which are provided, are a field installed option for the Demo Zone. The 5-inch diameter caster wheels offer high mobility for in-shop use.



SAFETY PRECAUTIONS

A WARNING

ELECTRIC SHOCK can kill. Turn the input power OFF at the disconnect switchs or fuse boxes before working on all equipment.

- · Do not touch electrically hot parts.
- Have qualified personnel do all maintenance and troubleshooting work.
- Turn engine or welders off before working inside the machines or servicing the engine.
- · Observe all safety precautions in the individual machine Operator's Manuals as well as this manual.

ROUTINE MAINTENANCE

Refer to individual Operator's Manuals for routine maintenance requirements.

Perform the following daily routine:

- · Check that no combustible materials are in the welding or cutting area or around the machine.
- · Remove any debris, dust, dirt, or materials that could block the air flow to the machines for cooling.

PERIODIC MAINTENANCE

Refer to individual Operator's Manuals for periodic maintenance requirements.

Perform the following periodically:

- Inspect the welding cables, torches and electrode holders for any slits or punctures in the cable jacket, or any condition that would affect the proper operation.
- Inspect gas hoses and regulators.
- Inspect gas cylinder chains and fasteners.
- The weld table is insulated from the Demo Zone frame. Inspect the weld table mechanism to ensure that the insulation system is intact.





D-1

A WARNING

Service and Repair should only be performed by Lincoln Electric Factory Trained Personnel. Unauthorized repairs performed on this equipment may result in danger to the technician and machine operator. For your safety and to avoid Electrical Shock, please observe all safety notes and precautions detailed throughout this and individual machine Operator's Manuals. Consult individual machine Operator's Manuals for detailed troubleshooting of specific machines.

A CAUTION

If for any reason you do not understand the test procedures or are unable to perform the tests/repairs safely, contact your **Local Lincoln Authorized Field Service Facility** for technical troubleshooting assistance before you proceed.







WARNING	 Do not touch electrically live parts or electrode with skin or wet clothing. Insulate yourself from work and ground. 	• Keep flammable materials away.	• Wear eye, ear and body protection.
AVISO DE PRECAUCION	 No toque las partes o los electrodos bajo carga con la piel o ropa moja- da. Aislese del trabajo y de la tierra. 	 Mantenga el material combustible fuera del área de trabajo. 	 Protéjase los ojos, los oídos y el cuerpo.
ATTENTION	 Ne laissez ni la peau ni des vête- ments mouillés entrer en contact avec des pièces sous tension. Isolez-vous du travail et de la terre. 	 Gardez à l'écart de tout matériel inflammable. 	 Protégez vos yeux, vos oreilles et votre corps.
German WARNUNG	 Berühren Sie keine stromführenden Teile oder Elektroden mit Ihrem Körper oder feuchter Kleidung! Isolieren Sie sich von den Elektroden und dem Erdboden! 	• Entfernen Sie brennbarres Material!	 Tragen Sie Augen-, Ohren- und Kör- perschutz!
ATENÇÃO	 Não toque partes elétricas e electrodos com a pele ou roupa molhada. Isole-se da peça e terra. 	 Mantenha inflamáveis bem guarda- dos. 	 Use proteção para a vista, ouvido e corpo.
注意事項	 ●通電中の電気部品、又は溶材にヒ フやぬれた布で触れないこと。 ●施工物やアースから身体が絶縁されている様にして下さい。 	 ● 燃えやすいものの側での溶接作業 は絶対にしてはなりません。 	● 目、耳及び身体に保護具をして下 さい。
Chinese 查 <u>牛</u> 言 古	 ●皮肤或濕衣物切勿接觸帶電部件及 銲條。 ●使你自己與地面和工件絶縁。 	●把一切易燃物品移離工作場所。	●佩戴眼、耳及身體勞動保護用具。
^{Korean} 위 험	● 전도체나 용접봉을 젖은 헝겁 또는 피부로 절대 접촉치 마십시요. ● 모재와 접지를 접촉치 마십시요.	●인화성 물질을 접근 시키지 마시요.	●눈, 귀와 몸에 보호장구를 착용하십시요.
Arabic تحذير	 لا تلمس الاجزاء التي يسري فيها التيار الكهرباني أو الالكترود بجلد الجسم أو بالملابس المبللة بالماء. ضع عاز لا على جسمك خلال العمل. 	 ضع المواد القابلة للاشتعال في مكان بعيد. 	 ضع أدوات وملابس واقية على عينيك وأذنيك وجسمك.

READ AND UNDERSTAND THE MANUFACTURER'S INSTRUCTION FOR THIS EQUIPMENT AND THE CONSUMABLES TO BE USED AND FOLLOW YOUR EMPLOYER'S SAFETY PRACTICES.

SE RECOMIENDA LEER Y ENTENDER LAS INSTRUCCIONES DEL FABRICANTE PARA EL USO DE ESTE EQUIPO Y LOS CONSUMIBLES QUE VA A UTILIZAR, SIGA LAS MEDIDAS DE SEGURIDAD DE SU SUPERVISOR.

LISEZ ET COMPRENEZ LES INSTRUCTIONS DU FABRICANT EN CE QUI REGARDE CET EQUIPMENT ET LES PRODUITS A ETRE EMPLOYES ET SUIVEZ LES PROCEDURES DE SECURITE DE VOTRE EMPLOYEUR.

LESEN SIE UND BEFOLGEN SIE DIE BETRIEBSANLEITUNG DER ANLAGE UND DEN ELEKTRODENEINSATZ DES HER-Stellers. Die Unfallverhütungsvorschriften des Arbeitgebers sind ebenfalls zu beachten.

	N.		
 Keep your head out of fumes. Use ventilation or exhaust to remove fumes from breathing zone. 	 Turn power off before servicing. 	 Do not operate with panel open or guards off. 	WARNING
 Los humos fuera de la zona de respiración. Mantenga la cabeza fuera de los humos. Utilice ventilación o aspiración para gases. 	 Desconectar el cable de ali- mentación de poder de la máquina antes de iniciar cualquier servicio. 	 No operar con panel abierto o guardas quitadas. 	AVISO DE PRECAUCION
 Gardez la tête à l'écart des fumées. Utilisez un ventilateur ou un aspira- teur pour ôter les fumées des zones de travail. 	 Débranchez le courant avant l'entre- tien. 	 N'opérez pas avec les panneaux ouverts ou avec les dispositifs de protection enlevés. 	French ATTENTION
 Vermeiden Sie das Einatmen von Schweibrauch! Sorgen Sie für gute Be- und Entlüftung des Arbeitsplatzes! 	 Strom vor Wartungsarbeiten abschalten! (Netzstrom völlig öff- nen; Maschine anhalten!) 	 Anlage nie ohne Schutzgehäuse oder Innenschutzverkleidung in Betrieb setzen! 	German WARNUNG
 Mantenha seu rosto da fumaça. Use ventilação e exhaustão para remover fumo da zona respiratória. 	 Não opere com as tampas removidas. Desligue a corrente antes de fazer serviço. Não toque as partes elétricas nuas. 	 Mantenha-se afastado das partes moventes. Não opere com os paineis abertos ou guardas removidas. 	Portuguese ATENÇÃO
● ヒュームから頭を離すようにして 下さい。 ● 換気や排煙に十分留意して下さい。	● メンテナンス・サービスに取りか かる際には、まず電源スイッチを 必ず切って下さい。	● パネルやカバーを取り外したまま で機械操作をしないで下さい。	注意事項
●頭部遠離煙霧。 ●在呼吸區使用通風或排風器除煙。	● 維修前切斷電源。	●儀表板打開或沒有安全罩時不準作 業。	Chinese 警告
 얼굴로부터 용접가스를 멀리하십시요. 호홉지역으로부터 용접가스를 제거하기 위해 가스제거기나 통풍기를 사용하십시요. 	● 보수전에 전원을 차단하십시요.	● 판넬이 열린 상태로 작동치 마십시요.	Korean 위험
 ابعد رأسك بعيداً عن الدخان. استعمل التهوية أو جهاز ضنط الدخان للخارج لكي تبعد الدخان عن المنطقة التي تتنفس فيها. 	اقطع التيار الكهربائي قبل القيام بأية صيانة.	 لا تشغل هذا الجهاز اذا كانت الاغطية الحديدية الواقية ليست عليه. 	تحذير

LEIA E COMPREENDA AS INSTRUÇÕES DO FABRICANTE PARA ESTE EQUIPAMENTO E AS PARTES DE USO, E SIGA AS PRÁTICAS DE SEGURANÇA DO EMPREGADOR.

使う機械や溶材のメーカーの指示書をよく読み、まず理解して下さい。そして貴社の安全規定に従って下さい。

請詳細閱讀並理解製造廠提供的説明以及應該使用的銀捍材料,並請遵守貴方的有関勞動保護規定。

이 제폼에 동봉된 작업지침서를 숙지하시고 귀사의 작업자 안전수칙을 준수하시기 바랍니다.

اقرأ بتمعن وافهم تعليمات المصنع المنتج لهذه المعدات والمواد قبل استعمالها واتبع تعليمات الوقاية لصاحب العمل.



World's Leader in Welding and Cutting Products •
 Sales and Service through Subsidiaries and Distributors Worldwide •
Cleveland, Ohio 44117-1199 U.S.A. TEL: 216.481.8100 FAX: 216.486.1751 WEB SITE: www.lincolnelectric.com