Rockwell Commander Type AC11 Elevator Spar Inspection and Report

Part 1. Aircraft Information

Table 1 Aircraft Information			
	Andrait information		
Model Year			
Model (circle at right)	112 112A 112B 112TC 112TCA 114 114A 114B 114TC 115		
Serial Number			
Total Time Airframe	Current Prop: [] 2-Blade [] 3-Blade		
· · · · · · · · · · · · · · · · · · ·			

		ding Below r> Hobbs			
Current Time					
Engine Conversion [] None [] Hot Shot Normalizer [] Camarillo Normalizer [] 390 Super [] 580 Super	Time <u>Installed</u>	Time <u>Installed</u>	Date <u>Installed</u>		
Service Bulletin SB-112- 56B or SB-114-12B in regard to lower fin rib [] No Record Found	Time Complied	Time Complied	Date <u>Complied</u>	Number of Rivet Rows ¹ [] Single Row [] Single Row plus Aft Only [] Single Row plus 1/2 Row [] Two Full Rows	
Service Letter SL-112-46 or SL-114-17 in regard to upper rudder spar [] No Record Found	Time Complied	Time Complied	Date <u>Complied</u>	[] Cracked Before Repair [] Gone Beyond Stop Drills [] Never Cracked	
Empennage Maintenance, Replacement or Repair Entries (report only most recent) Enter time and date of work from logs and check all boxes below that apply					
Elevators Mentioned] Left []	Right [] Damage History	
Replacement of Elevator Hinge Bushing/Bearing		[] Any on Left [] Any on Right			
Replacement of Fittings] Any on Left [] Any on Right		
Trim Tabs Mentioned] Left []	Right [] Damage History	
Replacement of Trim Tab Rod Ends		[Either on Either on		
Trim Jackscrew Service] Left []	Right	


Technical Advice (nominal fee charged) available. Fee credited toward service kit.

¹ SB-112-56B and SB-114-12B prescribed installation of a doubler at the lower fin rib located just beneath the horizontal stabilizer, consisting initially of a "horseshoe" doubler at the aft end, or later a half-rib doubler, or later yet a full-rib doubler. The level of repair is easily discernable by observing the extent of the second (lower) row of rivets forward along the rib skin starting from the aft edge. Note that the upper row of rivets may be obscured underneath the rubber seal.

Part 2: General Inspection

Note: Do no cleaning until instructed.

[] Install the control lock and inspect for detectable play at the locations set forth in Table 2. Any appreciable play heard, felt or seen in the hinges and bearings, and any play in excess of 1/8" total movement at the trailing edges of the elevators and/or trim tabs should be reported by checking the appropriate boxes:



	ble 2 ay in Horizontal Tail			
Left Elevator	Right Elevator			
Left Elevator Trailing Edge [] More than 1/8" Total Movement [] Less than 1/8" Total Movement [] Did Not Inspect	Right Elevator Trailing Edge [] More than 1/8" Total Movement [] Less than 1/8" Total Movement [] Did Not Inspect			
Left Elevator Hinges	Right Elevator Hinges			
OutboardMidInboard[] Audible[] Audible[] Audible[] Felt[] Felt[] Felt[] Visible[] Visible[] Visible[] No Play[] No Play[] No Play[] DNI²[] DNI[] DNI	InboardMidOutboard[] Audible[] Audible[] Audible[] Felt[] Felt[] Felt[] Visible[] Visible[] Visible[] No Play[] No Play[] No Play[] DNI[] DNI[] DNI			
Left Trim Tab	Right Trim Tab			
Left Trim Tab Trailing Edge [] More than 1/8" Total Movement [] Less than 1/8" Total Movement [] Did Not Inspect	Right Trim Tab Trailing Edge [] More than 1/8" Total Movement [] Less than 1/8" Total Movement [] Did Not Inspect			
Outboard Inboard Actuator Rod End Rod End Jack Screw [] Felt [] Felt [] Felt [] Visible [] Visible [] No Play [] DNI [] DNI [] DNI	Actuator Inboard Outboard Rod End Rod End Felt Felt State State Felt Outboard Rod End Felt Felt Outboard Rod End Felt Felt Outboard Felt Felt Outboard Felt Felt Felt Outboard Felt Felt Felt Outboard Felt Fe			
Elevator	Push Tube			
	n Tube - Upper Bearing elevator horn port) [] No Play [] DNI			
<u>Play at Elevator Pusl</u> [] Audible [] Observable (by rem	n <u>Tube - Lower Bearing</u> oving the stinger) [] No Play [] DNI			

² Check box if you did not inspect this item.

[] Check the torque on the elevator outboard hinge fitting attachment bolts using a 3/8" swivel socket on a 1/4" drive extension and torque wrench set to 30 inch pounds, reporting in Table 3 whether the bolts rotate before torque is reached:

Table 3 Torque Check of Attachment of Outboard Elevator Fitting to Elevator				
Left Elevator Outboard Hinge Fitting		Right Elevator Outboard Hinge Fitting		
Upper Outboard [] Rotates [] No Rotation [] DNI ³	<u>Upper Inboard</u> [] Rotates [] No Rotation [] DNI	<u>Upper Inboard</u> [] Rotates [] No Rotation [] DNI	Upper Outboard [] Rotates [] No Rotation [] DNI	
Lower Outboard [] Rotates [] No Rotation [] DNI	Lower Inboard [] Rotates [] No Rotation [] DNI	Lower Inboard [] Rotates [] No Rotation [] DNI	Lower Outboard [] Rotates [] No Rotation [] DNI	

Part 3: Special Inspection for Spar Cracks

Note: Do no cleaning until instructed.

[]	Visually inspect the area immediately surrounding the outboard elevator hinge fittings
	attached to the elevator for any cracks or signs of smoke produced by cracks in the
	elevator spar web. If cracks or signs are found, make mental note of areas for re-
	inspection after cleaning.

[] Clean the fittings and surrounding spar web and re-inspect for cracks. If cracks are found, the inspection may be ended at this point.

[] Check this box if inspection ended at this point, and report results in Table 4.

[] Remove the elevator tip and inspect the aft face of the spar web in the area of the fitting by inserting a flexible borescope⁴ between the aft end of the outboard elevator rib and the trailing edge of the elevator skin. Generally, it will be possible to insert a scope up to 9 mm diameter. Inspection should cover the areas surrounding the four attachment nuts

and extending upward and downward to the elevator skins and at least 1" inboard and outboard from the nuts.

Typically the spar web inside the elevator is clean, so any "lines" are likely of aluminum smoke generated by motion of cracks.

If viewing is obscured by dirt or grease, it may be possible to spray some cleaner (such as avgas) in through the small tooling hole in the outboard rib, and then re-inspect.

Technical Advice (nominal fee charged) available. Fee credited toward service kit.

³ Check this box if did not inspect this item.

⁴ The Bend-a-Light Mini Pro, sold by Aircraft Spruce, and the B5500 Visual Inspection Device, sold by Snap-On, are both reported to work.

If access cannot be gained for inspection using a borescope, or direct viewing is necessary for confirmation of cracks, contact Aerodyme or CPAC for further consultation.

[] The inspection is finished at this point. Report the results in Table 4. If cracks have been found, and if possible, take digital pictures for the owner to upload to the survey page.

Table 4 Special Inspection Res	ults		
(at right, check all that apply and record length, or distance, or count as appropriate)	<u>Elev</u> Left	ator Right	Length or Distance or Count
No Defects Found			
Crack Along Upper Edge of Fitting, and How Long?			
Crack Along Lower Edge of Fitting, and How Long?			
Crack Beyond Inboard Edge of Fitting, and How Far?			
Crack Beyond Outboard Edge of Fitting, and How Far?			
Crack Starting/Ending at Bolt Holes, How Many?			
Crack Visible by External Inspection of Elevator			
Crack Visible by Internal Inspection of Elevator			
Crack Visible Only by Dye-Penetrant Inspection			
Other Defect (please describe here)			

Part 4: Contact Information

Date of Inspection:	
Inspector's Name:	
Best Contact Method:	[] Email to
	[] Telephone

Please provide a copy of this report to the aircraft owner for entry of the results on the special survey page at www.commander.org.

Reference Information

Model 112 IPC Figure 2-35 Callout 46 Spar and Detail B Callout 56 Fitting Model 114 IPC Figure 2-35 Callout 46 Spar and Detail A Callout 56 Fitting