

Issues

#	Project	Tracker	Status	Priority	Subject	Updated
1069	CHIRP	Bug	New	Immediate	Channels/Template won't download - No Error Message Baofeng UV-82	08/17/2013 08:13 am
1205	CHIRP	Bug	New	Immediate	Baofeng UV-82L wrong frequency	11/01/2013 02:45 am
1831	CHIRP	Bug	New	Immediate	Error message when trying to download info from radio using an FTDI chip in a programming cable for Yaesu FT-2800	08/13/2014 08:50 am
2035	CHIRP	Bug	New	Immediate	bf-f8	11/10/2014 08:01 pm
2803	CHIRP	Bug	New	Immediate	Error	08/17/2015 03:02 pm
2953	CHIRP	Bug	New	Immediate	Bug at starting program	10/27/2015 04:41 pm
3161	CHIRP	Bug	New	Immediate	CHIRP will NOT open.	01/12/2016 08:06 pm
3301	CHIRP	Bug	New	Immediate	Failed to communicate with radio: Radio not responding	02/09/2016 03:14 pm
1113	CHIRP	Bug	New	Urgent	IC-2100H	09/05/2013 05:55 pm
1189	CHIRP	Bug	New	Urgent	Anytone 5888UV Read Error	10/24/2013 05:04 am
1423	CHIRP	New Model	New	Urgent	Bao-hui or Baohui BH-620	02/05/2014 01:24 am
2049	CHIRP	New Model	New	Urgent	Please do your magic and fully support the Midland HM477 UHF mobile CB unit. It appears to be a clone of the TYT TH9000 but programmed for 477 CBRS	11/12/2014 10:12 pm
2403	CHIRP	New Model	New	Urgent	kenwood TK-3302-1	03/09/2015 08:10 pm
2599	CHIRP	New Model	New	Urgent	Add the ANYTONE NSTIG-8R	12/06/2015 10:27 am
2885	CHIRP	New Model	New	Urgent	Retevis RT-5RV	09/29/2015 08:58 pm
2997	CHIRP	Bug	New	Urgent	Application Crashes when adjusting viewable memory range / exporting Anytone UV5888.img file	11/12/2015 10:05 pm
3031	CHIRP	Bug	New	Urgent	Baofeng UV-5R to Baofeng GT-3 Mk 2	11/29/2015 08:39 pm
3135	CHIRP	New Model	New	Urgent	Vertex VX-2200e	01/05/2016 02:52 pm
3157	CHIRP	Bug	New	Urgent	UV3d	01/12/2016 08:15 am
264	CHIRP	Bug	New	High	Can't upload to Puxing 777 VHF Model	07/31/2012 09:26 am
409	CHIRP	Bug	New	High	vx-8dr, banks not working	02/11/2013 01:23 pm
415	CHIRP	Bug	New	High	bank register bit not set to enable bank mode in radio(related to bug 409)	01/08/2013 05:10 pm
695	CHIRP	Bug	New	High	UV-5RA Backlights are gone.	03/14/2013 02:11 pm
945	CHIRP	Bug	New	High	Input Issue	07/23/2013 04:35 pm
963	CHIRP	Bug	New	High	VX7R fail to communicate	07/10/2013 03:29 am
1221	CHIRP	Bug	New	High	Le programme ne veut pas ouvrir	11/07/2013 03:26 pm
1235	CHIRP	Bug	New	High	Badfeng UV-5rA	11/14/2013 12:20 pm
1261	CHIRP	Bug	New	High	UV5RA, Nonfunctioning import and export	11/21/2013 10:44 pm
1439	CHIRP	New Model	New	High	Quansheng TG-K4AT(UV)	02/09/2014 11:45 pm

1571	CHIRP	Bug	New	High	Baofeng UV-82L	04/27/2014 05:48 am
1597	CHIRP	Bug	New	High	Unable to program Yawes A-338Plus handheld radio with THT TH-F8PG	11/12/2014 10:07 pm
1639	CHIRP	New Model	New	High	AnyTone AT-3318UV-A	05/16/2014 06:13 pm
1691	CHIRP	Feature	New	High	different pl tones	06/11/2014 02:32 pm
1735	CHIRP	Bug	New	High	Yaesu VX-8DR - Frequencies programmed with chirp have frequency offset in TX/TR	11/04/2015 03:11 pm
1737	CHIRP	Bug	New	High	RepeaterBook data loads wrong Offset?	08/09/2014 11:40 am
1829	CHIRP	New Model	New	High	IC-9100	08/11/2014 02:12 pm
1865	CHIRP	New Model	New	High	Alinco Dj- V5	08/23/2015 11:08 am
1951	CHIRP	Bug	New	High	Icom F10 / F20	10/07/2014 09:45 am
1953	CHIRP	New Model	New	High	Icom F10 / F20	10/07/2014 09:47 am
1963	CHIRP	New Model	New	High	ICOM IC-F34GT	10/14/2014 11:53 am
2061	CHIRP	New Model	New	High	Anytone AT-3318UV Support	11/19/2014 06:51 pm
2135	CHIRP	New Model	New	High	Zastone MP600 version (UHF or VHF model)	12/27/2014 04:35 pm
2139	CHIRP	Bug	New	High	Chirp not able to download from radio	01/21/2015 03:57 pm
2163	CHIRP	New Model	New	High	uv 5r v2 +	01/04/2015 07:29 pm
2167	CHIRP	Feature	New	High	Modify limits VHF FT-1D	01/06/2015 04:15 pm
2237	CHIRP	Bug	New	High	BAOFENG BF-F9V2+	01/23/2015 06:38 pm
2295	CHIRP	New Model	New	High	No estaria mal...	02/07/2015 11:47 am
2301	CHIRP	Bug	New	High	OS X Freezes between walkie swaps	02/07/2015 05:21 pm
2385	CHIRP	Bug	New	High	FT-2900 error message when adding new channel data through UI	03/04/2015 11:15 am
2421	CHIRP	Bug	New	High	Can download but not upload to Gt-3 mark 3	03/25/2015 08:50 am
2435	CHIRP	New Model	New	High	Wouxun KG-UV899	01/11/2016 07:40 am
2467	CHIRP	New Model	New	High	Icom F4GS and F25	03/29/2015 11:10 am
2545	CHIRP	Bug	New	High	[ft-7900] banks not working	04/28/2015 12:14 am
2577	CHIRP	New Model	New	High	HYT TC 2110	05/11/2015 09:07 pm
2607	CHIRP	New Model	New	High	AnyTone AT-3208UV	05/21/2015 06:43 pm
2625	CHIRP	Bug	New	High	Country	06/02/2015 12:24 pm
2667	CHIRP	New Model	New	High	Vertex/Yaesu VX-400	06/23/2015 05:30 am
2723	CHIRP	Bug	New	High	KK7DS Python Runtime R10 not installin on yosemite 10.10.3	07/16/2015 02:56 am
2777	CHIRP	Bug	New	High	baofeng BF-F9V2+ Port Driver issue.	11/21/2015 01:14 pm
2817	CHIRP	Bug	New	High	CHIRP does not upload only specified, but all, memories in new bank to VX6R	08/21/2015 04:11 pm
2991	CHIRP	Bug	New	High	CHIRP crashes due to bad UTF-8 in memory names	11/10/2015 03:42 am
3005	CHIRP	Bug	New	High	Doesn't load the Chirp with Puxing-777	11/16/2015 11:48 am
3075	CHIRP	Bug	New	High	Luiton LT-898uv	12/18/2015 09:26 pm
3111	CHIRP	Bug	New	High	TYT TH9000D	12/31/2015 01:17 pm

3165	CHIRP	Bug	New	High	CHIRP Linux - Daily 20160110 will not start	01/14/2016 04:10 am
3169	CHIRP	New Model	New	High	BF-F8-HP low or NO transmit	01/15/2016 01:53 am
3199	CHIRP	New Model	New	High	Icom ID-5100	01/21/2016 01:43 pm
3209	CHIRP	Bug	New	High	Does not set serial port info on debian Jessie	01/23/2016 05:31 pm
3233	CHIRP	New Model	New	High	ZASTONE MP-600 (UHF & VHF Models)	01/26/2016 02:23 pm
3335	CHIRP	Bug	New	High	FT-2800M	02/13/2016 06:24 pm
44	CHIRP	Bug	New	Normal	chirp XML editing problems	01/07/2012 10:50 pm
95	CHIRP	New Model	New	Normal	Support for Uniden Bearcat BC95XLT	03/30/2012 04:14 pm
129	CHIRP	Bug	New	Normal	Radio shows NFM for rx mode, but behaves as though it is in AM mode	04/30/2012 10:03 pm
142	CHIRP	Bug	New	Normal	csv inport ignores odd non step frequency on HF	04/23/2012 01:31 pm
169	CHIRP	Bug	New	Normal	VX-7 doesn't recognize memory groups until one is set on the radio's keypad	11/16/2015 09:47 pm
170	CHIRP	Bug	New	Normal	VX-7 reorganizes channels in memory groups nonsensically	05/15/2012 10:22 am
219	CHIRP	Bug	New	Normal	Unable to connect icom 92ad via usb serial adaptor	06/14/2012 01:41 pm
220	CHIRP	New Model	New	Normal	Kenwood models TK-3102(A) and TK-3212	02/15/2013 12:45 pm
227	CHIRP	Bug	New	Normal	Localization fail on 0.2.2 version	09/06/2012 05:02 pm
234	CHIRP	Feature	New	Normal	Batch memory editing	02/21/2013 02:43 pm
247	CHIRP	New Model	New	Normal	ICOM IC-T7H	07/17/2012 06:24 am
251	CHIRP	New Model	New	Normal	Kenwood TK-800-1	07/19/2012 02:23 pm
254	CHIRP	Bug	New	Normal	Alinco DR-235 CHIRP 'Download from Radio' error	01/25/2014 10:27 pm
263	CHIRP	Bug	New	Normal	OS X upload	09/05/2012 04:34 pm
267	CHIRP	Bug	New	Normal	Can't write _socket.pyd	08/06/2012 05:10 pm
272	CHIRP	Bug	New	Normal	CHIRP won't start on any of my systems: UTF-8 in path	09/05/2012 02:54 pm
274	CHIRP	Bug	New	Normal	Wouxun KG-UV6D save img - too few channels -export hangs	08/11/2012 09:42 pm
275	CHIRP	Feature	New	Normal	Repeaterbook Import Option: selectable source column for name	09/04/2012 10:17 am
277	CHIRP	New Model	New	Normal	KG-669/679/689/699	08/14/2012 03:28 am
286	CHIRP	Bug	New	Normal	Kenwood TH-F7 : cannot save memories with split frequencies	09/01/2012 03:45 am
300	CHIRP	Bug	New	Normal	Command to deinstall Chirp is wrong	09/10/2012 07:50 pm
311	CHIRP	Bug	New	Normal	FT-8800 only programs left side	09/23/2012 07:19 am
321	CHIRP	Bug	New	Normal	New User - Trying to Program Icom IC-U82	10/05/2012 06:26 am
327	CHIRP	Feature	New	Normal	VX7 220Mhz, instead of throwing error on power level, just "do the right thing"	10/14/2012 11:51 am
337	CHIRP	New Model	New	Normal	Icom IC706 mkII G	05/28/2015 11:41 am
343	CHIRP	New Model	New	Normal	Support of TYT TH-UVF9	10/31/2015 12:50 pm
351	CHIRP	New Model	New	Normal	Icom ID-1 (D-Star 1.2Ghz)	11/15/2012 08:28 am
353	CHIRP	Feature	New	Normal	TYT TH-UV3R	11/16/2012 03:50 pm
371	CHIRP	Bug	New	Normal	Export/Import should include Power level	02/07/2013 08:10 pm

382	CHIRP	New Model	New	Normal	Motorola MaxTrac/Radius/GM	02/15/2013 12:33 pm
383	CHIRP	New Model	New	Normal	Icom IC-F121/221	02/19/2013 10:41 am
385	CHIRP	Bug	New	Normal	Chirp not running on Mac OS 10.8.2	12/30/2012 05:29 pm
429	CHIRP	Bug	New	Normal	Insert row above	02/12/2013 05:45 pm
437	CHIRP	Feature	New	Normal	Setting in kg-uv2d	01/18/2013 11:56 am
459	CHIRP	Bug	New	Normal	ID-31A can't enter RPT1CALL or RPT2CALL	01/22/2013 12:32 pm
469	CHIRP	Feature	New	Normal	Puxing PX-2R - Entry/Edit of VHF Frequencies	01/27/2013 11:37 am
525	CHIRP	New Model	New	Normal	Vertex VX-2000u	12/31/2013 07:29 pm
529	CHIRP	New Model	New	Normal	FT-847	07/05/2013 02:07 pm
545	CHIRP	Feature	New	Normal	Present +/- offset UI for radios that only support odd-split	02/11/2013 05:56 pm
555	CHIRP	New Model	New	Normal	HYS UV-55	12/01/2013 07:43 pm
561	CHIRP	Bug	New	Normal	Unable to write to the radio	02/14/2013 10:49 am
565	CHIRP	Bug	New	Normal	Incorrect CTCSS tone getting set regardless of my trying to correct.	02/18/2013 09:50 am
567	CHIRP	New Model	New	Normal	IC-910	02/15/2013 09:24 am
577	CHIRP	Bug	New	Normal	Tuning step/frequency	02/16/2013 12:48 pm
579	CHIRP	New Model	New	Normal	Icom IC-T90A	12/01/2015 10:43 am
607	CHIRP	Feature	New	Normal	Hot key for Skipping	02/21/2013 07:24 am
611	CHIRP	New Model	New	Normal	Wouxun KG-920R-A	02/22/2013 10:55 pm
641	CHIRP	New Model	New	Normal	Icom M802	03/02/2013 06:14 am
651	CHIRP	Feature	New	Normal	VX-8 Support programmable (band limit) memory scan (PMS) and skip channels	07/13/2014 03:29 pm
677	CHIRP	Feature	New	Normal	VXA-700 MARS/CAP Unlock	02/27/2015 06:28 pm
679	CHIRP	Bug	New	Normal	VXA-700 Tone vs TSQL settings	06/14/2013 11:14 am
681	CHIRP	Feature	New	Normal	Support regional band plans	03/12/2013 05:09 pm
683	CHIRP	Bug	New	Normal	Automatic Repeater Offset configuration is applied inconsistently	03/12/2013 06:39 pm
689	CHIRP	New Model	New	Normal	DJ-V57 Alinco support	03/13/2013 11:30 am
699	CHIRP	New Model	New	Normal	Alinco DJ-G7	03/14/2013 05:20 pm
703	CHIRP	New Model	New	Normal	TAIT 2020 Series EM-PMR	03/15/2013 01:50 pm
705	CHIRP	New Model	New	Normal	ICOM IC-V21AT	07/24/2013 07:46 pm
707	CHIRP	New Model	New	Normal	Yaesu FT-2500M	07/24/2013 07:47 pm
711	CHIRP	Bug	New	Normal	Repeaterbook query in DC does not work	03/18/2013 01:32 pm
713	CHIRP	Bug	New	Normal	Repeaterbook support for Canada	03/18/2013 01:32 pm
725	CHIRP	Bug	New	Normal	icom ic-70e	03/28/2013 03:28 am
733	CHIRP	New Model	New	Normal	Kenwood TH-22AT/42AT	07/24/2013 04:23 pm
743	CHIRP	Bug	New	Normal	tk 8180 kenwood	04/01/2013 05:27 pm
777	CHIRP	Feature	New	Normal	Add option to set DTR and RTS	10/29/2013 04:09 pm

779	CHIRP	Bug	New	Normal	Delete (and shift up) Problems	04/12/2013 05:22 pm
793	CHIRP	Bug	New	Normal	Icom 2200H Power Incorrect	04/20/2013 05:28 pm
795	CHIRP	Bug	New	Normal	Kenwood TM-281A doesn't save memory channels with 2.5 kHz frequency steps	04/20/2013 05:08 pm
797	CHIRP	New Model	New	Normal	Icom IC-V8	04/21/2013 03:33 am
799	CHIRP	Bug	New	Normal	Comm Port	04/21/2013 03:56 pm
805	CHIRP	Bug	New	Normal	Wouxun UV6D - UART cable error	04/25/2013 02:09 am
807	CHIRP	New Model	New	Normal	ICOM IC-V80	04/23/2013 12:33 pm
811	CHIRP	New Model	New	Normal	ADI AT600 Kenwood TS-2000	04/27/2013 09:55 pm
819	CHIRP	New Model	New	Normal	Puxing PX-888D UHF	10/06/2013 11:38 am
821	CHIRP	Feature	New	Normal	[VX-8DR] Add settings menu	04/30/2013 02:35 pm
827	CHIRP	Feature	New	Normal	Being able to add an agency using radio reference	05/03/2013 09:37 am
829	CHIRP	New Model	New	Normal	Ritron DTX-150	04/30/2014 07:22 pm
831	CHIRP	New Model	New	Normal	Ritron DTX-450	04/30/2014 07:24 pm
839	CHIRP	New Model	New	Normal	IC-2800	09/18/2014 05:43 pm
847	CHIRP	Bug	New	Normal	FTM-350 does not allow symbols in the channel name	05/04/2013 06:16 pm
861	CHIRP	New Model	New	Normal	TM-471A	05/08/2013 04:10 pm
865	CHIRP	Bug	New	Normal	Import of .chirp fails on Mac OS	05/09/2013 06:51 pm
869	CHIRP	Bug	New	Normal	Moving memories should update bank membership	05/13/2013 02:23 pm
873	CHIRP	Bug	New	Normal	Fail to open download dialog on Windows 8	05/19/2013 05:44 am
879	CHIRP	New Model	New	Normal	Yaesu 1000MP MKV	05/23/2013 09:38 pm
883	CHIRP	Bug	New	Normal	Incorrect AM mode after download from YAESU FT-8900R	05/26/2013 09:55 am
893	CHIRP	New Model	New	Normal	Yaesu VX-150	02/08/2014 06:10 pm
895	CHIRP	New Model	New	Normal	Kenwood TS-590s	12/30/2015 10:21 am
897	CHIRP	Bug	New	Normal	Unable to disable transmit on Baofeng UV5R+Plus (firmware BFB297)	06/03/2013 03:42 pm
899	CHIRP	New Model	New	Normal	Wouxun KG-UV920R	06/03/2013 03:50 am
903	CHIRP	New Model	New	Normal	i have i old icom model ic-gm1500e	06/03/2013 02:55 pm
907	CHIRP	Bug	New	Normal	uv-5r memory zero keeps defaulting to 136.025	06/04/2013 03:47 am
921	CHIRP	Bug	New	Normal	Incomplete CSV data	06/10/2013 07:18 am
923	CHIRP	New Model	New	Normal	Baofeng UV-6	07/24/2013 12:59 am
927	CHIRP	New Model	New	Normal	ALT-669	06/14/2013 04:04 am
929	CHIRP	Bug	New	Normal	Alinco DR-235TMKIII not programming NFM	06/14/2013 08:15 pm
941	CHIRP	New Model	New	Normal	Request support for Duet DT-UVD1P	06/27/2013 05:41 pm
943	CHIRP	Feature	New	Normal	MacOS uses Command key, not Control Key for short cuts.	06/27/2013 01:26 pm
951	CHIRP	New Model	New	Normal	Yaesu FT-450D	07/03/2013 10:50 am
953	CHIRP	Feature	New	Normal	Extend Range on TYT TH-UV3R	07/05/2013 02:57 pm

955	CHIRP	Bug	New	Normal	Icom 91AD	07/08/2013 12:31 pm
959	CHIRP	New Model	New	Normal	ICOM IC-2300H support	06/05/2015 12:38 pm
965	CHIRP	New Model	New	Normal	AOR AR-3000A	07/10/2013 08:34 am
989	CHIRP	Feature	New	Normal	Tooltips on column and field labels?	07/17/2013 03:16 am
991	CHIRP	Feature	New	Normal	Showing VFO settings separate from memory channels	07/17/2013 03:19 am
999	CHIRP	New Model	New	Normal	Suicom VU King not supported model	07/18/2013 01:36 pm
1003	CHIRP	New Model	New	Normal	The new Icom IC-7100	02/06/2016 09:10 pm
1017	CHIRP	Feature	New	Normal	Add fields to TYT TH-UV3R	01/29/2015 09:23 pm
1027	CHIRP	Bug	New	Normal	Rfinder importation does not work	07/26/2013 06:35 am
1029	CHIRP	New Model	New	Normal	TDXone TD-Q8	07/26/2013 01:13 pm
1039	CHIRP	Feature	New	Normal	Support for Zonton 999G / Anytone 288	07/30/2013 06:10 am
1043	CHIRP	Bug	New	Normal	VX-6 Datafile will not Transmit to VX-3	07/31/2014 05:22 pm
1045	CHIRP	Bug	New	Normal	sort issue, frequency column, import dialog	08/03/2013 02:15 pm
1047	CHIRP	Feature	New	Normal	Chirp won't run in a Python virtualenv	08/03/2013 03:20 pm
1049	CHIRP	New Model	New	Normal	Kirisun radio's	08/06/2013 08:30 am
1051	CHIRP	New Model	New	Normal	IC-M88	08/07/2013 07:59 am
1053	CHIRP	Bug	New	Normal	Baojie BJ-UV99	08/07/2013 08:46 am
1055	CHIRP	New Model	New	Normal	Baojie BJ-UV99	08/07/2013 08:53 am
1057	CHIRP	New Model	New	Normal	Support of TYT TH-UVF8D	10/06/2013 01:39 pm
1063	CHIRP	Bug	New	Normal	Cannot add more than 278 memory entries from .chirp or .csv import to Kenwood TH-F6A	08/13/2013 04:38 pm
1067	CHIRP	New Model	New	Normal	M710 support	08/14/2013 08:26 am
1071	CHIRP	New Model	New	Normal	HYS TC-171	08/29/2013 07:34 pm
1075	CHIRP	Bug	New	Normal	Chirp don't work with may UV-5RC	08/17/2013 07:50 am
1081	CHIRP	Bug	New	Normal	wrong repeater offset in Icom ID-51	08/18/2013 04:48 pm
1085	CHIRP	Bug	New	Normal	VX3R FM Broadcast Memory Does not Work	08/20/2013 07:59 pm
1089	CHIRP	Bug	New	Normal	stock_configs file not opening properly in Windows 8	08/26/2013 04:05 pm
1091	CHIRP	Bug	New	Normal	Issue #1089 I have finally created stock_config files with great difficulty	12/30/2015 11:53 am
1093	CHIRP	New Model	New	Normal	Kenwood TK-690/790/890	08/25/2013 11:59 am
1095	CHIRP	New Model	New	Normal	Kenwood TK-3107 \ SCMY 3117	08/27/2013 04:32 am
1099	CHIRP	New Model	New	Normal	Yaesu FT-270R	08/28/2013 02:08 pm
1103	CHIRP	Bug	New	Normal	unable to write to Yaesu VX5R	08/30/2013 08:07 pm
1121	CHIRP	New Model	New	Normal	Yaesu 8000R support	09/07/2013 02:02 pm
1141	CHIRP	New Model	New	Normal	IC-T2H	09/18/2013 06:21 pm
1153	CHIRP	Bug	New	Normal	CHIRP Won't launch to desktop: Win7	09/28/2013 11:41 pm
1155	CHIRP	Bug	New	Normal	chirpw crashes on "pyver.split" on OpenSuSE 11.4	09/30/2013 09:03 am

1165	CHIRP	New Model	New	Normal	FTM-350AR	10/13/2013 04:28 am
1167	CHIRP	Bug	New	Normal	KG-UV3D 220/144 limited settings	10/31/2013 02:35 am
1173	CHIRP	Feature	New	Normal	IC-208H - F-1 and F-2 mic buttons not supported	10/15/2013 06:13 pm
1175	CHIRP	New Model	New	Normal	Quansheng TG-UV2	02/26/2014 02:39 am
1203	CHIRP	Bug	New	Normal	[VX-3] banks not recognized by radio if banks have not been used before	10/26/2013 07:58 pm
1223	CHIRP	Bug	New	Normal	vx-2	11/16/2013 03:54 pm
1225	CHIRP	New Model	New	Normal	Baofeng UV-8	09/24/2015 02:40 pm
1227	CHIRP	Bug	New	Normal	TYT TH-UV3R :: radio does not upload memories to CHIRP	11/09/2013 03:25 pm
1229	CHIRP	Bug	New	Normal	To add Yaesu FT-8100 to the programming ability listing.	01/15/2015 08:27 am
1233	CHIRP	New Model	New	Normal	Add Yaesu FT-50R	10/29/2014 10:03 pm
1237	CHIRP	New Model	New	Normal	Puxing PX-UV973 - dual-band cross-band repeat radio	11/14/2013 07:58 pm
1241	CHIRP	Bug	New	Normal	locales not included in Linux builds	11/27/2013 06:35 am
1269	CHIRP	Feature	New	Normal	Linux documentation for connection permission-denied	01/26/2014 04:43 pm
1285	CHIRP	New Model	New	Normal	Blackbox plus radios?	12/04/2013 06:25 pm
1289	CHIRP	Feature	New	Normal	add basic settings support to for Yaesu VX-6	12/07/2013 06:59 pm
1291	CHIRP	Feature	New	Normal	add basic settings support for Yaesu VX-3	12/07/2013 07:08 pm
1293	CHIRP	New Model	New	Normal	ALINCO DJ-190T/DJ-191T	12/12/2013 07:38 am
1303	CHIRP	New Model	New	Normal	FDC FD-850 Plus	01/31/2016 09:06 am
1311	CHIRP	New Model	New	Normal	ALinco DR-635	12/18/2013 07:50 am
1313	CHIRP	New Model	New	Normal	Alinco DR-620	12/21/2013 07:30 pm
1315	CHIRP	Feature	New	Normal	[uv-b5] additional settings	12/25/2013 08:23 am
1321	CHIRP	Bug	New	Normal	Baofeng UV-5S "Unknown response from radio"	12/27/2013 03:05 pm
1325	CHIRP	New Model	New	Normal	Ritron RTX-450	04/30/2014 07:22 pm
1327	CHIRP	Bug	New	Normal	TH-UVF1 open image detection fail	12/28/2013 08:03 pm
1329	CHIRP	Bug	New	Normal	TH-UVF1 "Error in setting value: String expects exactly 6 characters"	12/28/2013 08:07 pm
1331	CHIRP	New Model	New	Normal	Yaesu VR-5000	12/28/2013 07:56 pm
1339	CHIRP	New Model	New	Normal	baofeng uv-8d	12/31/2013 04:56 am
1345	CHIRP	Bug	New	Normal	icom ic-t70E banks	01/03/2014 04:18 am
1351	CHIRP	New Model	New	Normal	Wouxun KG-UV5 Support	01/06/2014 07:39 am
1361	CHIRP	New Model	New	Normal	"New Model" Icom IC-V8	01/08/2014 01:57 pm
1363	CHIRP	New Model	New	Normal	Alinco DJ-G29 & DJ-G7	10/29/2014 10:05 pm
1365	CHIRP	Bug	New	Normal	Anytone frequency errors	09/29/2015 03:44 pm
1373	CHIRP	Bug	New	Normal	Error when downloading from VX-8DR on Mac	01/15/2014 06:53 pm
1379	CHIRP	Bug	New	Normal	UV 82 firmware B82S1	01/17/2014 03:37 am
1383	CHIRP	Bug	New	Normal	px-2r can't read digital code	01/23/2014 09:11 am

1385	CHIRP	New Model	New	Normal	TYT-9000	03/10/2015 06:34 pm
1409	CHIRP	New Model	New	Normal	IC-T81A for loan, perhaps purchase and loan DJ-G29T	01/26/2014 04:55 pm
1427	CHIRP	Bug	New	Normal	Baofeng CTCSS setup wont save/load	02/05/2014 04:55 pm
1431	CHIRP	New Model	New	Normal	Support for Yedro YC-555D	02/05/2014 11:29 pm
1437	CHIRP	Bug	New	Normal	tpe exports	02/10/2014 06:27 pm
1441	CHIRP	Bug	New	Normal	BF-888S won't enter programming mode - extra character before ACK	05/14/2014 09:20 pm
1453	CHIRP	New Model	New	Normal	Iradio UV-F9	03/03/2014 12:41 pm
1455	CHIRP	New Model	New	Normal	Puxing PX-A6 (UHF 400-470MHz)	02/23/2014 09:39 am
1459	CHIRP	Bug	New	Normal	ICOM IC-W32A - CP2102 USB to UART - Mac OSX 10.9.1 - Download from radio fine, Upload to radio fails	02/23/2014 06:19 pm
1463	CHIRP	Bug	New	Normal	uv-5r bug	02/28/2014 07:47 pm
1467	CHIRP	New Model	New	Normal	Yaesu FT-8100R	04/19/2014 02:25 pm
1469	CHIRP	New Model	New	Normal	Yaesu FTM-400DR and FTM-400DE	09/05/2015 06:04 pm
1475	CHIRP	Bug	New	Normal	Yaesu VX-8 Upload	03/04/2014 09:38 am
1481	CHIRP	New Model	New	Normal	IC-V8000	09/21/2014 12:26 pm
1491	CHIRP	Bug	New	Normal	AnyTone AT-5888UV tone squelch programming problem	01/19/2016 08:19 am
1505	CHIRP	New Model	New	Normal	Vero VR-500	03/19/2014 08:12 am
1511	CHIRP	Bug	New	Normal	VX-8R Failure to Communicate with the Radio: Received Incomplete Image from Radio	07/24/2014 12:24 pm
1523	CHIRP	New Model	New	Normal	Wouxun KG-UV3X Pro	01/14/2015 10:19 pm
1537	CHIRP	Bug	New	Normal	Missing translation strings	12/30/2015 02:17 pm
1539	CHIRP	Bug	New	Normal	Error setting memory: Tuning step 100.00 not supported	04/06/2014 01:50 pm
1541	CHIRP	New Model	New	Normal	Icom ic R10	04/06/2014 08:57 pm
1547	CHIRP	Bug	New	Normal	[FT-60] Chirp should check parity on download	02/01/2015 11:37 pm
1553	CHIRP	Bug	New	Normal	The right clicked editor window don't show memory "extra" fields if the respective line is empty	04/11/2014 03:09 am
1575	CHIRP	New Model	New	Normal	Please Add Support for Zastone ZT-9908 dPMR	04/23/2014 05:55 am
1579	CHIRP	Bug	New	Normal	radio not responding anymore	04/27/2014 07:02 am
1583	CHIRP	Bug	New	Normal	ft60 chirp woes	04/27/2014 12:37 pm
1593	CHIRP	Bug	New	Normal	No me arranca el programa	04/29/2014 10:29 am
1599	CHIRP	New Model	New	Normal	Ritron JMX-150	04/30/2014 07:18 pm
1601	CHIRP	New Model	New	Normal	YAESU FTM400DR	04/30/2014 09:07 pm
1603	CHIRP	Bug	New	Normal	clone error, then port access denied	07/31/2014 05:17 pm
1609	CHIRP	Bug	New	Normal	Copying from one list to another	05/02/2014 04:47 pm
1611	CHIRP	Bug	New	Normal	Kenwood TH-D72A: Programming 2m repeater results in non-functional memory channel	05/08/2014 08:13 am
1613	CHIRP	New Model	New	Normal	CS700	05/11/2014 10:30 am

1615	CHIRP	Bug	New	Normal	Yaesu VX-8DR - Cannot be imported because mode NFM not supported	08/14/2014 01:03 pm
1617	CHIRP	Bug	New	Normal	UV-6	08/14/2014 02:19 pm
1619	CHIRP	Bug	New	Normal	FT8800 Banks no programming on RH side	05/07/2014 04:21 pm
1621	CHIRP	Bug	New	Normal	KG-UV6D	05/08/2014 11:12 am
1629	CHIRP	Bug	New	Normal	Update requested but no update comes	08/10/2014 07:09 am
1631	CHIRP	Bug	New	Normal	Unicode character in path	08/10/2014 09:17 am
1633	CHIRP	Bug	New	Normal	Kenwood TM-D700 not supported.	05/14/2014 11:59 pm
1635	CHIRP	New Model	New	Normal	add puxing px-uv973	05/15/2014 10:43 pm
1637	CHIRP	Bug	New	Normal	[TM-271] missing tuning steps	05/16/2014 11:41 am
1645	CHIRP	New Model	New	Normal	Nanfone NF-569 and alike	05/20/2014 11:38 am
1647	CHIRP	New Model	New	Normal	Support for ICOM ID-5100A	08/11/2015 06:23 pm
1651	CHIRP	Feature	New	Normal	[UV-82] Add Additional Settings and Expand Frequency Range [uv5r.py]	05/22/2014 03:43 pm
1653	CHIRP	New Model	New	Normal	Icom IC-T81a	05/24/2014 06:23 am
1657	CHIRP	New Model	New	Normal	Puxing UV-973	09/09/2015 03:23 pm
1659	CHIRP	New Model	New	Normal	Puxing PX-888K	01/18/2015 10:50 am
1661	CHIRP	New Model	New	Normal	Add Support for Wouxun KG-UV5D	05/27/2014 10:41 am
1665	CHIRP	Bug	New	Normal	Kenwood TM-D700 will only allow freq change, not pl or others	05/29/2014 02:37 pm
1679	CHIRP	New Model	New	Normal	Wouxun KG-699E	06/02/2014 04:20 pm
1681	CHIRP	Feature	New	Normal	[developer] Control fontsize of hex diff/dump display	12/30/2015 12:04 pm
1683	CHIRP	Bug	New	Normal	Unsupported band limits 0xef for PX-777 submodel 328	06/05/2014 01:16 pm
1685	CHIRP	Bug	New	Normal	Problem run program with russian characters in windows account name.	08/10/2014 08:27 am
1697	CHIRP	Feature	New	Normal	[developer] Control fontsize of file browser display	06/18/2014 02:00 pm
1699	CHIRP	Feature	New	Normal	[developer] Add diffs-only mode to file diff utility	06/18/2014 08:34 pm
1717	CHIRP	New Model	New	Normal	Yaesu FT-270R	04/04/2015 10:19 am
1721	CHIRP	New Model	New	Normal	Yaesu FTM-400 and FTDR1 C4FM radios	06/28/2014 11:33 am
1729	CHIRP	Bug	New	Normal	Problem with saving of data	07/02/2014 04:02 am
1745	CHIRP	New Model	New	Normal	Alinco DJ-V57T	07/07/2014 08:50 pm
1747	CHIRP	New Model	New	Normal	Maxon SM-4150M	07/07/2014 08:55 pm
1749	CHIRP	Bug	New	Normal	Anytone at5888uv Short Read	02/15/2015 03:51 am
1753	CHIRP	Feature	New	Normal	[developer] Add info re: hex dump modes to "Diff Radios" dialog	07/11/2014 05:29 pm
1755	CHIRP	New Model	New	Normal	Yaesu FTM-400de	07/13/2014 03:43 am
1763	CHIRP	Bug	New	Normal	Please create an AppData file for chirp	07/14/2014 02:49 pm
1767	CHIRP	Feature	New	Normal	[developer] Control address format for full-file dump/diff	07/15/2014 11:33 am
1769	CHIRP	Bug	New	Normal	Getting Chirp to Run on a MacBook running OS 10.8.5	08/10/2014 07:52 am
1775	CHIRP	Bug	New	Normal	Puxing 777	07/20/2014 10:15 am

1779	CHIRP	Feature	New	Normal	[UI] Enable "Hide Unused Fields" by default	07/29/2014 05:39 pm
1783	CHIRP	New Model	New	Normal	CRT 270M	07/24/2014 02:59 am
1785	CHIRP	Bug	New	Normal	Yaesu FT-8800 - Right side not getting all settings loaded	10/14/2014 11:12 am
1787	CHIRP	Feature	New	Normal	[developer] More informative Diff tabs window title	07/25/2014 07:40 am
1793	CHIRP	New Model	New	Normal	Polmar Work	07/27/2014 01:13 am
1795	CHIRP	New Model	New	Normal	Icom IC-F1010	07/28/2014 07:28 am
1797	CHIRP	Bug	New	Normal	Misleading Message "An ERROR has Occurred"	08/02/2014 07:37 am
1803	CHIRP	New Model	New	Normal	Wouxun KG833 programming	08/01/2014 05:39 pm
1805	CHIRP	Bug	New	Normal	Rename/Delete and Shift memory clears bank membership	08/02/2014 06:15 pm
1807	CHIRP	Feature	New	Normal	Add settings to VX-8 module	08/03/2014 04:48 pm
1813	CHIRP	Bug	New	Normal	Settings Tab Accessibility using the Orca screen reader	08/05/2014 06:04 am
1817	CHIRP	Bug	New	Normal	VX-8: Cleanup patch, add DTMF settings	08/09/2014 11:11 am
1819	CHIRP	New Model	New	Normal	Please add support for Wouxun KG-UV920P	08/09/2014 06:35 pm
1823	CHIRP	Bug	New	Normal	Split mode Duplex bug -- Input Frequency column suggestion	08/10/2014 09:38 pm
1825	CHIRP	Feature	New	Normal	Error setting memory: Frequency 0.000000 is out of supported range	08/10/2014 10:21 pm
1843	CHIRP	Bug	New	Normal	Alinco dr-135t -Failure to communicate with radio: Radio returned less than 16 bits	08/16/2014 04:59 am
1845	CHIRP	New Model	New	Normal	DR-635	11/29/2014 08:31 am
1859	CHIRP	New Model	New	Normal	Wouxun KG-UV2D Supported?	08/23/2014 09:58 am
1863	CHIRP	Feature	New	Normal	[KG-UV6]Improve Support for the Powerwerx Wouxun KG-UV6X	08/23/2014 04:00 pm
1877	CHIRP	Bug	New	Normal	Slow to program Yaesu FT-8800R	08/31/2014 05:32 pm
1879	CHIRP	Bug	New	Normal	Tonfa TF-Q5 transceiver not recognized.	08/30/2014 03:18 pm
1885	CHIRP	Bug	New	Normal	IC80AD upload crashes Mac 10.9.4	09/17/2014 01:48 pm
1889	CHIRP	Bug	New	Normal	Crash on attempt to upload	09/02/2014 02:50 am
1891	CHIRP	Bug	New	Normal	Unable to copy/paste memories on FT-8800R	02/18/2016 09:45 pm
1893	CHIRP	Bug	New	Normal	SFE S850UV	09/04/2014 08:40 am
1895	CHIRP	Bug	New	Normal	Non Standard CTCSS Tones	09/06/2014 05:24 pm
1899	CHIRP	Bug	New	Normal	IC-T8A Frequency upload/download error xxx.xx5 MHz	09/10/2014 07:35 am
1905	CHIRP	New Model	New	Normal	Wouxun KG-UV920P	09/12/2014 08:56 pm
1923	CHIRP	Bug	New	Normal	setting baofeng to tx and rx out of the range	09/21/2014 03:41 pm
1927	CHIRP	Bug	New	Normal	Baofeng GT-3 programming causes dead receive	09/22/2014 02:57 am
1935	CHIRP	Feature	New	Normal	Auto Set Duplex and offset on import	09/25/2014 09:28 am
1937	CHIRP	Bug	New	Normal	DR-06 programming issue	09/25/2014 02:29 pm
1943	CHIRP	New Model	New	Normal	Icom IC-V8 as developer trainee	09/28/2014 10:52 am
1947	CHIRP	New Model	New	Normal	Question regarding programming software for Icom IC-P7A	10/05/2014 11:58 am
1961	CHIRP	New Model	New	Normal	ID-51A Anniversary Edition	08/11/2015 06:24 pm

1965	CHIRP	Bug	New	Normal	Yaesu 8800R Right Side Memory Banks Not Programming	08/20/2015 10:02 am
1987	CHIRP	New Model	New	Normal	programming for Kenwood tk-370G-1 radio	10/22/2014 12:02 am
2003	CHIRP	Bug	New	Normal	Channel Skip Not working on BAOFeng UF-5R	10/29/2014 02:37 pm
2007	CHIRP	Feature	New	Normal	Find duplicate channels function suggestion	10/29/2014 11:01 pm
2013	CHIRP	Feature	New	Normal	RFinder routes query	10/31/2014 01:32 pm
2021	CHIRP	Bug	New	Normal	incorrect read length error for Wouxun KG-UV3D MacOS X 10.10 Yosemite w/NoZAP PL2303 and WXUSB cable	12/06/2014 11:59 am
2023	CHIRP	New Model	New	Normal	Midland CT-710	11/07/2014 01:14 am
2041	CHIRP	Bug	New	Normal	Squelch	11/10/2014 10:43 pm
2051	CHIRP	New Model	New	Normal	Add support for Vertex FLT-2011	12/30/2015 12:10 pm
2059	CHIRP	New Model	New	Normal	Yaesu FT-270R	05/05/2015 10:27 am
2063	CHIRP	Bug	New	Normal	HYT	11/20/2014 11:28 am
2065	CHIRP	Bug	New	Normal	Cannot upload nor download from FT-60	11/28/2014 09:11 am
2071	CHIRP	Bug	New	Normal	[BF-F8HP] Add Support for N5R3401 Firmware	11/24/2014 11:43 am
2077	CHIRP	New Model	New	Normal	PRO96 / DTS96	11/26/2014 02:20 am
2079	CHIRP	Bug	New	Normal	Uploading on IC-V82 hangs at 50%	11/27/2014 11:07 am
2083	CHIRP	New Model	New	Normal	Alinco DR-635	02/15/2015 08:32 am
2087	CHIRP	Bug	New	Normal	Windows: Serial port handle not freed after exception thrown in chirpw	12/11/2014 08:24 pm
2089	CHIRP	Feature	New	Normal	Kenwood TM-D710A - support memory channels L0-9, U0-9	11/30/2014 04:57 pm
2111	CHIRP	Bug	New	Normal	'hacked' UV-B5 settings not read back	12/17/2014 12:48 am
2119	CHIRP	Feature	New	Normal	[VV-898] Updates to Prepare for Adding User Settings	12/23/2014 06:15 pm
2121	CHIRP	Bug	New	Normal	[VV-898] Changing to "Low" Power Level Does Not Stick	12/23/2014 06:34 pm
2123	CHIRP	Feature	New	Normal	[VV-898] Add Support for TX Inhibited Memories	12/23/2014 07:18 pm
2125	CHIRP	Bug	New	Normal	ICOM IC-T70A Upload Error	12/25/2014 07:48 am
2127	CHIRP	New Model	New	Normal	Yaesu FT-51R	12/25/2014 09:12 am
2129	CHIRP	New Model	New	Normal	TYT TH-F5	12/26/2014 09:22 am
2131	CHIRP	Bug	New	Normal	New Baofeng UV-B5 - Radio did Not Ack ... - OEM soft-Ok	08/18/2015 02:22 am
2145	CHIRP	Bug	New	Normal	Wouxun KG-UV8D Mode and Power	01/02/2015 12:14 pm
2149	CHIRP	Feature	New	Normal	[VV-898] Add Settings to Leixen VV-898 Module	12/30/2014 03:59 pm
2157	CHIRP	Feature	New	Normal	New Radio(s) Request	01/03/2015 06:59 pm
2189	CHIRP	Bug	New	Normal	CAN NOT DOWN LOAD	01/12/2015 03:35 pm
2203	CHIRP	Bug	New	Normal	Mac OS Yosemite "LSOpenURLsWithRole() failed with error -10810"	01/15/2015 09:28 am
2207	CHIRP	Bug	New	Normal	FT-8800R Upload Programming Issue	01/15/2015 12:23 pm
2241	CHIRP	New Model	New	Normal	kennwood tk-3160	01/23/2015 11:12 am
2243	CHIRP	Bug	New	Normal	VX-3R off frequency when programmed with CHIRP	06/22/2015 08:11 am

2245	CHIRP	New Model	New	Normal	Yaesu FT-400DR	10/08/2015 07:16 am
2253	CHIRP	New Model	New	Normal	Icom E-7 & Icom T81	01/30/2016 02:50 pm
2257	CHIRP	New Model	New	Normal	Wouxun KG-UVA1 support	01/25/2015 11:06 pm
2263	CHIRP	Bug	New	Normal	Newest hungarian translation	01/29/2015 06:05 am
2271	CHIRP	Bug	New	Normal	Unable to program F8Hp with chirp	01/30/2015 06:54 pm
2277	CHIRP	Bug	New	Normal	download from ID-880H results in "unexpected response from radio"	01/31/2015 06:14 pm
2281	CHIRP	Bug	New	Normal	Error setting memory: Unable to calculate the required tuning step for 165.678750	02/03/2015 12:36 pm
2283	CHIRP	Bug	New	Normal	Raw memory indexes on special chans are invalid	02/01/2015 11:21 pm
2287	CHIRP	Feature	New	Normal	Wouxun KG-UV8D	02/04/2015 03:58 pm
2291	CHIRP	Feature	New	Normal	"off" duplex for H-777	02/06/2015 04:09 pm
2293	CHIRP	New Model	New	Normal	UV-B5 with new firmware (27 menu entries) currently not supported	10/13/2015 01:21 am
2297	CHIRP	Feature	New	Normal	chirpw launch script for Windows	02/07/2015 11:43 am
2303	CHIRP	Bug	New	Normal	Problem programming Yaesu FT-2800M. Two different cables work with software from another vendor	02/10/2015 07:58 am
2305	CHIRP	New Model	New	Normal	TYT DM-UVF10	02/20/2015 07:51 am
2311	CHIRP	New Model	New	Normal	Quansheng TG-UV2	05/23/2015 11:59 pm
2323	CHIRP	Bug	New	Normal	Marine Frequencies	12/23/2015 01:09 pm
2327	CHIRP	Bug	New	Normal	Kenwood TM-281A Offset Changes Following Chirp	02/17/2015 04:23 pm
2329	CHIRP	Bug	New	Normal	Wouxun KG-UV8D Display Message Won't Upload to Radio	02/17/2015 04:33 pm
2331	CHIRP	Bug	New	Normal	TYT TH-9800 won't import split tone frequencies.	02/18/2015 07:45 pm
2333	CHIRP	Bug	New	Normal	got a nv-5 that will not accept CHIRP	02/19/2015 05:01 pm
2337	CHIRP	New Model	New	Normal	TYT DM-UVF10	02/20/2015 07:55 am
2345	CHIRP	New Model	New	Normal	I have wanted to ask this for a while	02/23/2015 04:46 pm
2349	CHIRP	Feature	New	Normal	add option parsing to chirpw	02/24/2015 03:00 am
2353	CHIRP	New Model	New	Normal	Icom V80E	02/24/2015 05:17 am
2361	CHIRP	Bug	New	Normal	Allow copying between radios where some settings are not supported	02/25/2015 12:51 pm
2363	CHIRP	Bug	New	Normal	chirp will not start of PC - windows 7	02/25/2015 03:40 pm
2371	CHIRP	New Model	New	Normal	support VX-1R	02/27/2015 08:36 am
2373	CHIRP	New Model	New	Normal	FTM-400D	07/24/2015 10:45 pm
2379	CHIRP	New Model	New	Normal	Yeasu FT-2400	03/01/2015 09:39 pm
2381	CHIRP	Bug	New	Normal	FT-2900 should support banks	03/02/2015 03:49 pm
2387	CHIRP	Bug	New	Normal	Baofeng BF-F8HP Cant edit file after uploading from radio	03/04/2015 12:17 pm
2395	CHIRP	New Model	New	Normal	icom IC-V8	03/07/2015 06:27 pm
2397	CHIRP	Bug	New	Normal	file	03/08/2015 10:26 am
2399	CHIRP	New Model	New	Normal	FT-7100 support	09/10/2015 10:12 am

2405	CHIRP	Bug	New	Normal	Chirp does not save/load subaudible tone frequencies properly	03/11/2015 07:58 am
2409	CHIRP	Bug	New	Normal	Icom IC-2100H says "Unexpected response from radio"	03/12/2015 07:27 pm
2413	CHIRP	Bug	New	Normal	px-2r download fail	03/13/2015 01:51 pm
2415	CHIRP	Bug	New	Normal	Code downloaded incorrectly	03/13/2015 02:36 pm
2417	CHIRP	Bug	New	Normal	Name set in chirp not set in a radio	03/13/2015 02:18 pm
2419	CHIRP	New Model	New	Normal	Nanfone NF-6600	03/15/2015 11:33 am
2423	CHIRP	Bug	New	Normal	FT-2900 does not support odd splits.	03/14/2015 04:49 pm
2425	CHIRP	Feature	New	Normal	Add custom mic keys to settings	03/15/2015 08:36 am
2429	CHIRP	Feature	New	Normal	Import State agencies through Radio Reference	03/15/2015 02:28 pm
2433	CHIRP	Feature	New	Normal	FT-2900 should support cross tones	03/16/2015 07:32 pm
2441	CHIRP	Bug	New	Normal	VX8DR	03/18/2015 07:40 pm
2443	CHIRP	New Model	New	Normal	uv-9r+hp	03/19/2015 09:55 am
2445	CHIRP	Bug	New	Normal	FT-2900 doesn't always download cross tones that were entered via radio's UI	03/19/2015 09:00 pm
2449	CHIRP	Bug	New	Normal	CHIRP won't Open on Windows 7 32 bit	03/23/2015 02:38 pm
2453	CHIRP	Bug	New	Normal	Bug Report & Questions/Comments	03/24/2015 10:20 am
2455	CHIRP	Bug	New	Normal	TH-D72a clone image: 2m channels don't work, radio does not transmit	01/21/2016 05:30 am
2489	CHIRP	New Model	New	Normal	TYT TH-F8	04/02/2015 04:00 am
2491	CHIRP	New Model	New	Normal	Alinco DR-605 support	04/02/2015 02:09 pm
2493	CHIRP	New Model	New	Normal	Alinco DJ-296	04/03/2015 12:49 am
2495	CHIRP	New Model	New	Normal	Infinity P-1000 VHF	04/04/2015 09:12 am
2497	CHIRP	Bug	New	Normal	unable to load module:cannot import name	04/04/2015 01:32 pm
2503	CHIRP	Bug	New	Normal	Baofeng uv85c	04/06/2015 06:06 pm
2505	CHIRP	Bug	New	Normal	FT-2900 split tones entered via CHIRP UI can cause lock-ups	04/06/2015 09:56 pm
2513	CHIRP	New Model	New	Normal	Yaesu FT-1500M	04/17/2015 10:21 pm
2517	CHIRP	Feature	New	Normal	[uv-5r] Rework Firmware Version Support	04/10/2015 06:52 pm
2523	CHIRP	Bug	New	Normal	simplex channel entry	04/14/2015 08:02 pm
2527	CHIRP	New Model	New	Normal	Vitai VT-UV2	04/17/2015 10:00 am
2533	CHIRP	Bug	New	Normal	No RX no TX on Baofeng UV-5R (N5R-219BFB297)	04/27/2015 11:47 am
2537	CHIRP	Bug	New	Normal	Mixed firmware	04/25/2015 10:11 am
2541	CHIRP	Bug	New	Normal	YAESU FT-2900E -> Failed checksum on read	11/03/2015 02:54 pm
2555	CHIRP	New Model	New	Normal	AnyTone AT-3208	04/30/2015 09:54 am
2563	CHIRP	Feature	New	Normal	[TERMN-8R] Please support adding memories to banks	05/03/2015 09:49 am
2565	CHIRP	New Model	New	Normal	AnyTone AT-398UV	05/05/2015 12:51 am
2571	CHIRP	Feature	New	Normal	Can I use another tone code besides the presets that are given in the list?	05/06/2015 05:56 pm
2575	CHIRP	Bug	New	Normal	Kenwood TH-K2 Channel Numbers	05/08/2015 07:39 am

2589	CHIRP	New Model	New	Normal	TYT TH9000D	05/17/2015 08:30 pm
2597	CHIRP	Bug	New	Normal	Got BF-F8HP working with Chirp but haven't figured out programming "Name"	05/20/2015 05:43 pm
2601	CHIRP	Feature	New	Normal	Live Mode on TM 281	05/21/2015 05:57 am
2605	CHIRP	Bug	New	Normal	IC-T70A does not work with FTDI cable at all	06/09/2015 07:13 am
2611	CHIRP	New Model	New	Normal	Puxing PX-2R PLUS (VHF)	05/23/2015 08:37 pm
2615	CHIRP	Feature	New	Normal	Export to TravelPlus (TPE) and FTB formats	05/26/2015 07:07 am
2643	CHIRP	New Model	New	Normal	[UV-5R] Add Support for Baofeng UV-82HP	06/15/2015 09:34 am
2645	CHIRP	Bug	New	Normal	Baofeng - Chirp daily-20150615 error message - Incorrect "Model	06/15/2015 01:55 pm
2657	CHIRP	Bug	New	Normal	Jetstream JT270M - Image files get corrupted or read corrupted.	06/22/2015 06:04 am
2659	CHIRP	Bug	New	Normal	Error on upload	06/22/2015 11:51 am
2661	CHIRP	Bug	New	Normal	Yaesu FT-90 not reading/writing	09/25/2015 09:51 pm
2671	CHIRP	New Model	New	Normal	Wouxun KG-UV9D	01/29/2016 11:11 am
2673	CHIRP	New Model	New	Normal	Juentai JT-6188	02/09/2016 11:15 am
2681	CHIRP	Bug	New	Normal	Boafeng UV-5RCHP not working	06/28/2015 07:39 am
2683	CHIRP	Feature	New	Normal	Disable broadcast radio option on UV-82 and variants	06/28/2015 10:58 am
2695	CHIRP	Bug	New	Normal	Connecting with Yaesu FT-7900R	07/05/2015 01:33 pm
2703	CHIRP	Feature	New	Normal	Import Kenwood TH-F6A .fx files	07/05/2015 05:40 pm
2705	CHIRP	New Model	New	Normal	Intek model not found	07/06/2015 10:05 am
2711	CHIRP	Bug	New	Normal	Hello i am new and i need alot of help (mac user)	12/30/2015 12:24 pm
2715	CHIRP	New Model	New	Normal	Wouxun KG-920P-A	07/11/2015 06:43 pm
2727	CHIRP	Bug	New	Normal	Baofeng UV82L	07/18/2015 05:27 am
2729	CHIRP	Bug	New	Normal	Baofeng UV-82HP radio fails to respond	07/20/2015 12:39 pm
2735	CHIRP	New Model	New	Normal	Icom IC-V8	07/19/2015 06:00 pm
2739	CHIRP	Bug	New	Normal	YAESU TF1DE Namensfeld field size overrun	07/20/2015 01:05 am
2741	CHIRP	Bug	New	Normal	YAESU TF1DE einheitenchaos	07/20/2015 01:10 am
2747	CHIRP	Bug	New	Normal	UV B6	07/21/2015 07:41 am
2757	CHIRP	Bug	New	Normal	SSL Error downloading from RepeaterBook on Windows 8.1	07/30/2015 01:31 pm
2759	CHIRP	New Model	New	Normal	ICOM IC-F3GS	07/27/2015 10:42 am
2761	CHIRP	New Model	New	Normal	Baofeng/Pofung UV-6R	08/23/2015 01:39 am
2763	CHIRP	Bug	New	Normal	Yaesu 897 block 0	07/27/2015 12:40 pm
2769	CHIRP	New Model	New	Normal	Baisti	07/29/2015 05:25 pm
2773	CHIRP	Feature	New	Normal	Yeasu FT60 upload	08/02/2015 08:08 am
2775	CHIRP	New Model	New	Normal	Tera TR-590	11/13/2015 01:50 am
2779	CHIRP	New Model	New	Normal	New Firmware for Yaesu FTM-400	08/08/2015 09:33 pm
2791	CHIRP	Bug	New	Normal	Chirp won't open on my Mac G5.	08/13/2015 05:01 am

2795	CHIRP	New Model	New	Normal	Icom IC-R6	08/14/2015 11:15 am
2797	CHIRP	Feature	New	Normal	Sainsonic AP510 Firmware 20150616	08/15/2015 06:23 pm
2799	CHIRP	New Model	New	Normal	Baofeng UV-5RM HP	08/16/2015 01:54 pm
2801	CHIRP	New Model	New	Normal	Support for Quansheng TG-UV2?	09/13/2015 10:22 am
2809	CHIRP	Bug	New	Normal	Translate CHIRP into Chinese Language	08/20/2015 12:45 am
2811	CHIRP	Feature	New	Normal	Allow Canadian ZIP codes to download from RR database	08/20/2015 02:51 pm
2827	CHIRP	Bug	New	Normal	Kenwood 281a odd split repeater frequencies	08/23/2015 04:09 pm
2829	CHIRP	New Model	New	Normal	Zastone ZT-9V	08/24/2015 11:47 am
2831	CHIRP	Bug	New	Normal	Baofeng UV-5R5	08/28/2015 03:57 pm
2833	CHIRP	New Model	New	Normal	Pofung TF-317	08/26/2015 09:27 am
2835	CHIRP	New Model	New	Normal	Kenwood TK Commercial series	02/20/2016 01:11 pm
2837	CHIRP	New Model	New	Normal	TYT TH-UV8000D	11/08/2015 11:21 am
2839	CHIRP	Bug	New	Normal	TYT 9000D - 144	09/08/2015 03:54 pm
2863	CHIRP	New Model	New	Normal	Kenwood TS-590	12/30/2015 12:21 pm
2865	CHIRP	Feature	New	Normal	compatability	09/18/2015 05:14 pm
2867	CHIRP	Bug	New	Normal	[FT-2900R] Support settings.	09/22/2015 01:42 pm
2879	CHIRP	Bug	New	Normal	Chirp does not readout radio correctly	09/29/2015 10:02 am
2881	CHIRP	Bug	New	Normal	Screen Refresh Issue	10/01/2015 09:57 am
2887	CHIRP	Bug	New	Normal	Th-uvf8d settings issue	09/30/2015 12:25 pm
2891	CHIRP	Bug	New	Normal	drivers/ft60: add support for "off" duplex mode	10/02/2015 05:30 pm

...