



Prepared This Home Inspection Report Exclusively For:

Ms. Linda Tieaskie 508 Tishomingo Road Waxahachie, Texas 75165

To schedule an inspection call:

Tarrant (817) 265-5452

Dallas (972) 231-1945

Fax: (817) 469-1214

PROPERTY INSPECTION REPORT

Prepared For: Ms. Linda Tieaskie

(Name of Client)

Concerning: 508 Tishomingo Road

(Address of Inspected Property)

Waxahachie, Texas 75165 (City, State, Zip)

September 22, 2004

(Date)

By: Cliff Willis, #4225

(Name and License Number of Inspector)

(Other Identification: Report Number)

<u>38427, 38428</u>

(Name, and License Number of Sponsoring Inspector, if required) (Texinspec Report #)

The inspection of the property listed above must be performed in compliance with the rules of the Texas Real Estate Commission (TREC). The inspection is of conditions which are present and visible at the time of the inspection, and all of the equipment is operated in normal modes. The inspector must indicate which items are in need of repair or are not functioning and will report on all applicable items required by TREC rules.

This report is intended to provide you with information concerning the condition of the property at the time of inspection. Please read the report carefully. If any item is unclear, you should request the inspector to provide clarification.

It is recommended that you obtain as much history as is available concerning this property. This historical information may include copies of any seller's disclosures, previous inspection or engineering reports, reports performed for or by relocation companies, municipal inspection departments, lenders, insurers, and appraisers. You should attempt to determine whether repairs, renovation, remodeling, additions or other such activities have taken place at this property.

Property conditions change with time and use. Since this report is provided for the specific benefit of the client(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

ADDITIONAL INFORMATION PROVIDED BY INSPECTOR

- This report is received in agreement with the buyer's acceptance of the Pre-Inspection Letter (including the box labeled "DISCLAIMER OF
- Paint, Floor Coverings, and other Cosmetic Items are SPECIFICALLY EXCLUDED from this report.
- Buyer has received a notebook of useful information.
- Compensation may be received from outside companies for services/information provided by Texinspec pertaining to this inspection, unless otherwise requested in writing.
- Buyer has received a Home Inspection Information Sheet.
- This report cannot and does not represent the operation or condition of any items after the date and time of this inspection.
- These items should not be considered a complete list of all defects with the house. This list is Limited to those items that are Readily Accessible and the inspector(s) noted at the time of the inspection.
- This inspection does not include a mold test unless specifically requested. If indications of water penetration are known, such as notes of water penetration on this report or seller's disclosure or any visible water stains, recommend a mold inspection/test be considered.
- Some area utility companies may pressure test the gas line prior to turning on the utilities. Pressure testing the line is beyond the scope of this inspection and may find gas line leaks not noted at the time of inspection. Recommend contacting the local gas company regarding start up procedure prior to closing on the property and having the line pressure checked by them if available.

Weather: Clear and Warm Temp.: 869 Inspection Environment: Occupied Report Forwarded To: Buyer: ☑ Agent (Date) Wednesday, September 22, 2004	:: ⊠ Seller: □ Other:	People Present: BUYER - AGENT Access:	Thank?	7a_
	INVO	ICE		Tou
Residential Inspection	\$190.00	☐ Mold Screening	\$0.00	
	\$65.00	Sewer Cam Inspection	\$0.00	
Gas Line Leak Check	\$0.00	Sales Tax	\$4.88	
Swimming Pool	\$0.00	☐ Declined Termite Warranty Extension	\$0.00	
	To	tal	\$ 259.88	
Method of Payment	Credit Card Typ	e: Master Card Card #:		
☐ Check #	Expiration Date:	Name on Card:		
Cash	Security Code:	Billing Address:		

Licensed & Regulated by the Structural Pest Control Board (SPCB) 1106 Clayton Lane, Suite 100LW, Austin TX 78723 1-512-451-7200

Property Inspection Report

Additional pages may be attached to this report. Read them very carefully. This report may not be complete without the attachments. If an item is present in the property but is not inspected, the "NI" column will be checked and an explanation is necessary. Comments may be provided by the inspector whether or not an item is deemed in need of repair.

I = Ir	specte	d N	I = Not	Inspected NP = Not Present R = Not Functioning or In Need of Repair
I	NI	NP	R	Inspection Item
\boxtimes				 STRUCTURAL SYSTEMS A. Foundations (If all crawl space areas are not inspected, provide an explanation.) Comments (An opinion on performance is mandatory.): See the note(s) under the Structural Systems
				section of the Addendum page(s). Foundation type: SLAB ON GRADE There are no significant cracks or movement noted at this time. Method used to inspect the crawlspace: Entered Viewed from opening No Access
				B. Grading & Drainage Comments: ☐ See the note(s) under the Structural section of the Addendum page(s) ☐ Underground drainage systems are not inspected. These should be maintained for proper
				drainage. Sunken living room: checked under carpet in accessible corners. There are no indications of water penetration at this time. Notes: Proper drainage and soil moisture contents should be maintained around the foundation to help minimize future foundation problems. We make no statement concerning site stability.
				☐ I ☐ NI ☒ NP ☐ R Retaining Walls
				C. Roof Covering (If the roof is inaccessible, the method used to inspect): Comments: See the note(s) under the Structural section of the Addendum page(s). Type: Scomposition Wood Shingle Wood Shakes Tile Slate Built-up Roll Other
				 ☒ Roof fasteners are not readily accessible or visible. ☒ Recommend you consult with your insurance underwriter for insurability. ☒ More than one layer of shingles was noted.
				D. Roof Structure & Attic (If the attic is inaccessible, the method used to inspect): Comments: ☐ See the note(s) under the Structural section of the Addendum page(s). ☐ Framing type: Conventional ☐ Parts of the attic are not readily accessible. Method used to inspect the attic: ☐ Entered ☐ Viewed from opening ☐ No Access Insulation: ☐ Depth in inches: 10-12 (Approximate) Type: ☐ Blown Fiberglass ☐ Blown Rockwool ☐ Fiberglass Batts ☐ Rockwool Batts ☐ Cellulose ☐ Other
				E. Walls (Interior & Exterior) Comments: ☐ See the note(s) under the Structural section of the Addendum page(s). Exterior wall covering type: BRICK & COMPOSITION BOARD PANEL
				F. Ceilings & Floors Comments: See the note(s) under the Structural section of the Addendum page(s).
				G. Doors (Interior & Exterior) Comments: See the note(s) under the Structural section of the Addendum page(s). NOTE: INTERIOR DOOR LOCKS NOT TESTED.
				H. Windows Comments: See the note(s) under the Structural section of the Addendum page(s). Notes: Signs of lost seals in the thermal pane windows may appear and disappear as temperature and humidity changes. Some windows with lost seals may not been evident at the time of the inspection. Windows only checked for obvious fogging. If some lost seals were noted, recommend all windows be checked by a specialist for further lost seals. Storm windows only checked for damaged or missing glass. Recommend local municipalities be consulted for further information concerning the use and safety requirements suggested for the use of burglar bars.

er
ATION.
)
,
om
F THE
HEAT

I	NI	NP	R	Inspection Item
\boxtimes			\boxtimes	B. Cooling Equipment
				Comments: \boxtimes See the note(s) under the Heating-AC section of the Addendum page(s).
				Type: CENTRAL HEATPUMP
				Energy Source:
				Number of units: <u>ONE</u> Location: <u>HEATPUMP</u> Temperature Differential: <u>15</u> °F
				•
				Location: °F Location: °F Temperature Differential: °F
				Location: °F Location: Temperature Differential: °F Temperature Differential: °F
				Location: °F Only able to do a limited check of the A/C systems due to low outside temperature. The
				compressor(s) and control(s) are operable. Unable to check the condensate drain(s) due to low outside temperature. No secondary drain pan was noted below the unit. Notes: Window A/C units are not inspected. Unit(s) are not inspected for cleanliness and/or for rust. Recommend the filter be cleaned or changed on a regular basis. Units are not inspected for proper size or efficiency. Units are not disassembled or opened for inspection.
\boxtimes	П	П	П	C. Ducts and Vents
				Comments: \square See the note(s) under the Heating-AC section of the Addendum page(s).
				Heating – A/C filter size(s): \square Fiberglass: \square 12x24x1 \square 14x25x1 \square 16x25x1 \square 16x20x1
				☐ 20x20x1 ☐ 20x25x1 ☐ 25x25x1 ☐ Other ☐ Washable ☐ Electrostatic ☐ Fiberglass ☐ Media ☐ Hammock style fiberglass
\boxtimes				IV. PLUMBING SYSTEMS A. Water Supply System & Fixtures
	ш	Ш	ш	Comments: See the note(s) under the <i>Plumbing</i> section of the Addendum page(s).
				Type of Supply Lines: COPPER Location of Main Valve: FRONT YARD
				 ☐ The washer and dryer are connected, unable to check the laundry utility lines. ☐ The water meter was checked for any movement.
				NOTE: UNABLE TO TEST WASHER UTILITY DRAIN AT FULL CAPACITY.
\boxtimes				B. Drains, Wastes, Vents
				Comments:
				Type of Drain Pipes: PLASTIC Type of Vent Pipes: PLASTIC
				C. Water Heating Equipment (Report as in need of repair those conditions specifically listed as recognized hazards by TREC rules.)
				Energy Source: Gas Electric Other If unit uses natural gas: Type of connector line:
				Comments: \boxtimes See the note(s) under the <i>Plumbing</i> section of the Addendum page(s).
				Number of Water Heaters: ONE Location: GARAGE Size: 50 gallons
				Location: Size: gallons
П		\bowtie		D. Hydro-Therapy Equipment
_		_	_	Comments: ☐ See the note(s) under the <i>Plumbing</i> section of the Addendum page(s). ☐ Cover is absent or inaccessible for area under tub.
				V. APPLIANCES
\boxtimes				A. Dishwasher
				Comments: See the note(s) under the Appliances section of the Addendum page(s). NOTE: LOWER PANEL NOT REMOVED FOR INSPECTION.
				B. Food Waste Disposer *Comments: See the note(s) under the *Appliances section of the Addendum page(s).
\boxtimes				C. Range Hood
				Comments: See the note(s) under the Appliances section of the Addendum page(s).
				☐ Recirculating (vent pipe not required) ☐ Vented ☐ Downdraft NOTE: RANGE VENT NOT CHECKED FOR CLEANLINESS.

I	NI	NP	R	Inspection Item
\boxtimes				D. Ranges/Ovens/Cooktops
				Comments: See the note(s) under the Appliances section of the Addendum page(s).
				Oven: Electric Elements Gas Burners
				Range: Electric Elements Gas Burner Type of Pilot: Standing Automatic Igniter
				If unit uses natural gas: Type of connector line:
				Oven thermostat: Temperature 360°F/°F
				Notes: Oven Checked at 350°F.
				IF PRESENT, DELAY TIMER AND SELF-CLEAN MODE ARE NOT TESTED.
				☐ Gas line not readily accessible. ☐ Anti-tip device not required.
				Anti-tip device not required. Anti-tip device not visible, unable to determine if present.
\boxtimes	П			E. Microwave Cooking Equipment
	ш	ш	ш	Comments: See the note(s) under the Appliances section of the Addendum page(s).
				NOTE: MICROWAVE OVEN NOT INSPECTED FOR RADIATION LEAKS.
		\boxtimes		F. Trash Compactor
				Comments: See the note(s) under the Appliances section of the Addendum page(s).
\boxtimes				G. Bathroom Exhaust Fans and/or Heaters
				Comments: See the note(s) under the Appliances section of the Addendum page(s).
				☐ Heaters not present. ☐ Exhaust fans not present.
		\boxtimes		H. Whole House Vacuum Systems
				Comments: See the note(s) under the Appliances section of the Addendum page(s).
	_		_	NOTE: ONLY VISIBLE AND ACCESSIBLE OUTLETS ARE TESTED, ACCESSORIES ARE NOT TESTED OR NOTED.
\boxtimes			Ш	I. Garage Door Operators Comments: See the note(s) under the Appliances section of the Addendum page(s).
\boxtimes	Ш		Ш	J. Door Bell & Chimes
_	_	_		Comments: See the note(s) under the Appliances section of the Addendum page(s).
\boxtimes			Ш	K. Dryer Vent
				Comments: See the note(s) under the Appliances section of the Addendum page(s). Note: Dryer vent not checked for cleanliness. If the clothes dryer vent runs into the attic,
				LINT MAY COLLECT IN THE VENT PIPE OVER TIME CAUSING THE DRYER TO OVER-HEAT OR NOT
\Box				FUNCTION PROPERLY.
Ш			Ш	L. Other Built-In Appliances Comments: See the note(s) under the Appliances section of the Addendum page(s).
				☐ I ☐ NP ☐ R Smoke Detectors ☐ If inspected, tested with test button only.
				Part of a central security system.
				Some or all units are inaccessible.
				☐ I ☐ NI ☒ NP ☐ R Power Attic Vents ☐ Not readily accessible.
				□ I ⋈ NI ⋈ NP □ R Other
				VI. OPTIONAL SYSTEMS
		\boxtimes		A. Lawn Sprinklers Control Panel Location:
				Comments: See the note(s) under the Optional Systems section of the Addendum page(s).
				Coverage: Front Yard Back Yard Side Yard(s) Other Zones used: Valve Box Location:
				NOTE: SPRINKLER CONTROLS ARE OPERATED IN MANUAL MODE ONLY.
		\boxtimes		B. Gas Lines
_	_		_	Comments: See the note(s) under the Optional Systems section of the Addendum page(s).
				Type of Supply Lines: Location of Main Valve:
				NOTE: PROPANE SYSTEMS ARE NOT INSPECTED. Motor Check: With all gas appliances and associated pilot lights turned off in the house, there
				Meter Check: With all gas appliances and associated pilot lights turned off in the house, there is no measurable gas flow through the gas meter and the pilot lights were relit.

I	NI	NP	R	Inspection Item
		\boxtimes		C. Swimming Pools & Equipment
				Comments: See the note(s) under the Optional Systems section of the Addendum page(s). Type: In ground Above ground Other Shell Type: Gunite Fiberglass Vinyl Other There is no significant movement in the shell at this time. The main drain is plumbed into the skimmers, unable to fully evaluate the main drain. Type of filter: Sand Cartridge D. E. Other The following items were noted as being present: Slide Ladder Diving Board Pool Sweep Other/Heater Notes: Not checked for pool shell leakage or in backwash mode. The pool coating is considered cosmetic and not part of this inpsection. All controls are operated in the Manual mode only. Ancillary equipment such as computer controls, chlorinators or other chemical
		\boxtimes		DISPENSORS, OR WATER IONIZATION DEVICES OR CONDITIONERS ARE NOT INSPECTED. D. Outbuildings Comments: See the note(s) under the Optional Systems section of the Addendum page(s).
				E. Outdoor Cooking Equipment Comments: See the note(s) under the Optional Systems section of the Addendum page(s). Energy source: Natural Gas Propane Electric Other
				F. Sub-Termite (WDI) Inspection Comments: For more complete information refer to the Texas Official Wood Destroying Insect Report.
				This company has a contract or warranty in effect for control of the following wood destroying insects: Yes No List Insects: 90 Day Sub-Termite with \$200.00 Deductible.
				Conducive to wood destroying insect infestation: Yes \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
				Visible evidence in or on the structure: Subterranean Termites Yes No
				Explanation of signs of previous treatment identified: None noted at this time. Visible evidence of: N/A has been observed in the following areas: N/A Corrective treatment recommended for active infestation or evidence of previous infestation with no prior treatment as Yes No Preventive treatment and/or correction of conducive conditions is recommended as follows: Yes No Explain: n/a

Addendum Page

ITEMS IN NEED OF REPAIR AND ITEMS QUESTIONABLE AS TO PERFORMING FUNCTION AS INTENDED AS REQUIRED BY THE TEXAS REAL ESTATE COMMISSION (TREC). REPAIR IS NOT MANDATORY.

I. STRUCTURAL SYSTEMS

- 1. The foundation has shifted in one or two areas evident mainly by a hairline crack in the brickwork on the bedroom side of the house and slight separation between one window frame and brickwork. Also, there is a larger crack in the brickwork on the garage side wall. Also, there are cracks in garage drywall. Also, there are repaired cracks in the brickwork mortar under the utility room window and cracks and repaired cracks in the drywall over the utility room door. Also, the utility room door does not latch properly. Recommend a structural engineer and/or drainage specialist be consulted for further evaluation.
- 2. There is at least one missing ridge shingle from the roof over the garage area with exposed underlying materials. Recommend a roofer be consulted for further evaluation/repairs and check for other repairs that may be needed at that time.
- 3. There are at least two missing window screens.
- 4. The garage / living area door and the patio door do not fit squarely in the frames. Light is visible between the doors and frames when the doors are closed.
- 5. There is a hole in the garage ceiling drywall. This is noted as a fire safety concern.

II. <u>ELECTRICAL SYSTEMS</u>

1. There are two knockouts missing from the sub-panel in the garage.

III. HEATING, VENTILATION AND AIR CONDITIONING SYSTEMS

- 1. There is a section of exposed (not insulated) AC suction line near the outside unit.
- 2. There is a section of exposed (not insulated) AC suction line in the hall closet. Water condenses on this section and drips onto the closet flooring.

IV. PLUMBING SYSTEMS

- 1. The water heater is less than 18 inches from the floor.
- 2. This house is connected to a septic sewer system. We do not inspect these systems. Recommend consulting with the County Health Department for information regarding inspection, certification and maintenance of the septic systems.

V. APPLIANCES

- 1. There is no anti-tip device for the oven/range.
- 2. Smoke detectors were not noted in all recommended areas. Refer to the handbook provided at the time of inspection for further information.

Photo Page




Front view of house



Hairline crack, bedroom side




Ridge shingle missing, garage area



Crack in brickwork, garage side wall



Separation of bedroom window frame, brickwork




Insulation missing, AC suction line

Photo Page



Exposed AC suction line, hall closet



Exposed AC suction line, outside unit



Hole in garage ceiling drywall



View ductwork, insulation, attic structure