

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENEOUS AREA Black MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
3064	600SF	G	
3068	600SF	G	
3069A	800SF	G	
3073	500SF	G	
3093	300SF	G	
3096	300SF	G	
3098	300SF	G	
3099	600SF	G	
3075	300SF	G	
3076	300SF	G	
3074	300SF	G	
3079	300SF	G	
3071	300SF	G	
3082	600SF	G	
3080	300SF	G	
3083	300SF	G	
3085	300SF	G	
3087	200SF	G	
3002	500SF	G	
3087B	800SF	G	
3087C	300SF	G	
3091	300SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MastieBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
3001 B	300 SF	G	
3005	200 SF	G	
3007	300 SF	G	
3RD Floor Corridor O	2000 SF	G	
3009	300 SF	G	
3013	300 SF	G	
3015 B	300 SF	G	
3015 A	300 SF	G	
3004	800 SF	G	
3014	1000 SF	G	
3021	600 SF	G	
3106	300 SF	G	
3108	300 SF	G	
3122	2000 SF	G	
3119	1000 SF	G	
3100	400 SF	G	
3114	300 SF	G	
3116	200 SF	G	
3115	300 SF	G	
3113	300 SF	G	
3109	300 SF	G	
3RD Floor Corridor 8	1000 SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
2815	2000 SF	G	
2 ND Floor Upperlevel Auditorium	300 SF	G	
2 ND Floor Auditorium Control Room	300 SF	G	
1069	800 SF	G	
1061	1500 SF	G	
1066	1200 SF	G	
1037	1200 SF	G	
2036	1200 SF	G	
1029	1000 SF	G	
1320	1000 SF	G	
1314	900 SF	G	
317	400 SF	G	
1320	900 SF	G	
325	1200 SF	G	
893	1500 SF	G	
1705	300 SF	G	
1099C	150 SF	G	
1099B	1400 SF	G	
3 RD Floor Corridor 1	1600 SF	G	
3001A	400 SF	G	
3003	300 SF	G	
3011	600 SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDOMOGENOUS AREA Black MasticDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
124	2500 SF	G	
1114	100 SF	G	
1109	1800 SF	G	
1108	800 SF	G	
1104	1000 SF	G	
1617	600 SF	G	
1731	300 SF	G	
099D	1400 SF	G	
093	600 SF	G	
1087	1500 SF	G	
607	1600 SF	G	
001A	800 SF	G	
003	900 SF	G	
006	500 SF	G	
2012	1200 SF	G	
015A	2600 SF	G	
201	300 SF	G	
2202	1200 SF	G	
2213	2000 SF	G	
2225	2000 SF	G	
2224	2000 SF	G	
2000 2814B	2000 SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MasticDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
1854	2000 SF	G	
1859	600 SF	G	
1863	1500 SF	G	
874	600 SF	G	
528	3000 SF	G	
521	1200 SF	G	
1067	1000 SF	G	
1st Floor Auditorium	5000 SF	G	
003	1600 SF	G	
1008	900 SF	G	
1009	900 SF	G	
1015	2000 SF	G	
1206	800 SF	G	
1211	1200 SF	G	
117	4000 SF	G	
222	800 SF	G	
223 1835			
815	1000 SF	G	
1812	800 SF	G	
1806	900 SF	G	
1805	1000 SF	G	
1800A	1000 SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
SB702	2500 SF	G	
1B099	600 SF	G	
1B093	300 SF	G	
Room Adjacent to Computer Room	1000 SF	G	
3B703	4000 SF	G	
3B894	1000 SF	G	
3B 895	600 SF	G	
pen Area Adjacent to SB894	1000 SF	G	
3B608	300 SF	G	
3B607	1200 SF	G	
3B602	400 SF	G	
Subbasement Corridor	1600 SF	G	
D41	500 SF	G	
1036	1500 SF	G	
10306	50 SF	G	
314	1200 SF	G	
317	3000 SF	G	
320	1600 SF	G	
1833	600 SF	G	
1842	1200 SF	G	
839	1600 SF	G	
1851	500 SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MasticDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
B-918	400SF	G	
B-904	800SF	G	
B 826	1500SF	G	
3841B	300SF	G	
3322	1800SF	G	
3315	1000SF	G	
3307 Men's Room	600SF	G	
3031	1125SF	G	
3035	220SF	G	
aquarium Viewing Area	400SF	G	
aquarium Entrance + Office Area	1500SF	G	
B511A	200SF	G	
B511	500SF	G	
Basement Stairway #9	50SF	G	
5896	400SF	G	
5026	600SF	G	
3618	800SF	G	
3099	2500SF	G	
Basement Mezzanine Records Storage #2	1500SF	G	
3M029A	2000SF	G	
hallways in Basement Mezzanine	2500SF	G	
Basement Mezzanine Records Storage	1500SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
Basement - Printing Break Room 1	250 SF	G	
Basement - Printing Break Room 2	300 SF	G	
3-911	50 LF	G	
3-315	1000 SF	G	
307 (Men's Room)	60 SF	G	
3031	625 SF	G	
Basement Printing Back Room	3500 SF	G	
301B	300 SF	G	
3001	600 SF	G	
3003	1600 SF	G	
3012	2500 SF	G	
3014	1000 SF	G	
3212	400 SF	G	
3211	1000 SF	G	
3214	400 SF	G	
3223	1500 SF	G	
Basement Corridor 9	800 SF	G	
3B00	400 SF	G	
3805	250 SF	G	
Room adjacent to B805	150 SF	G	
B815	50 SF	G	
3911	600 SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUED

OMOGENOUS AREA Black MasticDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
4410	800 SF	G	
4416	1000 SF	G	
4424	1000 SF	G	
4525	2000 SF	G	
4519	2000 SF	G	
4522	1000 SF	G	
4510	1000 SF	G	
4612	800 SF	G	
4622	800 SF	G	
4628	800 SF	G	
463	800 SF	G	
4625	750 SF	G	
4629	700 SF	G	
4695	1200 SF	G	
4707	4000 SF	G	
4812	800 SF	G	
4828	1000 SF	G	
4822	1200 SF	G	
4828	4000 SF	G	
Basement Printing Back Room	3500 SF	S G	exposed where floor tile was damaged
3220A	1405 825 SF	G	
3121 Locker Room	225 SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUED

HOMOGENOUS AREA Black MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
4725	3000SF	G	
772	2000SF	G	
1897	2000SF	G	
1896	2000SF	G	
1893	2000SF	G	
1890	2000SF	G	
1883	1000SF	G	
1884	1000 SF	G	
1878	2000SF	G	
1881	2000SF	G	
1861	3500SF	G	
1858	3500SF	G	
1843	3500SF	G	
1842	3500SF	G	
876	2000SF	G	
1827	2000SF	G	
1524	1500 SF	G	
320	1500 SF	G	
1312	1500SF	G	
321	2000SF	G	
1311 Mechanical Room	6LF	G	
4411	800SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
1410	20LF	G	
1 st Floor Southeast Corridor	2400 SF	G	
7114	2000 SF	G	
7106	800 SF	G	
7 th Floor Corridor 1	2000 SF	G	
7215	400 SF	G	
7221	1500 SF	G	
7227	400 SF	G	
7231	800 SF	G	
7420	1500 SF	G	
7417	2000 SF	G	
7414 7 th Floor Corridor 4	250 SF	G	
7 th Floor Corridor 4	500 SF	G	
213	2000 SF	G	
2225	2000 SF	G	
2224	2000 SF	G	
2814B	2000 SF	G	
2815	2000 SF	G	
2810	2000 SF	G	
2807	2000 SF	G	
2806	2000 SF	G	
428	1600 SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black PlasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
2116	3000SF	G	
2104	400SF	G	
211	1500SF	G	
419	1500SF	G	
830B	3000SF	G	
841	3000SF	G	
854	2000SF	G	
865	3000SF	G	
ND Floor Central Mail Room	9000SF	G	
1051	2000SF	G	
1044	2000SF	G	
1066	2000SF	G	
1076	1000SF	G	
1077	1000SF	G	
1082	1000SF	G	
1083	1000SF	G	
1096	3000SF	G	
1091	3000SF	G	
1099A	1000SF	G	
1701	100SF	G	
1713	3000SF	G	
1708	3000SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
6013	1500 SF	G	
6012	1500 SF	G	
6006	1200 SF	G	
6204	1000 SF	G	
6022	1500 SF	G	
1 TH Floor Southeast Corridor	2000 SF	G	
6217	3000 SF	G	
6228	2000 SF	G	
6026	1000 SF	G	
6027	1000 SF	G	
6029 B	400 SF	G	
6043	2000 SF	G	
6037	500 SF	G	
6057	800 SF	G	
6054	2000 SF	G	
6065	800 SF	G	
6073	250 SF	G	
6078	1200 SF	G	
6083	400 SF	G	
6086	800 SF	G	
6092	1000 SF	G	
400 6097A	400 SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
099A 6098	1200 SF	G	
099C	1000 SF	G	
1701	400 SF	G	
1707	4000 SF	G	
1716	400 SF	G	
1720	800 SF	G	
0733A	2000 SF	G	
0895	1200 SF	G	
0889	1000 SF	G	
0629	400 SF	G	
0625	1200 SF	G	
0614	1000 SF	G	
0613	400 SF	G	
0612	500 SF	G	
0611	400 SF	G	
0608	600 SF	G	
0 TH Floor Snack Bar #57	900 SF	G	
0872	800 SF	G	
0869	800 SF	G	
0863	1200 SF	G	
0857	800 SF	G	
0840	200 SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
0839	2000 SF	G	
0827	1000 SF	G	
0828	1000 SF	G	
0822	1200 SF	G	
0823	400 SF	G	
0819	800 SF	G	
0814A	1400 SF	G	
0812	400 SF	G	
0809	2000 SF	G	
2 TH Floor Northwest Corridor	1200 SF	G	
2 TH Floor Corridor 1	1600 SF	G	
0128 (Storage Area)	1600 SF	G	
0128	1600 SF	G	
0111	800 SF	G	
0107	1200 SF	G	
0316	1400 SF	G	
0521	2000 SF	G	
0324	1200 SF	G	
1 TH Floor Corridor 4	20 SF	G	Across Stair #9
0422	1200 SF	G	
0508	800 SF	G	
0521	2000 SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MasticDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
1520	2000 SF	G	
2524	400 SF	G	
TH Floor Corridor Offices	4400 SF	G	
1021B	50 SF	G	
1029B	350 SF	G	
7071	600 SF	G	
7077	1000 SF	G	
7081	300 SF	G	
7087	1200 SF	G	
1089	300 SF	G	
7095	200 SF	G	
7097	450 SF	G	
7099C	1200 SF	G	
7703	150 SF	G	
7705	300 SF	G	
7713	1200 SF	G	
7717	1600 SF	G	
7727	800 SF	G	
7723	500 SF	G	
7614	900 SF	G	
7620	1000 SF	G	
7628	600 SF	G	

HSA 005

Page 29 of 38

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Black MasticDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
1898	1200 SF	G	
1892	1200 SF	G	
1886B	1000 SF	G	
1886	400 SF	G	
#8 1884	400 SF	G	
1882	400 SF	G	
1876	1200 SF	G	
1870	600 SF	G	
1869	600 SF	G	
1868	600 SF	G	
1862	400 SF	G	
1860	600 SF	G	
1865	300 SF	G	
1863	300 SF	G	
1861	500 SF	G	
1856	1000 SF	G	
1855	1000 SF	G	
1850	600 SF	G	
1849	400 SF	G	
1846	600 SF	G	
1840	600 SF	G	
1838	400 SF	G	

10MOGENOUS AREA Black Mastic

DING: Commerce Building

[illegible]

HSA-006

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 1-14-03
 ADDRESS: 14th & Constitution Ave.
 GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.) _____

Location in Bldg: Attic - Southeast Corridor
 (Include Functional Space) muddled joint

HOMOGENEOUS AREA: Pipe Elbow Debris Packing 1301-026

Type of Material	Damage <u>SEE ATTACHED</u>	Accessibility
☐ Fireproofing	☒ Significant	☐ High
☐ Acoustical Plaster	☒ Minor	☐ Medium
☐ Acoustical Tile	☒ None	☒ Low
☐ Thermal Systems Insulation		
☐ Vinyl Floor Tile		Air Plenum <u>N</u>
☒ Other: _____		(Y or N)

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☐ High	☐ High	☐ High
☐ Medium	☐ Medium	☒ Medium	☒ Moderate
☒ Low	☒ Low	☐ Low	☐ Low

Comments: _____

AHERA Classification (see instructions): 1

Sample Number	Sample location	Result
(Include percent and type of asbestos in result, e.g. 50% Chrysotile).		
<u>011403-010</u>	<u>Attic Southeast Cor.</u>	<u>20% Chrysotile</u>
<u>-013</u>	<u>Attic wing 7 near NE corner</u>	<u>8% Chrysotile</u>
<u>011403-17</u>	<u>Attic</u>	<u>20 %</u>
<u>-18</u>	<u>↓</u>	<u>25 %</u>
<u>-19</u>	<u>↓</u>	<u>20 %</u>

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Mudged Elbow Insulation on Fiberglass pipe insulationBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
Basement Printing Room	115	G	
Basement Printing Rack Room	20	SD	
220	20	SD	
3220A	30	G	
Mechanical Room #2	15	G	
Basement Corridor 9			
Basement Loading Dock #2	25	G	
5618	1	G	
1-43	20	G	
Hallways in Basement Mezzanine	10	G	
Attic SE Quadrant	43	SD	
Attic East Central	88	MD	
Attic East Central Mezzanine	23	MD	
Attic Northeast Corridor	9	G	
Attic Corridor 7	23	MD	
Attic Northwest Corridor	30	MD	
Attic West Central	40	G	
Attic South West	30	G	
Attic Corridor 2	20	MD	
Attic Corridor 3	50	G	
Attic Corridor 1	20	G	
Attic Corridor 4	5	G	
Attic Corridor 5	13	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Mudded Elbow Insulation on fiberglass pipe insulationBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
Attic - Stair 8	88	MD	
Attic - NE Corridor	8	MD	
Attic - Stair 13 / Wing 6	10	MD	
3208 Mechanical Room	10	G	
3724	13	G	
1123	18	G	
7855	2	G	
2210 Mechanical Room	14	G	
2 ND Floor Corridor / Mechanical Room 13		G	
2849 Mechanical Room	50	G	
4311 Mechanical Room	8	G	
5 TH Floor Central East Corridor	2	G	
5526 Mechanical Room	10	G	
6240 Mechanical Room	5	G	
6724	7	G	
6607	8	G	
6 TH Floor Corridor 1	7	G	
6 TH Floor Corridor 4	5	G	
6425 Mechanical Room	15	G	
6432	1	G	
6 TH Floor Corridor 5	3	G	Outside of 6508
Basement Mechanical Room	100	^{BS} MD	In main room + 2 offshoots
Wing 3 Corridor 0	100	G	

Page 4 of 4

ISOGENOUS AREA Muddled Elbow Insulation on Fiberglass pipe insulation

[illegible]

HSA 007

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 1-14-03
 ADDRESS: 14th & Constitution Ave.
 GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.) _____

Location In Bldg: Attic-East Central Corridor
 (Include Functional Space)

HOMOGENEOUS AREA: Concrete Mastic HSA-007

Type of Material	Damage	Accessibility
☐ Fireproofing	☐ Significant	☐ High
☐ Acoustical Plaster	☐ Minor	☐ Medium
☐ Acoustical Tile	☒ None	☒ Low
☐ Thermal Systems Insulation		
☐ Vinyl Floor Tile		Air Plenum: <u>N</u>
☒ Other: _____		(Y or N)

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☐ High	☐ High	☐ High
☐ Medium	☐ Medium	☐ Medium	☐ Moderate
☒ Low	☒ Low	☒ Low	☒ Low

Comments: _____

AHERA Classification (see instructions): _____

Sample Number	Sample location	Result
(Include percent and type of asbestos in result, e.g. 50% Chrysotile).		
061403-011	Attic-East Central Cor.	None Detected
070	6th Floor: 6840	None Detected
074	4th floor: Rm 4221	None Detected

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

HSA-008

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 1-14-03
 ADDRESS: 14th & Constitution Ave.
 GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.): _____

Location In Bldg: Attic NE Corridor
 (include Functional Space)

HOMOGENEOUS AREA: Beige mastic on Fiberglass Duct Insulation

Type of Material	Damage	Accessibility
☐ Fireproofing	☐ Significant	☐ High
☐ Acoustical Plaster	☐ Minor	☐ Medium
☐ Acoustical Tile	☒ None	☒ Low
☐ Thermal Systems Insulation		
☐ Vinyl Floor Tile		Air Plenum <u>N</u>
☒ Other: _____		(Y or N)

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☐ High	☐ High	☐ High
☐ Medium	☐ Medium	☐ Medium	☐ Moderate
☒ Low	☒ Low	☒ Low	☒ Low

Comments: _____

AHERA Classification (see instructions): _____

Sample Number	Sample location	Result
(Include percent and type of asbestos in result, e.g. 50% Chrysotile).		

<u>CD11403-012</u>	<u>Attic - NE Corridor</u>	<u>None Detected</u>

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

HSA 009

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 1-14-03
 ADDRESS: 14th & Constitution Ave.
 GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.) _____

Location In Bldg: Attic Wing 1 - Near SW Corner
 (Include Functional Space)

HOMOGENEOUS AREA: Black Mastic on Metal Duct HSA-009

Type of Material	Damage	Accessibility
☐ Fireproofing	☐ Significant	☐ High
☐ Acoustical Plaster	☐ Minor	☐ Medium
☐ Acoustical Tile	☒ None	☒ Low
☐ Thermal Systems Insulation		Air Plenum <u>N</u>
☐ Vinyl Floor Tile		(Y or N)
☒ Other: _____		

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☐ High	☐ High	☐ High
☐ Medium	☐ Medium	☐ Medium	☒ Moderate
☒ Low	☒ Low	☒ Low	☐ Low

Comments: _____

AHERA Classification (see instructions): Non-friable

Sample Number	Sample location	Result
<u>C011403-014</u>	<u>Attic - Wing 1</u>	<u>100% Chrysotile</u>

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

Page 2 of 2

HOMOGENOUS AREA Black Mastic on Metal Duct

[illegible]

HSA 010

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 1-14-03
 ADDRESS: 14th & Constitution Ave.
 GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.) _____

Location in Bldg: Attic - East Central Corridor
 (include Functional Space) Fiberglass Insulation

HOMOGENEOUS AREA: Skim Coat on Mudded Elbow on HSA-010

Type of Material	Damage	Accessibility
☐ Fireproofing	☐ Significant	☐ High
☐ Acoustical Plaster	☐ Minor	☐ Medium
☐ Acoustical Tile	☒ None	☒ Low
☐ Thermal Systems Insulation		
☐ Vinyl Floor Tile		Air Plenum ☒ (Y or N)
☒ Other: _____		

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☐ High	☐ High	☐ High
☐ Medium	☐ Medium	☐ Medium	☒ Moderate
☒ Low	☒ Low	☒ Low	☐ Low

Comments: _____

AHERA Classification (see instructions): 7

Sample Number	Sample location	Result
(Include percent and type of asbestos in result, e.g. 50% Chrysotile).		
C011403-015	Attic - East Central Cor.	10% Chrysotile
C011403-016	↓	6% Chrysotile
C011403-020	↓	8% Chrysotile

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

~~10/10/1997~~
HSA-011

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: _____
ADDRESS: 14th & Constitution Ave.
GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.) _____

Location in Bldg: _____
(include Functional Space)

HOMOGENEOUS AREA: MAG Boiler Insulation

Type of Material	Damage	Accessibility
☐ Fireproofing	☐ Significant	☐ High
☐ Acoustical Plaster	☒ Minor	☐ Medium
☐ Acoustical Tile	☒ None	☒ Low
☒ Thermal Systems Insulation		Air Plenum <u>N</u>
☐ Vinyl Floor Tile		(Y or N)
☐ Other: _____		

Friability	Traffic	Vibration	Potential for Air Erosion
☒ High	☐ High	☐ High	☒ High
☐ Medium	☐ Medium	☐ Medium	☐ Moderate
☐ Low	☒ Low	☒ Low	☒ Low

Comments: _____

AHERA Classification (see instructions): I

Sample Number	Sample location	Result
	(Include percent and type of asbestos in result, e.g. 50% Chrysotile).	
	<u>Basement Mech Rm</u>	<u>Assumed</u>

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

ISOTROPIC AREA Magnesia Boiler Insulation

DING: Commerce Building

[illegible]

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 1-14-02
 ADDRESS: 14th & Constitution Ave.
 GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.): _____

Location in Bldg: Attic - Wing 5 Near Stairs to MEZZ
 (include Functional Space)

HOMOGENEOUS AREA: Gypsum Wall Board MSA-002

Type of Material	Damage	Accessibility
☐ Fireproofing	☐ Significant	☐ High
☐ Acoustical Plaster	☐ Minor	☒ Medium
☐ Acoustical Tile	☒ None	☐ Low
☐ Thermal Systems Insulation		
☐ Vinyl Floor Tile		Air Plenum <u>N</u>
☒ Other: _____		(Y or N)

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☐ High	☐ High	☐ High
☐ Medium	☒ Medium	☐ Medium	☐ Moderate
☒ Low	☐ Low	☒ Low	☒ Low

Comments: _____

AHERA Classification (see instructions): _____

Sample Number	Sample location	Result
(Include percent and type of asbestos in result, e.g. 50% Chrysotile).		
<u>001403-021</u>	<u>Attic - Wing 5</u>	<u>None Detected</u>
<u>-0916</u>	<u>4098B</u>	<u>None Detected</u>
<u>-022</u>	<u>Attic - Wing 5</u>	<u>None Detected</u>

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 1-14-02
 ADDRESS: 14th & Constitution Ave.
 GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.): _____

Location In Bldg: Attic - Wing 5
 (Include Functional Space)

HOMOGENEOUS AREA: Gypsum Wall Board Joint Compound 15A-013

Type of Material	Damage	Accessibility
☐ Fireproofing	☐ Significant	☐ High
☐ Acoustical Plaster	☐ Minor	☒ Medium
☐ Acoustical Tile	☒ None	☐ Low
☐ Thermal Systems Insulation		
☐ Vinyl Floor Tile		Air Plenum <u>N</u>
☒ Other: _____		(Y or N)

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☐ High	☐ High	☐ High
☐ Medium	☒ Medium	☐ Medium	☐ Moderate
☒ Low	☐ Low	☒ Low	☒ Low

Comments: _____

AHERA Classification (see instructions): _____

Sample Number	Sample location	Result
(Include percent and type of asbestos in result, e.g. 50% Chrysotile).		
<u>011403-022</u>	<u>Attic - Wing 5</u>	<u>None Detected</u>

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 1-14-03
 ADDRESS: 14th & Constitution Ave.
 GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.): _____

Location In Bldg: Attic East Central Corridor
 (include Functional Space)

HOMOGENEOUS AREA: 9"x9" floor tile w/ Brown & White

Type of Material	Damage	Spots
☐ Fireproofing	☐ Significant	Accessibility
☐ Acoustical Plaster	☐ Minor	☒ High
☐ Acoustical Tile	☒ None	☐ Medium
☐ Thermal Systems Insulation		☐ Low
☐ Vinyl Floor Tile		Air Plenum <u>N</u>
☒ Other _____		(Y or N)

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☒ High	☐ High	☐ High
☐ Medium	☐ Medium	☐ Medium	☐ Moderate
☒ Low	☐ Low	☒ Low	☒ Low

Comments: _____

AHERA Classification (see instructions): Non-friable

Sample Number	Sample location	Result
(Include percent and type of asbestos in result, e.g. 50% Chrysotile).		

<u>CO11403-023</u>	<u>Attic-East Central Cor.</u>	<u>40% Chrysotile</u>

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

Page 2 of 2

HOMOGENOUS AREA 9" x 9" Floor Tile w/ Brown & White Spots

[illegible]

HSA-015

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 2-24-03
ADDRESS: 14th & Constitution Ave.
GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.) _____
Location In Bldg: 5th Floor Stair #9
(include Functional Space)

HOMOGENEOUS AREA: 12x12 FT Black w/white streaks

Type of Material	Damage	Accessibility
☐ Fireproofing	☐ Significant	☒ High
☐ Acoustical Plaster	☐ Minor	☐ Medium
☐ Acoustical Tile	☒ None	☐ Low
☐ Thermal Systems Insulation		Air Plenum <u>N</u>
☐ Vinyl Floor Tile		(Y or N)
☐ Other: _____		

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☒ High	☐ High	☐ High
☐ Medium	☐ Medium	☐ Medium	☐ Moderate
☒ Low	☐ Low	☒ Low	☒ Low

Comments: _____

AHERA Classification (see instructions): _____

Sample Number	Sample location	Result
(include percent and type of asbestos in result, e.g. 50% Chrysotile).		

<u>Com-074</u>	<u>5th Floor Stair #9</u>	<u>None detected</u>

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

HSA-016

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 1-14-03
 ADDRESS: 14th & Constitution Ave.
 GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.): _____

Location In Bldg: Attic - East Central Corridor Near Stairs to Mezz
 (include Functional Space)

HOMOGENEOUS AREA: Wire Insulation HSA-016 [REDACTED]

Type of Material	Damage	Accessibility
☐ Fireproofing	☐ Significant	☐ High
☐ Acoustical Plaster	☐ Minor	☐ Medium
☐ Acoustical Tile	☒ None	☒ Low
☐ Thermal Systems Insulation		
☐ Vinyl Floor Tile		Air Plenum _____
☒ Other: _____		(Y or N)

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☐ High	☐ High	☐ High
☐ Medium	☐ Medium	☒ Medium	☐ Moderate
☒ Low	☒ Low	☐ Low	☒ Low

Comments: _____

AHERA Classification (see instructions): _____

Sample Number	Sample location	Result
(Include percent and type of asbestos in result, e.g. 50% Chrysotile):		

<u>011403-025</u>	<u>Attic - East Central Corridor</u>	<u>None Detected</u>

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

HSA 017
1 of 17

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 1-19-03
ADDRESS: 14th & Constitution Ave.
GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.): _____

Location in Bldg: 7th floor Corridor - Intersection of East Corr. and Wing 1
(include Functional Space)

HOMOGENEOUS AREA: 9" x 9" Tan floor Tile w/ Brown & White Streaks [REDACTED] HSA-017

Type of Material	Damage	Accessibility
☐ Fireproofing	☐ Significant	☒ High
☐ Acoustical Plaster	☐ Minor	☐ Medium
☐ Acoustical Tile	☒ None	☐ Low
☐ Thermal Systems Insulation		
☒ Vinyl Floor Tile		Air Plenum _____ (Y or N)
☐ Other: _____		

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☒ High	☐ High	☐ High
☐ Medium	☐ Medium	☐ Medium	☐ Moderate
☒ Low	☐ Low	☒ Low	☒ Low

Comments: _____

AHERA Classification (see instructions): Non-Friable

Sample Number	Sample location	Result
(Include percent and type of asbestos in result, e.g. 50% Chrysotile).		
C011403 - 0261	7th floor Corridor	None Detected
C012203 - 040	Room 4035	None Detected
C012203 - 042	Room 3099C	None Detected

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

Page 3 of 17

HOMOGENEOUS AREA 9x9 FT Tan

Commerce Building

[illegible]

HSA 017

Page 3 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 FT TanBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
4893	2000 SF	G	
4890	2000 SF	G	
4883	1000 SF	G	
4884	1000 SF	G	
4878	2000 SF	G	
4881	2000 SF	G	
4861	3500 SF	G	
4858	3500 SF	G	
4843	3500 SF	G	
4842	3500 SF	G	
4826	2000 SF	G	
4827	2000 SF	G	
4324	1500 SF	G	
4320	1500 SF	G	
4312	1500 SF	G	
4321	2000 SF	G	
4411	800 SF	G	
4410	800 SF	G	
4416	1000 SF	G	
4424	1000 SF	G	
4525	2000 SF	G	
4519	2000 SF	G	

HSA 017

Page 4 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 FT TanBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
1035	600 SF	G	
1039	600 SF	G	
1036	1500 SF	G	
1053	2000 SF	G	
1054	2000 SF	G	
1057	2000 SF	G	
1044	2000 SF	G	
1065	2000 SF	G	
1076	1000 SF	G	
1077	1000 SF	G	
1082	1000 SF	G	
1083	1000 SF	G	
1096	3000 SF	G	
1091	3000 SF	G	
1099 A	1000 SF	G	
1101	500 SF	G	
1113	3000 SF	G	
1108	5000 SF	G	
1125	3000 SF	G	
1122	2000 SF	G	
1197	2000 SF	G	
1196	2000 SF	G	

HSA 017

Page 5 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 FT TanBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
1813	1000 SF	G	
1814	1300 SF	G	
1807	300 SF	G	
1800B	1000 SF	G	
1800	1000 SF	G	
1 TH Floor Southwest Corridor	1200 SF	G	
1 TH Floor Southeast Corridor	1200 SF	G	
1 TH Floor Corridor 1	1800 SF	G	
H150	800 SF	G	
H120	1500 SF	G	
H119	800 SF	G	
H112	1500 SF	G	
H113	800 SF	G	
H109	400 SF	G	
H102	1200 SF	G	
H024	800 SF	G	
H023	300 SF	G	
H025	300 SF	G	
H027	300 SF	G	
H029A	500 SF	G	
H029B	800 SF	G	
H035	600 SF	G	

HSA 017

Page 6 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 FT TanBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
2099B	1400 SF	G	
4001	1000 SF	G	
4003	1000 SF	G	
4008	1400 SF	G	
4009	900 SF	G	
4012	600 SF	G	
4015	600 SF	G	
4015C	600 SF	G	
4203	600 SF	G	
4017	300 SF	G	
1019	300 SF	G	
1021	300 SF	G	
1020	1000 SF	G	
204	800 SF	G	
1217	300 SF	G	
4219	300 SF	G	
4221	600 SF	G	
4220	300 SF	G	
4227	300 SF	G	
4226	800 SF	G	
4821	1000 SF	G	
4820	1600 SF	G	

HSA 017

Page 7 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 Floor Tile TanBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
2213	2000SF	G	
2225	2000SF	G	
2224	2000SF	G	
2814B	2000SF	G	
2815	2000SF	G	
281D	2000SF	G	
2807	2000SF	G	
2806	2000SF	G	
2128	1600SF	G	
2116	3000SF	G	
2104	400SF	G	
2111	1500SF	G	
2119	1500SF	G	
2830B	3000SF	G	
2841	3000SF	G	
2854	2000SF	G	
2865	3000SF	G	
Central Mail Room 2nd floor	9000SF	G	
2320	900SF	G	
1325	1200SF	G	
2893	1500SF	G	
2705	300SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 Floor Tile TanBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
1117	1200 SF	G	
1222	800 SF	G	
1815	1000 SF	G	
1800	900 SF	G	
1805	1000 SF	G	
1800A	1000 SF	G	
1124	2500	G	
1114	100 SF	G	
1109	1800 SF	G	
1108	800 SF	G	
1104	1000 SF	G	
1731	300 SF	G	
1099D	1400 SF	G	
1093	600 SF	G	
1087	1500 SF	G	
1607	1600 SF	G	
2001A	800 SF	G	
2003	900 SF	G	
2006	500 SF	G	
2012	1200 SF	G	
2015A	2600 SF	G	
2201	300 SF	G	
2202	1200 SF	G	

HSA 017

Page 9 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 FT Tan w/ Tan & White StreaksBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
3427	900 SF	G	
3527	300 SF	G	
3525	300 SF	G	
3523	300 SF	G	
3521	300 SF	G	
3519	300 SF	G	
3517	300 SF	G	
3515	600 SF	G	
3510	1600 SF	G	
3518	900 SF	G	
7 th Floor ^{Southeast Corridor} ALL Corridors	2400 SF	G	300 SF per Corridor
7077	1000 SF	G	
7081	300 SF	G	
7087	1200 SF	G	
7089	300 SF	G	
7095	200 SF	G	
7097	450 SF	G	
7099C	1200 SF	G	
7703	150 SF	G	
7705	300 SF	G	
7713	1200 SF	G	
7717	1600 SF	G	
7727	800 SF	G	

HSA 017

Page 10 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 FT TanBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
723	500SF	G	
7614	900SF	G	
7620	1000SF	G	
7628	600SF	G	
7898	1200SF	G	
7892	1200SF	G	
7886B	1000SF	G	
7886	400SF	G	
7884	400SF	G	
7882	400SF	G	
7876	1200SF	G	
7870	600SF	G	
7869	600SF	G	
7868	600SF	G	
7862	400SF	G	
7860	600SF	G	
7865	300SF	G	
7863	300SF	G	
7861	300SF	G	
7865	1000SF	G	
7855	1000SF	G	
7850	600SF	G	

ASA 017

Page 11 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUED

HOMOGENOUS AREA 9x9 FT Tan

BUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
7849	400 SF	G	
7846	600 SF	G	
7840	600 SF	G	
7838	400 SF	G	
7837	1200 SF	G	
7836	400 SF	G	
7832	800 SF	G	
7826	800 SF	G	
7824	600 SF	G	
7816	800 SF	G	
7814C	400 SF	G	
7814A	2000 SF	G	
7800	2000 SF	G	
1 TH Floor NW Corridor	1600 SF	G	
1114	2000 SF	G	
106	800 SF	G	
1 TH Floor Corridor 1	2000 SF 2500 SF	G	
7215	400 SF	G	
7221	1500 SF	G	
7227	400 SF	G	
7231	800 SF	G	
1 TH Floor Corridor 2	1600 SF	G	

ASA 017

Page 10 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUED

HOMOGENOUS AREA 9x9 FT Tan

BUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
3877	600SF	G	
3875	300SF	G	
3868 A	2000SF	G	
3867	300SF	G	
3863	1000SF	G	
3862	3500SF	G	
3855	1400SF	G	
3849	400SF	G	
3845	2000SF	G	
3832	2000SF	G	
3826	900SF	G	
3827	900SF	G	
3327	1000SF	G	
3324	900SF	G	
3319	1500SF	G	
3320	600SF	G	
3316	600SF	G	
3413	600SF	G	
3412	1500SF	G	
3415	300SF	G	
3421	900SF	G	
3420	300SF	G	
3424	900SF	G	

HRA 017

Page 13 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 FT TanBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
3079	300 SF	G	
3077	300 SF	G	
3082	600 SF	G	
3080	300 SF	G	
3083	300 SF	G	
3085	300 SF	G	
3087	200 SF	G	
3002	500 SF	G	
3087B	800 SF	G	
3087C 3096	300 SF	G	
3098	300 SF	G	
3099	600 SF	G	
3099B	1000 SF	G	
3898 C	2000 SF	G	
3899C	300 SF	G	
3897	1000 SF	G	
3889	800 SF	G	
3886C	1500 SF	G	
3882	600 SF	G	
3883	1000 SF	G	
3623	600 SF	G	
3618	600 SF	G	
3878	1000 SF	G	

HSA 017

Page 14 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 FT TanBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
3113	300SF	G	
3109	300SF	G	
Corridor B	1100SF	G	
3802	1600SF	G	
3810	1200SF	G	
3814	1000SF	G	
3805	1200SF	G	
3818	1000SF	G	
3215	2500SF	G	
3224	1000SF	G	
3038	2000SF	G	
3058	300SF	G	
3061	300SF	G	
3060	300SF	G	
3065	600SF	G	
3063	300SF	G	
3064	600SF	G	
3068	600SF	G	
3069 A	800SF	G	
3073	500SF	G	
3075	300SF	G	
3076	300SF	G	
3074	500SF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 FT TAYBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
3001 A	400 SF	G	
3003	300 SF	G	
3011	600 SF	G	
3001 B	300 SF	G	
3005	200 SF	G	
3007	300 SF	G	
Corridor O	2000 SF	G	
3009	300 SF	G	
3013	300 SF	G	
3015 B	300 SF	G	
3015 A	300 SF	G	
3004	800 SF	G	
3014	1000 SF	G	
3021	600 SF	G	
Corridor I	1000 SF	G	
3106	300 SF	G	
3108	300 SF	G	
3122	2000 SF	G	
3119	1000 SF	G	
3100	400 SF	G	
3114	300 SF	G	
3116	200 SF	G	
3115	300 SF	G	

HSA 017

Page 16 of 17

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA 9x9 Floor Tile TanBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
1041	500 SF	G	
1030	1500 SF	G	
1314	1200 SF	G	
1317	3000 SF	G	
1320	1600 SF	G	
833	600 SF	G	
842	1200 SF	G	
1839	1600 SF	G	
1851	500 SF	G	
854	2000 SF	G	
1859	600 SF	G	
1863	1500 SF	G	
1874	600 SF	G	
1528	3000 SF	G	
1521	1200 SF	G	
1067	1600 SF	G	
1st Floor Auditorium	5000 SF	G	
1003	1600 SF	G	
1008	900 SF	G	
1009	900 SF	G	
1015	2000 SF	G	
1206	800 SF	G	
1700	1700 SF	G	

Page 17 of 17

HOMOGENOUS AREA 9x9 Tan FT

BUILDING: Commerce Building

[illegible]

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg. ASSESSMENT DATE: 1-14-03
 ADDRESS: 14th & Constitution Ave.
 GSA BLDG NO.: DC0013ZZ AMOUNT(S.F./L.F.): _____

Location in Bldg: 7th floor - Men's Bathroom 7021 M
 (include Functional Space)

HOMOGENEOUS AREA: Ceramic Wall-Tile Grout 153.46 153.46

Type of Material	Damage	Accessibility
☐ Fireproofing	☐ Significant	☒ High
☐ Acoustical Plaster	☐ Minor	☐ Medium
☐ Acoustical Tile	☒ None	☐ Low
☐ Thermal Systems Insulation		
☐ Vinyl Floor Tile		Air Plenum <u>N</u>
☒ Other: _____		(Y or N)

Friability	Traffic	Vibration	Potential for Air Erosion
☐ High	☐ High	☐ High	☐ High
☐ Medium	☐ Medium	☐ Medium	☐ Moderate
☒ Low	☒ Low	☒ Low	☒ Low

Comments: _____

AHERA Classification (see instructions): _____

Sample Number	Sample location	Result
(Include percent and type of asbestos in result, e.g. 50% Chrysotile).		
<u>001403 - 0271</u>	<u>7th floor - 7021 M</u>	<u>None Detected</u>
<u>-051, 6th Floor - Rm 6229W</u>	<u>6229W</u>	<u>None Detected</u>

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

HBA 019

1 of 25

ASBESTOS ASSESSMENT DATA FORM

BLDG NAME: Commerce Bldg
 ADDRESS: 14th & Constitution Ave.
 GSA BLDG NO.: DC0013ZZ

ASSESSMENT DATE: 1-22-03
 AMOUNT(S.F./L.F.) _____

Location In Bldg: Room 7019
 (include Functional Space)

HOMOGENEOUS AREA: Brass Mastic on Metal Duct HBA-019

Type of Material
☐ Fireproofing
☐ Acoustical Plaster
☐ Acoustical Tile
☐ Thermal Systems Insulation
☐ Vinyl Floor Tile
☒ Other: _____

Damage
☐ Significant
☐ Minor
☒ None

Accessibility
☐ High
☐ Medium
☒ Low

Air Plenum N
 (Y or N)

Friability
☐ High
☐ Medium
☒ Low

Traffic
☐ High
☐ Medium
☒ Low

Vibration
☐ High
☐ Medium
☒ Low

Potential for Air Erosion
☐ High
☒ Moderate
☐ Low

Comments: _____

AHERA Classification (see instructions): Nonfriable

Sample Number	Sample Location	Result
(Include percent and type of asbestos in result, e.g. 50% Chrysotile).		
C012203-029	Room 7019: 7th F/R	3% Chrysotile
-072, 6th Floor: 6814		4% Chrysotile

NOTE: Use one form per homogeneous area. Consult 40 CFR Part 763 for sampling and analytical protocols and definitions.

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Brown Mastic on Metal DuctLOADING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
60316	30 LF	G	
60321	10 LF	G	
60324	20 LF	G	
60422	30 LF	G	
60416	10 LF	G	
60412	20 LF	G	
60411	20 LF	G	
60508	10 LF	G	
60521	20 LF	G	
60520	20 LF	G	
60714	10 LF	G	
Basement Wing 3 Corridor	100 LF	G	
3315	50 LF	G	
Basement Wing 3 Corridor	55 LF	G	
3031	5 LF	G	
Basement South end of entrail eastern corridor	50 LF	G	
Basement Cafeteria	50 LF	G	
3099	50 LF	G	
	560		

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENEOUS AREA Brown Mastic on Metal DuctBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
6013	20 LF	G	
6012	10 LF	G	
6011	10 LF	G	
6008	10 LF	G	
6072	20 LF	G	
6069	10 LF	G	
6065	20 LF	G	
6057	30 LF	G	
6040	40 LF	G	
6039	40 LF	G	
6027	20 LF	G	
6028	20 LF	G	
6022	20 LF	G	
6023	10 LF	G	
6019	20 LF	G	
6014A	30 LF	G	
6012	10 LF	G	
6009	50 LF	G	
6128	75 LF	G	
6128	30 LF	G	
6111	10 LF	G	
6107	30 LF	G	

HSA 019

Page 4 of 25

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Brown Mastie on Metal DuctBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
60216	20 LF	G	
6037	30 LF	G	
6054	30 LF	G	
6065	20 LF	G	
6073	10 LF	G	
6078	20 LF	G	
6083	10 LF	G	
6087	10 LF	G	
6086	20 LF	G	
6080A	10 LF	G	
6089	20 LF	G	
6092	20 LF	G	
6095	15 LF	G	
6099A	30 LF	G	
6098	10 LF	G	
6099C	20 LF	G	
6701	10 LF	G	
6707	50 LF	G	
6733A	25 LF	G	
6729	10 LF	G	
6725	20 LF	G	
6716	10 LF	G	

HSA 019

Page 5 of 25

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Brown Mastic on Metal DuctBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
5 TH Floor Corridor 5	200LF	G	4" Strips every 12'
5 TH Floor Corridor 4	200LF	G	4" Strips every 12'
5521	10LF	G	
5517	15LF	G	
5511	10LF	G	
5516	20LF	G	
5413	20LF	G	
5414	20LF	G	
5421	15LF	G	
5422	20LF	G	
5425	10 LF	G	
5312	10LF	G	
5321	20 LF	G	
5324	30LF	G	
5327	10 LF	G	
6013	50LF	G	
6012	20LF	G	
6009	20LF	G	
6006	20LF	G	
6204	30LF	G	
6217	70LF	G	
6228	20LF	G	

HSA 019

Page 6 of 25

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Brown Mastic on Metal DuctBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
5108	10LF	G	
5111	20LF	G	
5118	20LF	G	
5119	10LF	G	
5128	25LF	G	
5TH Floor Corridor 1	225LF	G	4" Strip every 12'
5804	20LF	G	
5805	20LF	G	
5810	30LF	G	
5811	20LF	G	
5814A	30LF	G	
5820	20LF	G	
5821	10LF	G	
5TH Floor Southwest Corridor	100LF	G	
5825	15LF	G	
5824	5LF	G	
5830	20LF	G	
5835	10LF	G	
5870	20LF	G	
5875	20LF	G	
5876	10LF	G	
5TH Floor West Central Corridor	250LF	G	4" Strip every 12'

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Brown Mastic on Metal DuctLDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
5717	20LF	G	
5721	10LF	G	
5727	10LF	G	
5733	10LF	G	
5898C	10LF	G	
5897	10LF	G	
5896	10LF	G	
5893	20LF	G	
5890	20LF	G	
5889	20LF	G	
5886C	20LF	G	
5886	20LF	G	
5883	20LF	G	
5618	10LF	G	
5611	10LF	G	
5612	10LF	G	
5217	30LF	G	
5224	20LF	G	
5230	10LF	G	
5 TH Floor Corridor	200LF	G	4" Strip every 12'
5102	10LF	G	
5104	10LF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Brown Mastic on Metal DuctBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
5053	20LF	G	
5063	10LF	G	
5067	10LF	G	
5071	10LF	G	
5075	20LF	G	
5080	20LF	G	
5083	20LF	G	
5087	10LF	G	
5086	10LF	G	
5093	20LF	G	
5092	20LF	G	
5098	10LF	G	
5090	20LF	G	
5 TH Floor Northwest Corridor	125LF	G	4" Strip every 12'
5 TH Floor Corridor T	225LF	G	4" Strip about every 12'
5 TH Floor Northwest Corridor	225LF	G	4" Strip about every 12'
5 TH Floor Corridor 6	200LF	G	4" Strip about every 12'
5701A	40LF	G	
5705 5709	10LF	G	
5711	10LF	G	
5712	10LF	G	
5710	10LF	G	

KSA 019

Page 9 of 25

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Brown MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
4522	10 LF	G	
4510	10 LF	G	
4 TH Floor Corridor	60 LF	G	
4612	10 LF	G	
4622	10 LF	G	
4628	10 LF	G	
4613	10 LF	G	
4625	10 LF	G	
4629	10 LF	G	
5001	10 LF	G	
5005	30 LF	G	
5004	20 LF	G	
5019	10 LF	G	
5016	10 LF	G	
5020	10 LF	G	
5023	10 LF	G	
5027	10 LF	G	
5026	10 LF	G	
5029 B	20 LF	G	
5039	10 LF	G	
5040	20 LF	G	
5045	10 LF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Brown MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
4881	10LF	G	
4 TH Floor West Central Corridor	170LF	G	
4861	20LF	G	
4858	20LF	G	
4843	20LF	G	
4842	20LF	G	
4836	10LF	G	
4826	20LF	G	
4827	20LF	G	
7 TH Floor Corridor 3	60LF	G	
4324	10LF	G	
4320	10LF	G	
4312	10LF	G	
4321	20LF	G	
6 TH Floor Corridor 4	60LF	G	
411	10LF	G	
410	10LF	G	
416	5LF	G	
424	10LF	G	
4 TH Floor Corridor 5	60LF	G	
4525	10LF	G	
4519	20LF	G	

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Brown MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
4077	10LF	G	
4082	10LF	G	
4083	10LF	G	
1 TH Floor NE Corridor	10LF	G	
4096	20LF	G	
4091	20LF	G	
4099A	10LF	G	
4701	40LF	G	
4 TH Floor Corridor 7	50LF	G	
4713	10LF	G	
4708	10LF	G	
4725	10LF	G	
4722	10LF	G	
1 TH Floor NW Corridor	50LF	G	
4897	20LF	G	
4896	20LF	G	
4893	10LF	G	
4890	10LF	G	
4 TH Floor NW Corridor	50LF	G	
4883	20LF	G	
4884	20LF	G	
4878	10LF	G	

HSA 019

Page 13 of 25

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Brown masticBUILDING: Commercial Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
4119	20LF	G	
4112	20LF	G	
4113	20LF	G	
409	10LF	G	
402	20LF	G	
4024	20LF	G	
4023	5LF	G	
4025	5LF	G	
4027	5LF	G	
4029A	5LF	G	
4029B	20LF	G	
4035	10LF	G	
4039	10LF	G	
4 TH Floor East Central Corridor	10LF	G	
4036	5LF	G	
4053	5LF	G	
4054	10LF	G	
4057	10LF	G	
4044	10LF	G	
4 TH Floor Corridor O	50LF	G	
4065	20LF	G	
4076	10LF	G	

HSA 019

Page 13 of 25

ASBESTOS ASSESSMENT DATA FORM - CONTINUEDHOMOGENOUS AREA Brown MasticBUILDING: Commerce Building

LOCATION	APPROX. QUANTITY	CONDITION	NOTES
4015	10LF	G	
4203	10LF	G	
4017	10LF	G	
4019	10LF	G	
4021	10LF	G	
4020	10LF	G	
4204	10LF	G	
4217	10LF	G	
4219	10LF	G	
4221	10LF	G	
4220	10LF	G	
4227	10LF	G	
4226	20LF	G	
4821	20LF	G	
4820	20LF	G	
4813	10LF	G	
4814	30LF	G	
4807	10LF	G	
4800B	20LF	G	
4800	10LF	G	
4130	20LF	G	
4120	20LF	G	