

uEZGUI-RX62N-35QT Product Change Notification Form

| | | |
|--------------------------------|-----------------|-------------------------|
| PCN Number: 20110914-01 | Rev: 1.1 | Date: 09/14/2011 |
|--------------------------------|-----------------|-------------------------|

Summary of Change: uEZGUI-RX62N-35QT-BA board rework to allow use of CAN bus

Reason for Change: FDI has reworked the uEZGUI-RX62N-35QT-BA to allow use of the CAN bus on the expansion connector.

Detailed Description of Change: The LCD HSYNC signal was moved to a different pin to allow CAN to be available on the previously used pin. This involved 7 trace disconnections to the board and reconnections using jumper wire.

Products Affected:

| Effected Product (Rev 1.0) | Recommended Replacement Product (Rev 1.1) |
|----------------------------|---|
| uEZGUI-RX62N-35QT | uEZGUI-RX62N-35QT |
| uEZGUI-RX62N-35QT-BA | uEZGUI-RX62N-35QT-BA |

Availability of new revision stock at distributors:

Distributors will continue to sell through their existing available stock before filling customers' orders with stock of the new revision of the product.

Forecasted Key Dates and Milestones:

09/14/11 PCN Date, the date this document was released for distribution to customers and distributors.

09/14/11 Production Date for Recommended Replacement Product, the first date that production quantities of the replacement units will be available for customer order.

Reference Documents: <http://www.teamfdi.com/support/touch-screen.php#uezgui-rx62n-35qt>

1. uEZGUI-RX62N-35QT Brochure.pdf
2. uEZGUI-RX62N-35QT Quick Start Guide.pdf
3. uEZGUI-RX62N-35QT Users Manual.pdf
4. uEZGUI-RX62N-35QT_SCH_1.pdf
5. uEZGUI-RX62N-35QT_SCH_1.1.pdf
6. uEZGUI-RX62N-35QT Rev 1.1 ECO



FDI Contacts:

For additional information or details please contact any of our franchised Distributors including Avnet, Digi-Key and Mouser. Or contact the Product Team at FDI directly via email at support@teamfdi.com or via phone at 256-883-1240 or fax at 256-883-1241.