



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	19,258.3	TSO:	0.0	W/O#:	7102
PCE:	41546	CSN:	18,999	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	86B515	10,255	8,745
Disk, 2 nd Stg.	3013712	A001EENX	10,255	13,745
Disk, 3 rd Stg.	3011713	A001ED8K	10,255	14,745
Impeller	3013176	9H833	10,255	8,745
Disk, CT	3013411	A001ENK9	10,255	5,745
PT Disk, 1 st Stg.	3026812	5X300	10,813	9,187

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004	1198942	0.0
FUEL PUMP	025323-101-03	11706	0.0
FUEL CONTROL UNIT	2524440-9	C7222	0.0
START FLOW CONTROL	3019109	9535	0.0
OIL/FUEL HEATER	10552E	1392	0.0
COMP. BLEED VALVE	3100829-03	A7038	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.