

OWNER: CO OWNERS CHALLENGER VH-URR
ADDRESS: PO BOX 242
 SCARBOROUGH WA 6922
PHONE: 08 9444 5800
FAX: 08 9444 3748

OPERATOR: CO OWNERS CHALLENGER VH-URR
ADDRESS: PO BOX 242
 SCARBOROUGH WA 6922
PHONE: 08 9444 5800
FAX: 08 9444 3748

OPERATOR: ROWBOTTOM AVIATION SERVICE
ADDRESS: P.O. BOX 201
 PERTH WESTERN AUSTRALIA 6936
PHONE: +61 429773333
FAX:

ANALYST: CRAIG MALLA 514-448-1128 (OFFICE) 800-787-9749
 (EFAX-CARDS)
EMAIL: CMALLA@CAMPSYSTEMS.COM 514-448-1120 (FAX) 631-980-4222
 (EFAX-CARDS)
 WWW.CAMPSYSTEMS.COM

PROJECTED : 4 MOS. to 03-DEC-2012

AIRCRAFT	SERIAL/REGNO: 5439/VH-URR	MODEL: CL-604	MANUFACTURER: BOMBARDIER INCORPORATED	
DATES		LAST ACTUALS		PROJECTED
CERTIFICATION DATE: 31-MAY-2000		6221.6 A/C HRS	as of 30-JUL-2012	6382.03
		2555 AFL	as of 30-JUL-2012	2655
		3695 APH	as of 20-JUL-2012	3815.33

APU	SERIAL/PART: P-641C/3800804-1	MODEL: GTCP 36-150 (CL)	MANUFACTURER: HONEYWELL	
INSTALLED ON 21-OCT-2011		LAST ACTUALS		PROJECTED
3486 APU HRS		3695 APU HRS	as of 20-JUL-2012	3815.33
0 APUS		0 APUS	as of 20-JUL-2012	100

ENGINE NO. 1	SERIAL/PART: 872641/CF34-3B	MODEL: CF-34-3B (CIMMS)	MANUFACTURER: GENERAL ELECTRIC	
INSTALLED ON 31-MAY-2000		LAST ACTUALS		PROJECTED
9 ENG. HRS	9 A/C HRS	6221.6 ENG. HRS	as of 30-JUL-2012	6382.03
21 ENC		2554 ENC	as of 30-JUL-2012	2654

ENGINE NO. 2	SERIAL/PART: 872642/CF34-3B	MODEL: CF-34-3B (CIMMS)	MANUFACTURER: GENERAL ELECTRIC	
INSTALLED ON 31-MAY-2000		LAST ACTUALS		PROJECTED
9 ENG. HRS	9 A/C HRS	6221.6 ENG. HRS	as of 30-JUL-2012	6382.03
21 ENC		2554 ENC	as of 30-JUL-2012	2654



NEW REQUIREMENT/FLAGGED ITEMS Operator Review And Action Required

CL-604 S/N 5439 (VH-URR): 6221.6 HRS, 2555 AFL as of 30-Jul-2012

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

TASK NO	TASK DESCRIPTION	EFFECTIVE DATE	UNIT	INTERVAL	BASE TIME		NEXT DUE	DISPOSITION	
					Current	Change To			
SB 604-34-065	MODIFICATION – PITOT-STATIC AND TEMPERATURE SENSING SYSTEM – REPLACEMENT OF PITOT-STATIC VISUAL DRAIN BOTTLES TO LARGER CAPACITY BOTTLES SERVICE BULLETIN	31-JUL-2012	DUE NEXT	MOS	24	31-JUL-2012	_____	31-JUL-2014	RECOMMENDED
				HRS/MSC			_____		
	REF: BULLETINS			AFL			_____		
	NEW REQUIREMENT ADDED ON 01-AUG-2012. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

AUTHORIZED BY _____ CERT.# _____ DATE _____

?-Insufficient Information (s) Suppressed Requirement *-Estimated Due (New Requirement) (EBT)-Estimated Base Time

03-AUG-2012

© CAMP SYSTEMS



Due List

All Items

CL-604 S/N 5439 (VH-URR): 6221.6 HRS, 2555 AFL as of 30-Jul-2012

Operator: CO OWNERS CHALLENGER VH-URR

Report Date: 03-AUG-2012

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
05-00-CUS-9001	UPDATE / REISSUE ONBOARD MAINTENANCE DUE LIST	DAYS	30			19-JUL-2012		CUSTOMER CODE	
		HRS/MSC				6209.40		15 d	18-AUG-2012
	REF:	AFL				2548			
WO: 400 H / 400 H CUSTOMIZED									
792023	PERFORM L/H ENGINE TREND DOWNLOAD	MOS				10-MAY-2012			21-AUG-2012
		HRS/MSC				6149			
	REF:	AFL	50			2520	2570	2580	15 (+10)
				+10/-10					
WO: 400 H / 400 H CUSTOMIZED									
792025	PERFORM R/H ENGINE TREND DOWNLOAD	MOS				10-MAY-2012			21-AUG-2012
		HRS/MSC				6149			
	REF:	AFL	50			2520	2570	2580	15 (+10)
				+10/-10					
WO: 400 H / 400 H CUSTOMIZED									
056605	1 MONTH INSPECTION ITEMS	MOS	1			24-JUL-2012			24-AUG-2012
		HRS/MSC				6209.40			
	REF:	AFL				2548			21 d
WO: 400 H / 400 H CUSTOMIZED									
346106	UPDATE NAV DATA BASE	MOS				19-JUL-2012			28-AUG-2012
		HRS/MSC				6209.40		25 d	28-AUG-2012
	REF:	AFL				2548			
WO: 400 H / 400 H CUSTOMIZED									
49-51-00-301	APU - RESTORATION (ON-WING CLEANING) OF THE AUXILIARY POWER UNIT (APU) LOAD CONTROL VALVE FILTER	MOS				19-JUL-2012		OPTIONAL	02-SEP-2012
		HRS/MSC	30			3695	3725	30	
	REF: See Workcard	APUS				0			
050012	100 HOUR CHECK	MOS				25-JUN-2012			20-SEP-2012
		HRS/MSC	100			6185.90	6285.90	64.3	
	REF: GENERIC NO REF	AFL				2535			
WO: 400 H / 400 H CUSTOMIZED									
38C078	OPERATIONAL TEST AIR PRESSURE REGULATOR PRESSURE GAGE	MOS	3			25-JUN-2012			20-SEP-2012
		HRS/MSC	100			6185.90	6285.90	53 d	20-SEP-2012
	REF:	AFL				2535		64.3	
WO: 400 H / 400 H CUSTOMIZED									

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W
 * - Estimated Due (applies to New Requirement)



Due List

All Items

CL-604 S/N 5439 (VH-URR): 6221.6 HRS, 2555 AFL as of 30-Jul-2012

Operator: CO OWNERS CHALLENGER VH-URR

Report Date: 03-AUG-2012

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
05-00-00-701	VISUAL CHECK OF THE ALERT SERVICE BULLETINS LISTED IN SECTION 5-30-10 OF THE TLMC	MOS	3			25-JUN-2012		AIRWORTHINESS	
		HRS/MSC				6185.90		53 d	25-SEP-2012
	REF: See Workcard	AFL				2535			
WO: 400 H / 400 H CUSTOMIZED									
26C137	CHECK SMOKE HOODS/PBE EXPIRATION/SHELF-LIFE DATE, INTEGRITY OF SEALED CONTAINER.	MOS	3			25-JUN-2012			
		HRS/MSC				6185.90		53 d	25-SEP-2012
	REF:	AFL				2535			
WO: 400 H / 400 H CUSTOMIZED									
761113-001A	FUNCTIONAL TEST OF THE ENGINE THROTTLE CONTROL GEARBOX (76-11-00-101)							CMR	
	P/N: 2100140-007	MOS				17-DEC-2009			25-SEP-2012
	S/N: 914	HRS/MSC	1000			5292	6292	70.4	
	REF: AMM 76 11 13 720 802	AFL				2138			
761113-002A	FUNCTIONAL TEST OF THE ENGINE THROTTLE CONTROL GEARBOX (76-11-00-101)							CMR	
	P/N: 2100140-010	MOS				11-DEC-2009			25-SEP-2012
	S/N: 316	HRS/MSC	1000			5292	6292	70.4	
	REF: AMM 76 11 13 720 802	AFL				2138			
05-00-00-702	VISUAL CHECK OF THE RECOMMENDED SERVICE BULLETINS LISTED IN SECTION 5-30-11 OF THE TLMC	MOS	6			02-APR-2012		AIRWORTHINESS	
		HRS/MSC				6107.90		60 d	02-OCT-2012
	REF: See Workcard	AFL				2507			
WO: 400 H / 400 H CUSTOMIZED									
+ 27-13-04-101	OPERATIONAL TEST ROLL DISCONNECT SYSTEM	MOS				05-AUG-2010			18-OCT-2012
	27.070	HRS/MSC	800			5522	6322	100.4	
	REF: AMM 27 13 04 710 801	AFL				2276			
+ 27-14-01-101	FUNCTIONAL TEST AILERON POWER CONTROL UNITS (PCUS)	MOS				05-AUG-2010			18-OCT-2012
	27.075	HRS/MSC	800			5522	6322	100.4	
	REF: AMM 27 14 01 720 801	AFL				2276			
+ 27-21-00-101	FUNCTIONAL TEST RUDDER BACKLASH	MOS				05-AUG-2010			18-OCT-2012
	27.090	HRS/MSC	800			5522	6322	100.4	
	REF: AMM 27 21 00 720 805	AFL				2276			

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W
 * - Estimated Due (applies to New Requirement)

Due List

CL-604 S/N 5439 (VH-URR): 6221.6 HRS, 2555 AFL as of 30-Jul-2012

Operator: CO OWNERS CHALLENGER VH-URR

Report Date: 03-AUG-2012

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
+ 27-32-00-101	OPERATIONAL TEST ELEVATOR DISCONNECT SYSTEM	MOS				05-AUG-2010			18-OCT-2012
27.115		HRS/MSC 800			5522	6322		100.4	
	REF: AMM 27 32 00 710 801	AFL			2276				
+ 27-33-01-101	FUNCTIONAL TEST ELEVATOR BACKLASH	MOS				05-AUG-2010			18-OCT-2012
27.120		HRS/MSC 800			5522	6322		100.4	
	REF: AMM 27 31 00 720 805	AFL			2276				
+ 273404-001B	DETAILED INSPECTION LEFT OUTBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-102)	MOS				05-AUG-2010			18-OCT-2012
27.300	P/N: 600-75142-9	HRS/MSC 800			5522	6322		100.4	
	S/N: HA12166	AFL			2276				
	REF: AMM 27 34 04 220 801								
+ 273404-002B	DETAILED INSPECTION LEFT INBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-102)	MOS				05-AUG-2010			18-OCT-2012
27.305	P/N: 600-75142-9	HRS/MSC 800			5522	6322		100.4	
	S/N: HA12173	AFL			2276				
	REF: AMM 27 34 04 220 801								
+ 273404-003B	DETAILED INSPECTION RIGHT INBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-102)	MOS				05-AUG-2010			18-OCT-2012
27.310	P/N: 600-75142-9	HRS/MSC 800			5522	6322		100.4	
	S/N: HA12182	AFL			2276				
	REF: AMM 27 34 04 220 801								
+ 273404-004B	DETAILED INSPECTION RIGHT OUTBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-102)	MOS				05-AUG-2010			18-OCT-2012
27.315	P/N: 600-75142-9	HRS/MSC 800			5522	6322		100.4	
	S/N: HA12252	AFL			2276				
	REF: AMM 27 34 04 220 801								
+ 275107-001B	DETAILED INSPECTION NO. 1 AILERON FLUTTER (FLIGHT CONTROLS) DAMPER (27-15-07-101)	MOS				05-AUG-2010			18-OCT-2012
27.405	P/N: 600-75142-9	HRS/MSC 800			5522	6322		100.4	
	S/N: HA12224	AFL			2276				
	REF: AMM 27 15 07 220 801								
+ 275107-002B	DETAILED INSPECTION NO. 2 AILERON FLUTTER (FLIGHT CONTROLS) DAMPER (27-15-07-101)	MOS				05-AUG-2010			18-OCT-2012
27.410	P/N: 600-75142-9	HRS/MSC 800			5522	6322		100.4	
	S/N: HA12121	AFL			2276				
	REF: AMM 27 15 07 220 801								
+ 050017	800 HOUR CHECK	MOS				05-AUG-2010			07-NOV-2012
		HRS/MSC 800	+40/-40		5522	6348.40	6388.4	126.8 (+40)	
	REF: GENERIC NO REF	AFL			2276				

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W
 * - Estimated Due (applies to New Requirement)

Due List

CL-604 S/N 5439 (VH-URR): 6221.6 HRS, 2555 AFL as of 30-Jul-2012

Operator: CO OWNERS CHALLENGER VH-URR

Report Date: 03-AUG-2012

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
1	OIL/LUBE SERVICING QUANTITY CHECK OF THE OIL LEVEL IN THE INTEGRATED DRIVE GENERATOR (IDG)	DAYS				10-MAY-2012			07-NOV-2012
	REF:	HRS/MSC 200			6149		6349	127.4	
		AFL			2520				
	WO: 400 H / 400 H CUSTOMIZED								
273504-001A	FUNCTIONAL TEST NO. 1 ANGLE OF ATTACK TRANSDUCER LINEARITY (27-35-04-101)	MOS				31-JAN-2012			28-NOV-2012
27.330	P/N: 600-59154-3	HRS/MSC 300			6076.30		6376.30	154.7	
	S/N: GST02845	AFL			2490				
	REF: AMM 27 35 04 720 801								
273504-002A	FUNCTIONAL TEST NO. 2 ANGLE OF ATTACK TRANSDUCER LINEARITY (27-35-04-101)	MOS				31-JAN-2012			28-NOV-2012
27.335	P/N: 600-59154-3	HRS/MSC 300			6076.30		6376.30	154.7	
	S/N: 1241	AFL			2490				
	REF: AMM 27 35 04 720 801								
+ 57-10-00-117	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK WS85.5, STRINGERS 14 TO 17	MOS				31-MAY-2000			28-NOV-2012
57.075		HRS/MSC			21				
	REF: NDT ET-57-20-017	AFL 2651			9		2651	96	
+ 050040	6 MONTH CHECK	MOS	6	+1m/-1m		23-MAY-2012	01-DEC-2012	01-JAN-2013	120 d (+31) 01-DEC-2012
	REF: GENERIC NO REF	HRS/MSC			6149				
		AFL			2520				
056615	6 MONTH CUSTOMIZED CHECK	MOS	6	+1m/-1m		23-MAY-2012	02-DEC-2012	02-JAN-2013	121 d (+31) 02-DEC-2012
	REF:	HRS/MSC			6149				
		AFL			2520				
319001	REPLACE PILOT CLOCK BATTERIES	MOS	12			02-DEC-2011	02-DEC-2012		121 d 02-DEC-2012
	REF:	HRS/MSC			6034.30				
		AFL			2467				
319002	REPLACE CO-PILOT CLOCK BATTERIES	MOS	12			02-DEC-2011	02-DEC-2012		121 d 02-DEC-2012
	REF:	HRS/MSC			6034.30				
		AFL			2467				

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W
* - Estimated Due (applies to New Requirement)

Discrepancy Due List Report

MODEL: CL-604 SERIAL: 5439 RegNo: VH-URR

Report Date: 03-AUG-2012

DISCR # DATE LOGGED PART/SERIAL	CATEGORY	ATA	DESCRIPTION	UNIT	INTERVAL	LOGBOOK TIMES	NEXT DUE (x Ext)	TIME REMAINING	EST. DATE
---------------------------------------	----------	-----	-------------	------	----------	------------------	------------------	-------------------	-----------

NO DATA FOUND