



Service Bulletin

(This bulletin and all other active bulletins are downloadable from our website at www.frymaster.com/parts_service.)

Bulletin 2004-05-ABDE

Page 1 of 1

Date: 01/13/2004

SUBJECT: Warranty Label for McDonald's Products

This bulletin supersedes and cancels bulletin 2002-08-ABDE. Remove bulletin 2002-08-ABDE from your active files.

Since June 1, 2002, products manufactured by Frymaster for McDonald's have shipped with a warranty label, illustrated below.



The label, when the proper tabs are removed, denotes the month and year of the product's installation.

The labels are used on all McDonald's products, including H52 gas fryers, H14 electric fryers, HLZs, UHCs and VTs. Servicers must remove the appropriate tabs when the installation of the equipment is complete. In the case of fryers, servicers must also indicate on the Fryer Start-Up Form (819-5689) that the tabs have been removed.