

TEST ID NUMBER: 998890
DATE RECEIVED: 01/22/2016
REPORT DATE: 01/25/2016

DANIEL WELCH
1232 RIVER PARK CIRCLE WEST
MUKWONAGO, WI 53149

TEST LOCATION

1232 RIVER PARK CIRCLE WEST
WAUKESHA
MUKWONAGO, WI 53149

This is a confidential report of the radon samples that were submitted to our laboratory for measurements of radon-222 levels. The results represent the amount of radon that was present in the air during the time of sampling. The radon is measured in our laboratory using the liquid scintillation method (EPA 402-R-92-004). This report will not be released to anyone without your permission except as required by individual state laws and guidelines.

HERE ARE YOUR TEST RESULTS

<u>VIAL #</u>	<u>ROOM TESTED</u>	<u>DATE OPENED</u>	<u>DATE CAPPED</u>	<u>DATE ANALYZED</u>	<u>RADON LEVEL</u>
3999807	BASEMENT	Jan 16, 2016 1:00 PM	Jan 20, 2016 1:00 PM	Jan 24, 2016 9:28 AM	6.5 pCi/L
3985491	BASEMENT	Jan 16, 2016 1:00 PM	Jan 20, 2016 1:00 PM	Jan 24, 2016 9:39 AM	6.1 pCi/L

AVERAGE RADON LEVEL (average result of two tests) : 6.3 pCi/L

THE EPA RECOMMENDS THAT YOU FIX YOUR HOME IF THE RADON LEVEL IS 4 PICOCURIES (PCi/L) OR HIGHER.

Please read the EPA Citizen's Guide to Radon at www.epa.gov/radon/pubs/citguide.html. Residents of New Jersey should read "Radon Testing and Mitigation: The Basics" at <http://njradon.org/download/mitbas.pdf>. Radon levels less than 4 pCi/L still pose a risk. You may want to take additional measurements because radon levels can vary with the seasons. You may also want to consider doing a long term test to determine the average radon concentrations over a longer period of time. If the radon level is 4.0 pCi/L or higher you should perform either a long-term test or a second short-term test. If the radon level is higher than 10 pCi/L you should perform a second short-term test immediately. **If you would like to learn how to lower your radon levels, or have other questions, please contact your state radon office at (888) 569-7236.**

LIMITATIONS OF DATA AND PRODUCT LIABILITY

PRO-LAB expressly disclaims any and all liability for any special, incidental, or consequential damages resulting directly or indirectly from the improper use of or improper interpretation of the radon product or its results. Any delays in receipt of the test sample by PRO-LAB shall be the sole responsibility of the purchaser and their legal remedy shall be limited to recourse with their chosen carrier. Additionally, PRO-LAB shall not be responsible for the improper placement of the test canister nor shall PRO-LAB be liable for results derived directly or indirectly from the improper placement of said test canister. PRO-LAB, its agents, its retailers, its distributors, and the manufacturers' sole liability are limited to the cost for the replacement of the test canister itself only.



Malissa Sears, RMS

NEHA-NRPP CERT# 104126RT
AARST ID#779



James E. McDonnell IV

NEHA-NRPP ID# 103456RT
AARST ID#558