


BUILDING RECORD

MAP LOT ACCOUNT NO. 411 ADDRESS CARD NO. OF

| | | | | | |
|-------------------------|---------------|-------------------------------|---------|---------------------------|-------------|
| BUILDING STYLE | | S/F BSMT LIVING | 468 | INSULATION | 1 |
| 1. Conv. | 6. Split Lev. | FIN BSMT GRADE | 0.3 | 1. Full | 4. Minimal |
| 2. Ranch | 7. Contemp. | | 100% | 2. Heavy | 9. None |
| 3. R. Ranch | 8. Log | HEAT TYPE | 1 | 3. Capped | |
| 4. Cape | 9. Other | 1. HW BB | | UNFINISHED % | |
| 5. Garrison | | 6. Grav. WA | | | |
| DWELLING UNITS | | 2. HW CI | | GRADE & FACTOR | |
| 1 | | 3. HW Radiant | | 1. E | 4. B |
| OTHER UNITS | | 4. Steam | | 2. D | 5. A |
| STORIES | | 5. FWA | | 3. C | 6. AA |
| 1. One | 4. 1 1/2 | COOL TYPE | | SQ. FOOTAGE | |
| 2. Two | 5. 1 3/4 | 1. Central | 9 | 936 | |
| 3. Three | 6. 2 1/2 | 9. None | | CONDITION | |
| EXTERIOR WALLS | | KITCHEN STYLE | | 1. Poor | 5. Avg + |
| 1. Clapboard | 6. BR/Stone | 1. Good | 2 | 2. Fair | 6. Good |
| 2. WD.SH. | 7. Novelty | 2. Typical | | 3. Avg - | 7. V Good |
| 3. Comp. | 8. AL/Vinyl | 4. Obsolete | | 4. Avg. | 8. Exc. |
| 4. ASB/ASP | 9. Other | BATH(S) STYLE | | PHYS. % GOOD | |
| 5. T1-11 | | 1. Good | 2 | | |
| ROOF SURFACE | | 2. Typical | | FUNCT. % GOOD | |
| 1. Asphalt | 4. Comp. | 4. Obsolete | | | |
| 2. Slate | 5. Wood | # ROOMS | | FUNCT. CODE | |
| 3. Metal | 6. Other | # BEDROOMS | 4 | 1. Incomp. | 5. CDU |
| S/F MASONRY TRIM | | # FULL BATHS | 2 | 2. Overbuilt | 6. Style |
| YEAR BUILT | | # HALF BATHS | | 3. Delap. | 7. Layout |
| 1980 | | # ADDN FIXTURES | | 4. Small Size | 8. Other |
| YEAR REMODELED | | # FIREPLACES | 1 | 9. None | |
| FOUNDATION | | # HEARTHES | | ECON. % GOOD | |
| 1. Conc. | 4. Wood | LAYOUT | 1 | ECON. CODE | |
| 2. C Blk | 5. Slab | 1. Typical | | 1. Location | 3. Services |
| 3. Br./Stone | 6. Piers | 2. In adeq. | | 2. Encroach | 9. None |
| BASEMENT | | ATTIC | 4 | ENTRANCE CODE | |
| 1. 1/4 | 3. 3/4 | 1. 1/4 Fin. | | 1. Inspct. | 3. Vacant |
| 2. 1/2 | 4. Full | 4. Full Fin. | | 2. Refused | 5. Estim. |
| 5. Crawl | 6. None | 5. F/Stairs | | 3. Info Only | |
| BSMT GAR # CARS | | 3. 3/4 Fin. | | INFO. CODE | |
| 1 CAR | | INT COMP TO EXIT + = - | | 1. Owner | 4. Agent |
| WET BASEMENT | | INSPECTED BY | JLD | 2. Relative | 5. Estimate |
| 1. Dry | 3. Wet | DATE INSPECTED | 12/2/05 | 3. Tenant | 6. Other |
| 2. Damp | 9. None | | | 2. Refused | 5. Estim. |



| ADDITIONS, OUTBUILDINGS & IMPROVEMENTS | | | | | | PERCENT GOOD | | CODES |
|--|------|-------|-------|------|-------|--------------|---|--------------------|
| TYPE | YEAR | UNITS | GRADE | COND | Phys. | Funct. | | |
| DWL | 01 | 1980 | 936 | 3.00 | 5 | % | % | 1. 1S Fr. |
| OK | 68 | | 236 | | 5 | % | % | 2. 2S Fr. |
| JHD | 24 | | 48 | | 4 | % | % | 3. 3S Fr. |
| JHD | 24 | | 48 | | 4 | % | % | 4. 1 1/2S Fr. |
| JHD | 24 | | 144 | | 4 | % | % | 5. 1 3/4S Fr. |
| JHD | 24 | | 84 | | 4 | % | % | 6. 2 1/2S Fr. |
| | | | | | | % | % | Add 10 for Bsmt |
| | | | | | | % | % | 21. OFF |
| | | | | | | % | % | 22. EFP |
| | | | | | | % | % | 23. Garage |
| | | | | | | % | % | 24. Shed |
| | | | | | | % | % | 25. Bay Window |
| | | | | | | % | % | 26. Overhang |
| | | | | | | % | % | 27. Unf. Bsmt |
| | | | | | | % | % | 28. Unf. Attic |
| | | | | | | % | % | 29. Fin. Attic |
| | | | | | | % | % | Add 20 for 2 Story |
| | | | | | | % | % | 61. Carport |
| | | | | | | % | % | 62. Patio |
| | | | | | | % | % | 63. Swimming Pool |
| | | | | | | % | % | 64. Tennis Court |
| | | | | | | % | % | 65. Stable w/lot |
| | | | | | | % | % | 66. Greenhouse |
| | | | | | | % | % | 67. Natatorium |
| | | | | | | % | % | 68. Wood Deck |
| | | | | | | % | % | 69. Jacuzzi |

PHOTO

NOTES: JHD'S ARE RECENT - ROUGH FINISHED