

1 of 2

#### **Facility Information**

Permit Number: 13-51-12281

Name of Facility: Bob Graham Educational Center PLC South

Address: 8875 NW 143 Street City, Zip: Miami 33018

Type: Public School

Owner: M-DCSB Food and Nutrition

Person In Charge: Elizabeth Hernandez Phone: 305 231 8778

Correct By: Next Inspection Re-Inspection Date: None

**RESULT: Satisfactory** 

# Inspection Information

Purpose: Routine Begin Time: 01:00 PM Inspection Date: 2/2/2016 End Time: 02:30 PM

## **Additional Information**

CENSUS	190
FEMALES	98
MALES	92

As per section 120.695 of the Florida Statutes (FS), this form will serve as a "Notice of Non-Compliance: for any violations noted. Items marked below violate the requirements of Chapters 64E-13 and 64E-11 of the Florida Administrative Code (FAC) and must be corrected within the time period indicated in the "Results" section above. Continued operation of this facility without making these corrections is a violation of Chapter 64E-13 and 64E-11, FAC, and Chapter 381, FS. Failure to correct violations may result in an administrative fine or other legal action being initiated or continued.

## **Violation Markings**

SCHOOL SANITATION 11. Cleanliness & Repair 22. Solid Waste

 School Site 12. Toilet Facilities

VECTOR/VERMIN CONTROL 2. Playground Equipment 13. Separation of Sexes 23. Infestation/Control

3. Athletic Equipment 14 Fixture Ratio 24. Brush/Trash 25. Water Collection/Drainage **BUILDINGS** 15. Handwash Facilities

4. Construction 16. Showers/Fixtures SAFETY X 5. Maintenance & Repair 17. Shower Water Temp. 26. First Aid Kit

6. Lighting/Foot-Candles WATER SUPPLY **FOOD** 

18. Installed/Operated/Maintained 7. Heating, Ventilation, A/C 27. Food Insp. Rpt. 8. Natural Ventilation 19. Drinking Fountains OTHER

20. Approved Source 9. Mechanical Ventilation 28. SANITARY FACILITIES LIQUID/SOLID WASTE 29 10. Provided/Accessible 21. Sewage Disposal

### **General Comments**

No General Comments Available

Email Address(es): ecrespo@dadeschools.net;ymartinez@dadeschools.net;ipalacio@dadeschools.net;tequigley@dadeschools.net

**Inspector Signature:** 

Form Number: DH 4030 01/05

eralmodenary

13-51-12281 Bob Graham Educational Center PLC South



2 of 2

## **Violations Comments**

Violation #5. Maintenance & Repair

Repair broken tile on the wall next to hand sink in restroom 116A.

CODE REFERENCE: Maintenance & Repair 64E-13.004(3)(b)(c). Buildings shall be kept clean and in good repair, free from hazardous conditions, such as loose or broken floor tiles and boards; loose moldings; loose hanging fixtures, pipes, and electric wires; and broken plaster. Furnishings and equipment shall be kept clean and in good repair, free of missing parts and hazards such as sharp edges, splinters, and protruding or rusty nails.

Inspection Conducted By: Maria Moreno (27482)

Maria Moreno Date: 2/2/2016

Inspector Signature:

MARTEN

erales demand

Form Number: DH 4030 01/05 13-51-12281 Bob Graham Educational Center PLC South



**RESULT: Satisfactory** 

1 of 2

#### **Facility Information**

Permit Number: 13-51-13055

Correct By: Next Inspection Name of Facility: Bob Graham Educational Center Re-Inspection Date: None Address: 15901 NW 79 Avenue

City, Zip: Miami Lakes 33016

Type: Public School

Owner: M-DCSB Food and Nutrition

Person In Charge: Yecenia Martinez-Lopez Phone: 305 557 3303

Inspection Information

Purpose: Routine Begin Time: 10:00 AM Inspection Date: 2/2/2016 End Time: 11:30 AM

**Additional Information** 

**CENSUS** 940 **FEMALES** 446 **MALES** 494

As per section 120.695 of the Florida Statutes (FS), this form will serve as a "Notice of Non-Compliance: for any violations noted. Items marked below violate the requirements of Chapters 64E-13 and 64E-11 of the Florida Administrative Code (FAC) and must be corrected within the time period indicated in the "Results" section above. Continued operation of this facility without making these corrections is a violation of Chapter 64E-13 and 64E-11, FAC, and Chapter 381, FS. Failure to correct violations may result in an administrative fine or other legal action being initiated or continued.

## **Violation Markings**

SCHOOL SANITATION 22. Solid Waste 11. Cleanliness & Repair

 School Site 12. Toilet Facilities

VECTOR/VERMIN CONTROL 2. Playground Equipment 13. Separation of Sexes 23. Infestation/Control 14. Fixture Ratio 24. Brush/Trash

3. Athletic Equipment 25. Water Collection/Drainage **BUILDINGS** X 15. Handwash Facilities

4. Construction 16. Showers/Fixtures SAFETY X 5. Maintenance & Repair 17. Shower Water Temp. 26. First Aid Kit

6. Lighting/Foot-Candles WATER SUPPLY **FOOD** 

18. Installed/Operated/Maintained 7. Heating, Ventilation, A/C 27. Food Insp. Rpt. 8. Natural Ventilation 19. Drinking Fountains OTHER

20. Approved Source 9. Mechanical Ventilation 28. SANITARY FACILITIES LIQUID/SOLID WASTE 29. 10. Provided/Accessible 21. Sewage Disposal

### **General Comments**

No General Comments Available

Email Address(es): ymartinez@dadeschools.net;jesusmesa@dadeschools.net;tequigley@dadeschools.net;ipalacio@dadeschools.net

**Inspector Signature:** 

**Client Signature:** 



Form Number: DH 4030 01/05 13-51-13055 Bob Graham Educational Center



2 of 2

### **Violations Comments**

Violation #5. Maintenance & Repair

Secure loose handle in water fountain in classroom 218 and 217.

Repair leak in toilet valve 040A and restore pressure in the toilet. It flushes completely the second time.

CODE REFERENCE: Maintenance & Repair 64E-13.004(3)(b)(c). Buildings shall be kept clean and in good repair, free from hazardous conditions, such as loose or broken floor tiles and boards; loose moldings; loose hanging fixtures, pipes, and electric wires; and broken plaster. Furnishings and equipment shall be kept clean and in good repair, free of missing parts and hazards such as sharp edges, splinters, and protruding or rusty nails.

Violation #15. Handwash Facilities

Provide soap in girls restroom 217B, boys restroom 244 A, restroom 073A and 072A. Corrected at time of inspection.

REFERENCE: Handwash Facilities 64E-13.004(6)(b). Handwashing facilities shall be located within or adjoining each toilet room. Soap dispensers shall be provided at all wash basins and liquid or powdered soap shall be used. Individual towels, preferably paper shall be used. Use of common or public towels is prohibited. Hot-air hand drying devices

Inspection Conducted By: Maria Moreno (27482)

Maria Moreno Date: 2/2/2016

**Inspector Signature:** 

Form Number: DH 4030 01/05

MAM

Client Signature:

13-51-13055 Bob Graham Educational Center



1 of 2

## **Facility Information**

Permit Number: 13-51-14215 Correct By: Next Inspection Name of Facility: Bob Graham MLC Re-Inspection Date: None Address: 15901 NW 79 Avenue

Type: Public School

Owner: M-DCSB Food and Nutrition

Person In Charge: Yecenia Martinez-Lopez Phone: 305 557 3303

## Inspection Information

City, Zip: Miami Lakes 33016

Purpose: Routine	Begin Time: 11:30 AM
Inspection Date: 2/2/2016	End Time: 12:30 PM

## **Additional Information**

CENSUS	622
FEMALES	318
MALES	304

As per section 120.695 of the Florida Statutes (FS), this form will serve as a "Notice of Non-Compliance: for any violations noted. Items marked below violate the requirements of Chapters 64E-13 and 64E-11 of the Florida Administrative Code (FAC) and must be corrected within the time period indicated in the "Results" section above. Continued operation of this facility without making these corrections is a violation of Chapter 64E-13 and 64E-11, FAC, and Chapter 381, FS. Failure to correct violations may result in an administrative fine or other legal action being initiated or continued.

## **Violation Markings**

SCHOOL SANITATION X 11. Cleanliness & Repair 22. Solid Waste

School Site

2. Playground Equipment

3. Athletic Equipment

**BUILDINGS** 

4. Construction

5. Maintenance & Repair

X 6. Lighting/Foot-Candles

7. Heating, Ventilation, A/C

8. Natural Ventilation

9. Mechanical Ventilation

SANITARY FACILITIES

10. Provided/Accessible

12. Toilet Facilities

13. Separation of Sexes

14. Fixture Ratio

X 15. Handwash Facilities

16. Showers/Fixtures 17. Shower Water Temp.

WATER SUPPLY

18. Installed/Operated/Maintained

19. Drinking Fountains

20. Approved Source

LIQUID/SOLID WASTE

VECTOR/VERMIN CONTROL

**RESULT: Satisfactory** 

23. Infestation/Control

24. Brush/Trash

25. Water Collection/Drainage

SAFETY 26. First Aid Kit

FOOD 27. Food Insp. Rpt.

OTHER

28. 29.

21. Sewage Disposal

# **General Comments**

No General Comments Available

Email Address(es): ymartinez@dadeschools.net;jesusmesa@dadeschools.net;ipalacio@dadeschools.net;tequigley@dadeschools.net

**Inspector Signature:** 

**Client Signature:** 



Form Number: DH 4030 01/05 13-51-14215 Bob Graham MLC



2 of 2

### **Violations Comments**

Violation #5. Maintenance & Repair

Repair leak at toilet valve in first stall in girls restroom 9309. Small amount of water comes out of toilet valve only after flushed.

CODE REFERENCE: Maintenance & Repair 64E-13.004(3)(b)(c). Buildings shall be kept clean and in good repair, free from hazardous conditions, such as loose or broken floor tiles and boards; loose moldings; loose hanging fixtures, pipes, and electric wires; and broken plaster. Furnishings and equipment shall be kept clean and in good repair, free of missing parts and hazards such as sharp edges, splinters, and protruding or rusty nails.

Violation #6. Lighting/Foot-Candles

Repair deemed light in girls restroom 405 A.

Repair 1 non working water fountain third floor next to restroom girls 9308.

CODE REFERENCE: Lighting/Foot-Candles 64E-13.004(4)(a-d). Illumination in all instructional spaces shall be designed to provide a minimum of forty (40) foot-candles glare free at normal task level. Fixtures shall be so located that there will be uniform (within ten (10) foot-candles) illumination suitable for the activities conducted therein. All required illumination shall be designed so that the failure of any single unit, such as the burning out of an electric bulb will not leave any occupied area or means of egress in darkness. Illumination of chalkboards and other visual aids shall be designed to eliminate glare and shadows.

Violation #11. Cleanliness & Repair

Clean water spill on the first floor stairs (back building). Corrected at time of inspection.

CODE REFERENCE: Cleanliness & Repair 64E-13.004(6)(a). Walls to a height of at least 4' feet toilet partitions and floor of all toilet rooms shall be finished with impervious materials. All plumbing fixtures shall conform to the provisions of the local plumbing code. All group toilet rooms shall be provided with at least one (1) floor drain and (1) hose bib. The floor shall be sloped to the drain. Deodorizers shall not be used in toilet rooms.

Violation #15. Handwash Facilities

Provide soap in boys restroom 330 A. girls restroom 326B, boys restroom 9205, boys restroom 9305. Corrected at time of inspection.

Repair 1 non working faucet in boys restroom 330A, 1 non working faucet in boys restroom 326A and 1 non working faucet in boys restroom 9205. Corrected at time of inspection.

CODE REFERENCE: Handwash Facilities 64E-13.004(6)(b). Handwashing facilities shall be located within or adjoining each toilet room. Soap dispensers shall be provided at all wash basins and liquid or powdered soap shall be used. Individual towels, preferably paper shall be used. Use of common or public towels is prohibited. Hot-air hand drying devices

Inspection Conducted By: Maria Moreno (27482)

Maria Moreno Date: 2/2/2016

**Inspector Signature:** 

Client Signature: ~\m\\n\m

Form Number: DH 4030 01/05 13-51-14215 Bob Graham MLC