



Colorado Department
of Public Health
and Environment

COLORADO DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

4300 Cherry Creek Drive South

Denver, CO 80246-1530

Phone (303) 692-3620

Fax (303) 753-6809

Page 1 of 2

NAME OF SCHOOL FREMONT MIDDLE SCHOOL				SCHOOL DISTRICT FREMONT SCHOOL DISTRICT RE-2				
PRINCIPAL ANDY FIETH				PHONE NUMBER (719) 784-4856				
ADDRESS 215 N MAPLE FLORENCE CO						ZIP 81226		
COUNTY	FIRM ID	INSPECTOR ID	DATE			TRAVEL TIME	INSPECT TIME	TYPE
			MONTH	DAY	YEAR			
22	10697	259	11	15	11	20	150	<input checked="" type="checkbox"/> REGULAR
								<input type="checkbox"/> FOLLOW-UP
								<input type="checkbox"/> PRE-OPERATIONAL
								<input type="checkbox"/> COMPLAINT

SCHOOL INSPECTION REPORT

Items circled below identify violations to be corrected as indicated by the regulatory authority. Failure to comply may result in further action by the regulatory authority.

2.0. GROUND

a. General

3.0. SANITARY FACILITIES AND CONTROLS

- a. Water
- b. Sewage disposal
- c. Refuse disposal
- d. Insects, rodents, animals
- e. Plumbing
- f. Toilet, lavatory, bathing
- g. Swimming pool (if applicable; see attached pool inspection)

4.0. BUILDING, OCCUPANCY, SPACE AND USE

a. General

5.0. MECHANICAL

- a. Electrical
- b. Lighting
- c. Ventilation
- d. Heating

6.0. EQUIPMENT AND SUPPLIES

a. General

7.0. FOOD SERVICE

- a. If applicable; see attached food service inspection
- b. Dining area

8.0. LABS, INDUST, ARTS, VOCATIONAL

- a. General
- b. Chemical storage, handling
- c. Chemical Inventory
- d. MSDS
- e. Written plans
- f. Safety Equipment
- g. Ventilation

9.0. HEALTH SERVICES

a. General

10.0. MISCELLANEOUS

- a. General
- b. Asbestos plan
Date
10/21/2008
- c. Radon monitored
Date
07/15/2009

259

PLEASE INSTALL THE PROPER VERSION
OF JAVA ON YOUR MACHINE

ID#

PLEASE INSTALL THE PROPER VERSION
OF JAVA ON YOUR MACHINE

TITLE

Colorado Department of Public Health and Environment

Schools Inspection Report

Items described below identify violations to be corrected as indicated by the regulatory authority. Failure to comply may result in further action by the regulatory authority.

Schools Name of School Fremont Middle School	City FLORENCE	Firm ID 10697	Date (mm/dd/yy) 11/15/2011
--	-------------------------	-------------------------	--------------------------------------

Item #	Remarks	Method of/for Correction	Corrected by (MM/DD/YY)
3e	3-504 Cross connection observed in the dark room in the art classroom (Annex Building), section of hose attached to sink faucet, end of hose hanging into the sink. Remove the section of hose or install a vacuum breaker on the faucet.		
3e	3-606 Hot water at the handsinks in the public restrooms next to the gym (Annex Building) exceed the maximum temperature of 120 Deg.F.		
3e	3-606 Hot water at the handsinks in the student locker rooms (Annex Building) exceeds 120 Deg.F. Hot water supplied to sinks and bathing facilities accessible to students may not exceed 120 Deg.F.		
4a	4-101 Damaged floor tiles under lab bench in Room #209, Main Building.		
8b	8-113 A written plan that explains the proper storage, handling and disposal procedures for all poisonous, toxic or hazardous substances was not in the school safety binder.		
8c	8-101 Chemicals used in the school (the science lab inventory is OK) are not inventoried. All chemicals, solvents and hazardous substances shall be inventoried by the school a minimum of once a year. The inventory shall include the name of the compound, the amount and the date it entered the school. A copy of the inventory shall be kept on file in a location away from the areas where the aforementioned materials are stored.		
8e	8-112 A written plan for response to and cleanup of chemical spills was not available in the school safety binder.		
10c	10-102 Radon test results were not available, however test results were noted during the previous inspection. These are required to be on file and available for review (asbestos results were available).		
Comments	<p>8:30 a.m.</p> <p>The vent hood has been removed from the science lab classroom (#209).</p> <p>Chemical inventory for the science classroom and lab are maintained on computer.</p> <p>No active gas connections in the science classroom and lab, portable propane burners are used when required.</p> <p>A wall-mounted fire blanket is available in the science classroom and lab, and eye wash unit and an emergency hand shower are available and can be attached to any of the water faucets in case of an emergency.</p> <p>The office of the school nurse was closed when I returned later during the inspection, so I was not able to determine if first aid procedures for accidental poisoning are posted or if the poison control number is also posted. I was also not able to determine if one or more staff members have current first aid certification and if a list of all certified staff is maintained.</p>		

Colorado Department of Public Health and Environment

Schools Inspection Report

Items described below identify violations to be corrected as indicated by the regulatory authority. Failure to comply may result in further action by the regulatory authority.

Schools Name of School	City	Firm ID	Date (mm/dd/yy)
Fremont Middle School	FLORENCE	10697	11/15/2011

Comments	
Environmental Health Specialist: Please install the proper version of Java on your machine	Received by: Please install the proper version of Java on your machine

Method of/for Correction

Corrected On Site (COS):
 CIVCS:
 Follow-Up (F/U):
 Compliance Agreement (CA):

Form RF001-2_revF_PageTwoInspectionReport_0706.doc