

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	01379	Legal Intervention:	NO	At Intersection with:	"N/A"
Date of Acc:	05/29/14	Private Property:	NO	Div HWay Trvl Dir:	"N/A"
Time of Acc:	20:43 Hrs.	County:	DUBUQUE - 31	Distance 1:	"N/A"
Name of Agency:	DYERSVILLE POLICE DEPARTMENT	Acc Loc City:	DYERSVILLE - 2160	Direction 1:	"N/A"
Officer:	LINK MOLLY	Acc Dir From City:	"N/A"	Distance 2:	"N/A"
Badge #:	07	Closest City:	"N/A"	Direction 2:	"N/A"
Report Date:	05/29/2014	Miles From City:	"N/A"	X-Coordinate:	00655017
Officer Notified:	08:50 Hrs.	Road, Street, HWay:	"N/A"	Y-Coordinate:	04703872
Officer Arrived:	08:50 Hrs.	Definable Location:	"N/A"	Location Literal:	STATE 136/9TH ST SE
Scene Investigated:	YES	Milepost Number:	"N/A"	Description:	

Unit 001

Driver Name - Last:	RUNDLE	Towing:	NO	Injury Status:	5 - UNINJURED
First:	DUSTIN	Initial Trvl Dir:	3 - SOUTH	Transported to:	
Middle:	IKE	Vision Obscured:	01 - NOT OBSCURED	Transported by:	
Address:	934 2ND AVE SE	Traffic Controls:	04 - STOP SIGNS	Emergency Veh:	1 - NOT APPLICABLE
City:	DYERSVILLE	Point of Init Impact:	05 - REAR	Emergency Status:	3 - NOT APPLICABLE
State:	IA	Most Damaged Area:	05 - REAR	Cont. Circum., Drvr:	
Zip:	52040	Undrrid/Ovrid:	0 - OVERRIDE, PARKED/STATIONARY VEHICLE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$1,000.00	Carrier Address:	
Gender:	Male	Ext of Damage:	9 - UNKNOWN	Carrier City:	
Age:	18	First Event:		Carrier State:	
License State:	IA	Second Event:		Carrier Zip:	
License Class:	C	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:	NONE	Fourth Event:		Number of Axles:	
License Restrictions:	S,B	Most Harmful Event:		HazMat Released?:	
Speed Limit:	0	Abg Switch Stat:	9 - UNKNOWN	GVWR:	
Seating Position:	01 - FRONT: LEFT SIDE / MOTORCYCLE DRIVER	Abg Deploy:	5 - NOT DEPLOYED	Placard #:	
Driver Condition:	1	Trapped:	1 - NOT TRAPPED	Cit Chrg Code 1:	
Alcohol Test Given:	NO	Ejection:	1 - NOT EJECTED	Citation Charge 1:	
Drug Test Given:	NO	Ejection Path:	1 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:	
Total Occupants:	3	Occpnt Protect:	9 - UNKNOWN	Citation Charge 2:	
Vehicle Year:	2014			Cit Chrg Code 3:	
Vehicle Make:	FORD - FORD			Citation Charge 3:	
Vehicle Model:	PICKUP TRUCK			Cit Chrg Code 4:	
Vehicle Style:	2 DOOR			Citation Charge 4:	
Vehicle Config:	02 - FOUR-TIRE LIGHT TRUCK (PICK-UP, PANEL)				
Vehicle Defect:	99 - UNKNOWN				
Vehicle Action:	11 - STOPPED FOR STOP SIGN/SIGNAL				

Unit 002

Driver Name - Last:	KLOCKE	Towing:	YES	Injury Status:	5 - UNINJURED
First:	EMILY	Initial Trvl Dir:	3 - SOUTH	Transported to:	
Middle:	ELIZABETH-STRAN	Vision Obscured:	01 - NOT OBSCURED	Transported by:	
Address:	1808 COBBLESTONE DR	Traffic Controls:	02 - TRAFFIC SIGNALS	Emergency Veh:	1 - NOT APPLICABLE
City:	MUSCATINE	Point of Init Impact:	01 - FRONT	Emergency Status:	3 - NOT APPLICABLE
State:	IA	Most Damaged Area:	01 - FRONT	Cont. Circum., Drvr:	13 - FTYROW: FROM STOP SIGN
Zip:	52761	Undrrid/Ovrid:	0 - OVERRIDE, PARKED/STATIONARY VEHICLE	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	\$2,000.00	Carrier Address:	
Gender:	Female	Ext of Damage:	3 - FUNCTIONAL DAMAGE	Carrier City:	
Age:	37	First Event:	21 - VEHICLE IN TRAFFIC	Carrier State:	
License State:	IA	Second Event:	99 - UNKNOWN	Carrier Zip:	
License Class:	C	Third Event:		Cargo Body Type:	01 - NOT APPLICABLE
License Endorsmnt:	NONE	Fourth Event:		Number of Axles:	
License Restrictions:	NONE	Most Harmful Event:	21 - VEHICLE IN TRAFFIC	HazMat Released?:	
Speed Limit:	25	Abg Switch Stat:	1 - SWITCH IN ON POSITION	GVWR:	
Seating Position:	01 - FRONT: LEFT SIDE / MOTORCYCLE DRIVER	Abg Deploy:	3 - DEPLOYED BOTH FRONT/SIDE	Placard #:	
Driver Condition:	1	Trapped:	1 - NOT TRAPPED	Cit Chrg Code 1:	62.01938)
Alcohol Test Given:	NO	Ejection:	1 - NOT EJECTED	Citation Charge 1:	
Drug Test Given:	NO	Ejection Path:	1 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:	
Total Occupants:	1	Occpnt Protect:	9 - UNKNOWN	Citation Charge 2:	
Vehicle Year:	2014			Cit Chrg Code 3:	
Vehicle Make:	BUICK - BUICK			Citation Charge 3:	
Vehicle Model:	ENCORE			Cit Chrg Code 4:	
Vehicle Style:	WHITE SUV			Citation Charge 4:	
Vehicle Config:	04 - SPORT UTILITY VEHICLE				
Vehicle Defect:	99 - UNKNOWN				
Vehicle Action:	01 - MOVEMENT ESSENTIALLY STRAIGHT				

Accident Environment

First Harmful Event Loc: **1 - ON ROADWAY**
Manner of Crash/Collision: **3 - REAR-END**
Light Conditions: **2 - DUSK**
Weather Conditions: **01 - CLEAR, 99 - UNKNOWN**

Surface Conditions: **1 - DRY**

First Harmful Evt of Crash: **99 - UNKNOWN**

Roadway Characteristics

Environment: **1 - NONE APPARENT**
Roadway: **01 - NONE APPARENT**
Type of Road Junc/Feat: **11 - FOUR-WAY INTERSECTION**

Workzone Related: **NO**

Location:

Type:

Workers Present:

Narrative

UNIT 1 WAS TRAVELING SOUTH BOUND ON HWY 136 AND WAS STOPPED AT A RED LIGHT ON HWY 136 AND 16TH AVE SE. UNIT 2 REAR ENDED UNIT 1 AT THE STOP LIGHT.

Diagram

